1 C82   1 pc	22017442/7243
ASS. RECBY: TOWN REF. COT LVC	220174477745
ASSI	GNMENT
From: Date:	Veh No: SL S19000 Yr Regn: 2017, SCP.
Estimated lost	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / (TP) / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspecivehide No:	Make: Maserat Quattroporte c.c 2979
at Workship m/s	Colour Whate A/C: Insured / Std / Ni / NA
ហ៍	Sp.Reading 121076 T/Radio: Insured / Std / NI / NA
insured:	Eng/No:
Policy No.	C/No: ZAMXP56(UD=1256019
Claims No.	Gen. Cond: Good / Fair / Poor / Burnf
Sum Insued: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nii / Spim / STD A/Rim or /
	Tyre Size: F: 285 35 R 20
(Policy Condition)	R:
Remark: The veh had commenced its N/S 0/S repair at the time of inspection.	BS / DUN / EXNOVA / GY /-FS / LIZA / MIC / OHTSU (PIR) SUMI /
3,2 4	TOYO/YOKO DI
Bal. or Market Value: 92681C.	Front Rear
IDAC Accident Rport Consistent? : Yes or No	R/Bal, mm R/Bal 6 mm
GIA / PR Seen: Consistent? : Yes or No	D.O.A. D.O.I. U3/0//23
Est. Repairs: days Res.: Yes or No	
01 008	52.10) 1010 21
CA / REV / REP. / 24 HRS Vehicle: IN / OU	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date /Time Action / Instruction	
)	*
Date/Tine, File Pass to? : Preli. Report	Days Of Repair:
i) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Refurn to?	Transportation:
2) Add F	
	: Interview (\$ ) Photos
Reput Format :	Tech. Irsvs (\$ ) Others
Lump Sum / LB.A: ('p)	: Weel and (\$

SS3722CC0008 / Success United Pte Ltd ENTRY DATE & TIME: 12/12/2022 19:46 (SGT) SUBMITTED BY: Elise Law Yi Ting VERSION: 1 (12/12/2022 19:46 (SGT))



# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

  5. Any false reporting may be referred to the Police for Investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving
- and that copies of this report will, for a fee, be made available upon application by interested parties.

  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### **ACCIDENT STATEMENT**

Date of Submission

12/12/2022 19:46 (SGT)

Reported by

Both

Date of Accident

09/12/2022 12:55 (SGT)

**Exact Location of Accident** 

531 Upper Cross St, Singapore 050531

Additional Location Information

Mutistorage Carpark

Country/State of Loss

Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number

SLS1900D

INSURED/POLICYHOLDER

Is company?

No

Name Of Registered Owner

Lim Han Yaw, Dominic

NRIC No

S8515092H

Email Address Mobile Phone No domlhy@hotmail.com (Phone) +65-82680777

Alternative Phone No

VEHICLE PARTICULARS

Manufacturer

Maserati

Model

Quattroporte **GRANLUSSO** 

Variant

Exact purpose for which vehicle was being used at time of

Private use

accident Are you claiming under your own insurance policy for repair to

No - Claiming third party

your vehicle?

Private car

Vehicle Category Transmission

Auto

CC

2979

INSURANCE COMPANY

Name of Insurance Company

Policy Number / Cover Note Number

Liberty Insurance Pte Ltd SD22V03768/VPS/R0

DRIVER

Name of Driver

NRIC No

Date Of Birth

Occupation

Lim Han Yaw, Dominic

S8515092H

13/05/1985

Outdoor

Accident report SS3722CC0008

Date Of Driving Pass 18/10/2012 10 YEARS AND 2 MONTHS Driving experience Gender Mobile Number (Phone) +65-82680777 Alt. Phone Number Email Address domlhy@hotmail.com Address Blk 156 Bedok South Avenue 3 Address complement #04-593 Singapore Postcode 460156 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Major/Minor Rd Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement PASSENGER 1 Name Catherine Wee Zi Ting Gender Female DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT Refer to sketch plan. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera?

## **DETAILS OF OTHER VEHICLE PROPERTY 1**

Yes

Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant

GBF8883K

Accident report SS3722CC0008

Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	Zhang YiMeng
NRIC No	S8378346Z
Contact Number	2
Address	¥
Address complement	-
Postcode	÷.
Insurance Company Name	*
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

### SKETCH PLAN

### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2 This Formmust be completed by the Policyholder and/or the Authorised Driver
- 3 information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withfielding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation
- 6. The report will be forwarded by the insurers of the GA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
- (a) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers law yers/law firms, may/are permitted to collectuse, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal information may/can be disclosed by any of the insurers and/or GW to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time Driver's Signature (if driver is not the policyholder) / Date & Time

Variessed by Reporting Centre ersonnel

Sketch Plan

B D

(A) : SLS1900D

(B): GBF8883K

	Un (GRF88832k) came out f	from his carpork let
d hil to my	valicle's left rear portion.	
J		
laration		
	$\wedge$	
Λ		
/L		
1-1	774	
	Driver's Signature of driverors not the policy half tent	

Describe Circumstances of the Accident

I was driving at 531 upper (ross St., (s) 050531, mutistorage