

ASS. REC. BY:

REF:

122012454/kpKennerth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

21 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

06/30

Person Contacted:

Vehicle: IN / OUT

Veh No:

SEA 6088

Yr Regn:

06/10

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M. C180

c.c

1796

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

136237

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD 20 404 P 2A 373992

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD / Rlm or

Tyre Size:

F:

R:

245/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

9/12/22

D.O.I.

14/12/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

8 / 151

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1Booth & Bonnet jammed

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

Paints

Others

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

TOTAL



方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

GOH CHOON THYE
4 JALAN UJI
SINGAPORE 678358

*Not withanw
11 May @
Penny After Rain
21 days*

Dear sir

Estimate cost of repair to vehicle no. SCA 6088S

To supply

1. Front bonnet	B ₁ 2,130.00	✓
2. Front bonnet hinge x2	240.00	?
3. Front bonnet logo	M ₁ 55.00	✓
4. Front bonnet hook x2	o/s o/i 100.00	✓
5. Front bonnet damper x2	320.00	?
6. Front bonnet cover garish	180.00	?
7. Front bonnet lock x2	o/s B ₁ 460.00	✓
8. Front bumper	B ₁ 1,233.00	✓
9. Front bumper inner part	CM 108.00	✓
10. Front bumper reinforcement	B ₁ 688.00	✓
11. Front bumper bracket x2	240.00	?
12. Front bumper sponge	CM 128.00	✓
13. Front bumper moulding x2	M ₁ 264.00	✓
14. Front bumper fog lamp x2	o/s ? 1,160.00	MISX
15. Front bumper towing cover	mi 45.00	✓
16. Front bumper lower grille	Di 103.00	✓
17. Front grille	CM 850.00	✓
18. Front grille top cover garish	CM 180.00	✓
19. Front support panel x3	950.00	?
20. Radiator	1,080.00	?
21. Air condenser	980.00	?
22. Fan and motor cowing	890.00	?
23. air filter outlet garish	203.00	?
24. Radiator spare tank	102.00	?
25. Tail boot cover	B ₁ 1,772.00	✓
26. Tail boot inner lock	T ₁ 314.00	✓
27. Tail boot cover hinge x2	B ₁ 240.00	✓
28. Tail boot hinge cover garish x2	160.00	?
29. Tail boot logo	M ₁ 51.00	✓
30. Tail boot badge c180	M ₁ 68.00	✓
31. Tail boot badge gdi	M ₁ 68.00	✓
32. Tail boot outer handle	Wop 319.00	✓
33. Tail boot outer lock	201.00	?



方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

Pg 2

- 34. Tail boot number plate lamp x2
- 35. Tail boot garish cover
- 36. Tail boot rubber
- 37. Tail lamp left
- 38. Tail lamp right
- 39. Tail lamp housing right
- 40. Rear panel
- 41. Rear panel top garish
- 42. Rear bumper
- 43. Rear bumper inner part
- 44. Rear bumper sensor
- 45. Rear bumper reinforcement
- 46. Rear bumper side moulding x2
- 47. Rear bumper centre moulding
- 48. Rear tyres spare board
- 49. Rear spare tyre panel garish
- 50. Rear chassis memberx2
- 51. Rear fender right
- 52. Rear fender inner side cover x2
- 53. Seat belt x4
- 54. Head rest x2
- 55. Relay sensor
- 56. Rear exhaust box

Neform	60.00	?
Dislod	320.00	✓
CM	156.00	50%in
Bu	793.00	✓
Bu	793.00	✓
Bu	340.00	✓
Bu	1,358.00	✓
Di	240.00	✓
Bu	1,595.00	✓
Bu	108.00	✓
nd/sher	350.00	✓
Bu	738.00	✓
na	290.00	✓
na	205.00	✓
	350.00	?
	550.00	?
R	1,796.00	?
Bu	1,205.00	✓
	1,200.00	?
Tu	2,080.00	✓
Ar	700.00	✓
	280.00	?
	890.00	?

108



方 商 昭 噴 漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

Pg3

Labour charges	100.00	✓
Rust proofing	3,800.00	260d
Panel beating	2,500.00	2200d
Spray painting	500.00	24d
To remove and refit rear w/s glass and cushion	550.00	100d
Air con gas and check	(Bill) 200.00	?
Towing		
Total	40,129.00	

Your faithfully

ALBERT POON

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	13/12/2022 11:57 (SGT)
Reported by	Both
Date of Accident	09/12/2022 13:30 (SGT)
Exact Location of Accident	Clementi Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCA6088S
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Goh Choon Thye
NRIC No	S1064074A
Email Address	sitti1@singnet.com.sg
Mobile Phone No	(Phone) +65-96791749
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	C180
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1800

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMPCSNW00247682106

DRIVER

Name of Driver	Goh Choon Thye
NRIC No	S1064074A
Date Of Birth	19/12/1944
Occupation	Outdoor

IMPORTANT NOTICE**SKETCH PLAN**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers-law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers-law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers-law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

13/12/22

Sketch Plan

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Owner ID Type:	Singapore NRIC
Owner ID:	074A
Vehicle No.:	SCA6088S
Vehicle to be Exported:	Yes
Intended Deregistration Date:	13 Dec 2022
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 180 CGI
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	27182030041377
Chassis No.:	WDD2040492A373992
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$38,917.00
Original Registration Date:	14 Jun 2010
First Registration Date:	14 Jun 2010
Transfer Count:	2
Actual ARF Paid:	\$38,917.00

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

COE Expiry Date:	13 Jun 2030
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$33,568.00
COE Rebate Amount:	\$25,176.00
Total Rebate Amount:	\$25,176.00

The information contained herein is correct as at 13 Dec 2022

OK