ASS. FEC. BY: LASAU REF: CS CT 2	2012460/RVP3
	SSIGNMENT
From: Date:	
Estimated Cost.	Type M.Carl M.Cycle J Bus J Van J Long J Tax J Prime Mover J
OD/TH/WS/TP RES/OD RES/EVA/INV/IMV	Truck/Trailer or
To Inspect Vehicle No: SNO 78P	Make: Volksunghen SHARAN 20 Blac 1984
at Worthop m/s Volks maken	
of _[1/TW/S MVK 9	
Insured: YQ 2951G CT(Sp.Reading 3544 T.Radio: Insured / Std / NI / NA Eng.No.
Policy No. DMCVSNA00087202200	
Claims No. SNM22D208939/C02/LEEPG	C/No: WVW 2227NZM V 80-2696 Gen. Cond: Good / Cair) Poor / Burnt
Sum Insured: Excess:	Steering: Inorder/ Jammed / Leaked / Burnt or
(Client's Record)	Brake: inorder! Jammed / Leaked / Burnt or
Make of Veh:	Medi: NII 1 Strain 1 SED Aftern or
 	
(Policy Condition)	Tyre Size: F: DZS/YSR18
B	BS INVINIENMENT COVER 14 TA 14 TO 15
repair at the time of inspection.	
Bal. or Market Value: 173K	TOYO/YOKO or
IDAC Accident Rport: Consistent?: Yes or No	Front Rear
GIA / PR Seen: Consistent?: Yes or No	R/Bal. 0 mm R/Bal. 9 mm
	L/Bal. mm L/Bal. mm
	D.O.A. 16/12/22 D.O.I. 14/12/22
	Survey held at Volksuahen
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftep or
Date: Person Contacted: Vehicle: 1N /-O	
Date / Time Action / Instruction	The UIC / Chassis frame / Body Structure affected due to collision.
REPAIR LIMIT - 104K	
· · · · · · · · · · · · · · · · · · ·	
4/5/23 Submit preli report-revised fig \$22,	367.23 check items \$2286.92
	2,416.31 \$2481.92
ΨΕΕ	φ2401.32
Pate/Time, File Pass to?	D
: Final Report	Days Of Repair: 8
Data/Time, File Return to?	Resurvey No. of Trip: Survey Fee:
24/5/23-typist Add F	Transportation:
)_S+RS_SI
Report Format : Merimen	: Interview (\$) Photes
Lump Sum / I.B.I; (\$	Tech. Invs (\$) Others
	: Waekend (\$

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road Singapore 159934

Biz. Reg. No.: 199101494Z GST No.: M200985052







Quotation Non binding - Preview

Page

1/4

Document no. Document date

13-12-2022 5211033201

Customer no. Customer GST-ID

Dealer

30001

Job order number Job order date

2022036092/1 12-12-2022

Service Advisor

SHU SHI TANG

License plate SND78P

Ms.

POON

#15-31

YEN LING

29 KOVAN ROAD

Singapore 545022

Model code 7N24MYH2 First registration 26-03-2021

VIN WVWZZZ7NZMV002696 Model

Sharan Highline 2.0 TSI 162kW DSG Toulon

Mileage 35,440

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount To excl. GST	tal amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR	S			#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
9801B002	B&P LEAKED CHECK, VACUUM & REGAS	1			#1	420.00 ?	449.40
9801B002	A/C GAS				#1	60.00 ?	64.20
9801B003	B&P WHEEL ALIGNMENT				#1	360.00	385.20
9801B001	R&R RIM & BALANCE				#1	50.00	53.50
9801B001	TO ALIGN HEADLIGHT				#1	100.00	107.00
7N2819404B 9B9	Water Deflector Satin Bla	1	pcs.	103.86	#1	103.86	111.13
7N0823031A	Hood W	1	pcs.	1,796,13	#1	1,796.13	1,921.86
8E0823429A	Jounce Bumper AUL BONNET STOP BUFFER 7	Z1	pcs.	23.83	#1	47.66	51.00
7N0823301B	Flap Hinge Jf/ f	1	pcs.	194.26	#1	194.26	207.86
7N0823302B	Flap Hinge	1	pcs.	194.26	#1	194.26	207.86
1Q0823480	Hook BONNET LATCH 3 14/	1	pcs.	105.83	#1	105.83	113.24
N 90820401	Bolt Hex. Hd. Au	3	pcs.	4.00	#1	12.00	12.84
7N1823509B	Hood Latch Lower Portion 2 54 / BONNET LOCK	1	pcs.	160.93	#1	160.93	172.20
7N0863831	Hood Silencer BONNET INSULATOR	1	pcs.	316.21	#1	316.21	338.34
7N0807217J GRU	Cover For Bumper Primed	1	pcs.	2,212.59	#1	2,212.59	2,367.47
7N0805903 9B9	Front Spoiler Satin Black X NN	1	pcs.	180.73	#1	180.73	193.38
7N0807205 GRU	Cap Primed TOWING COVER 3 × nn	1	pcs.	71.34	#1	71.34	76.33
7N0807183A	Guide Piece BUMPER SIDE BRACKET LH	1	pcs.	44.68	#1	44.68	47.81
7N0807184A	Guide Piece BUMPER SIDE BRACKET RH	1	pcs.	44.68	#1	44.68	47.81
7N0807724	Support Part RHS NOZZLE CYLINDER BRACKET	าที	pcs.	36.70	#1	36.70	39.27
7N0807192	Guide Piece BUMPER CTR BRACKET	1	pcs.	160.06	#1	160.06	171.26
7N0807109D	Bumper Bracket 3 nn REINFORCEMENT 2 nn Pressure Cylinder 2 nn	1	pcs.	944.96	#1	944.96	1,011.11
7N0955979	DUC NOZZI E CYLINDED	1	pcs.	211.03	#1	211.03	225.80
7N0955104	Jet Carrier With Jet 7 nn RHS NOZZLE	1	pcs.	48.98	#1	48.98	52.41
7N0807938A GRU	Cap Primed RHS NOZZLE COVER 3 MUS	1	pcs.	70,36	#1	70.36	75.29

OLKSWAGEN CENTRE SINGAPORE

47 Alexandra Road Singapore 159934

Biz. Reg. No.: 199101494Z GST No.: M200985052







Quotation Non binding - Preview

Page

2/4

Document no. Document date

13-12-2022 5211033201

Customer no. Customer GST-ID

Dealer

30001

Job order number Job order date

2022036092/1

12-12-2022

Service Advisor

SHU SHI TANG

License plate SND78P

Ms.

POON

#15-31

YEN LING

29 KOVAN ROAD

Singapore 545022

Model code **7N24MYH2** First registration 26-03-2021

VIN WVWZZZ7NZMV002696 Model Sharan Highline 2.0 TSI 162kW DSG Toulon

Mileage 35,440

į į	1			Toulon		1	
Position no.	Description	Quanti	ty Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
1J0955665E	Elbow L-JOINT 3 × nn	1	pcs.	18.44	#1	18.44	19.73
8D0955873	Distributor Piece } × nn	1	pcs.	20.77	#1	20.77	22.22
1J0955964F	Hose In Coils Of 5m 'Orde X NN	1	pcs.	34.73	#1	34.73	37.16
1J0955846	Clip ne /	6	pcs.	1.70	#1	10.20	10.91
1T0919297A GRU	Sensor Primed 17	1	pcs.	190.18	#1	190.18	203.49
	PARKING SENSOR (SIDE) 7 -	**	poo.	100.10	11.1	100.10	200.10
1T0919133B 9B9	Seal Ring Satin Black X NN	1	pcs.	0.87	#1	0.87	0.93
1S0919275C GRU	Sensor Primed 7	1	pcs.	190.18	#1	190.18	203.49
1T0919133C 9B9	Seal Ring Satin Black X Nn	1	pcs.	0.87	#1	0.87	0.93
7N0853651F 9B9	Radiator Grille Satin Bla	1	pcs.	739.52	#1	739.52	791.29
7N0853600A FOD	Vw Sign Black High Gloss/ MY	1	pcs.	141.79	#1	141.79	151.72
7N0853677 9B9	Grill Satin Black BUMPER CTR LOWER GRILLE?	nn ¹	pcs.	251.12	#1	251.12	268.70
7N0853101 2ZZ	Decorative Moulding Brigh BUMPER CTR LOWER GRILLE CHR	X 1	pcs.	239.35	#1	239.35	256.10
7N0853666B 9B9	Cooling Air Grill Satin B RHS FOG LAMP GRILLE	1	pcs.	189.91	#1	189.91	203.20
N0807244 2ZZ	Protective Strip Bright C	ne/1	pcs.	120.75	#1	120.75	129.2
N2941753B	Headlamps For Curve Light 3 × nn	4	pcs.	2,669.12	#1	2,669.12	2,855.9
N2941754B	Headlamps For Curve Light	1	pcs.	2,669.12	#1	2,669.12	2,855.9
10721806	Gas Discha	1	pcs.	634,25	444	624.25	678.6
	Halogen Bulb 'Longlife'	1	pcs.	40.84	#1	634.25	43.7
10256407	Bulb Yellow Glass 'Longli	;			#1	40.84	
T0941329A	Control Unit For Cornerin MI>	1	pcs.	9.63	#1	9.63	10.3
	Pollact For Con Discharge Ast \$		pcs.	695.74	#1	695.74	744.4
	Ballast For Gas Discharge M1	1	pcs.	946.95	#1	946.95	1,013.2
	Power Module For Day Driv MA.)	1	pcs.	469.86	#1	469.86	502.7
2)	Flat Contact Housing With 3	1	pcs.	21.54	#1	21.54	23.0
/HT000372	H/LAMP WIRE HOUSING	9249				74477920571	manna
	Hexagon Socket Head Bolt Mar	2	pcs.	4.22	#1	8.44	9.0
	Halogen Fog Lights With S 2 CM	1	pcs.	372,13	#1	372.13	398.1
N0805588D	Lock Carrier With Mountin 7.	1	pcs.	1,247.85	#1	1,247.85	1,335.2
N0805567B	Support For Lock Carrier 7	1	pcs.	132.81	#1	132.81	142.1
N0805932	Cross Support RHS H/LAMP TOP PANEL 3 164	/ i	pcs.	66.53	#1	66.53	71.1
12E050A2	Coolant 1B 7	2	pcs.	22.95	#1	45.90	49.1
AA951221B	Horn Cre/	1	pcs.	151.73	#1	151.73	162.3
N0951182C	Halter Fuer Signalhorn 764 /	i	pcs.	37.20	#1	37.20	39.8
N0821022B	Fender hu	1	pcs.	714.05	#1	714.05	764.0

DLKSWAGEN CENTRE SINGAPORE

,7 Alexandra Road ingapore 159934

Ms.

POON

#15-31

YEN LING

29 KOVAN ROAD

Singapore 545022

3iz. Reg. No.: 199101494Z GST No.: M200985052







Quotation

Non binding - Preview

Page

3/4

Document no.

Document date Customer no.

13-12-2022 5211033201

Customer GST-ID

Dealer

30001

Total amount

excl. GST

53.04

173.61

11.88

7.92

195.00

040.00

< 80.00

400.00

500.00

Job order number Job order date 2022036092/ 1

Service Advisor

12-12-2022 SHU SHI TANG

Unit price

excl. GST

53.04

173.61

1.98

1.32

195.00

840.00

800.00

80.00

400.00

100.00

License plate | Model code SND78P | 7N24MYH2

Model code First registration 7N24MYH2 26-03-2021

WVWZZZ7NZMV002696

1

Quantity Unit

pcs.

Model Sharan Highline 2.0 TSI 162kW DSG Toulon

Tax code

#1

#1

#1

#1

#1

#1

#1

#1

#12520 5

#1400 4,800.00

Mileage 35,440

Total amount

incl. GST

56.75

185.76

12.71

208.65

5,392.80

5,136.00

85.60

428.00

535.00

8.47

Position no. Description

7N0821136A Cross Support
RHS FENDER BRACKET

7N0805912B Wheelhouse Liner
RHS FENDER LINER
WHT004694 Expanding Nut
Hexagon Socket Head Panel
Towing assistance - AWP Fault?
LABOUR

Expanding Nut Above Hexagon Socket Head Panel A Towing assistance - AWP ABOUR SPRAY PAINT FRT NUMBER PLATE AND SPRAY RHS FRT RIM ACOATING INVOICE.

Colourgloss Respray CHINA TAIPING DIRECT

DOA: 10/12/2022 TP VEH: YQ2951G SURVEY BY:

Quotation valid till 19-12-2022

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	1,750.00	31,301.07	7%	2,313.57	33,051.07	35,364.64
Total	1,750,00	31,301.07		2,313,57	33,051.07	35,364.64

Cus	tomer
-----	-------

Service Advisor

----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).----

DLKSWAGEN CENTRE SINGAPORE

17 Alexandra Road singapore 159934

Biz. Reg. No.: 199101494Z GST No.: M200985052





Quotation Non binding - Preview

Page

4/4

Document no. Document date Customer no.

13-12-2022 5211033201

Customer GST-ID Dealer

Job order number

30001 2022036092/1 12-12-2022

Job order date Service Advisor

SHU SHI TANG

License plate SND78P

Ms.

POON

#15-31

YEN LING

29 KOVAN ROAD

Singapore 545022

Model code **7N24MYH2** First registration 26-03-2021

WVWZZZ7NZMV002696

Sharan Highline 2.0 TSI 162kW DSG

Mileage 35,440

Toulon

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Pasul Hp 90010068 8days 14/12/22 @1445 Resy before print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver

- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this Porm by insurance companies is not an admission of policy habiting of the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving of this report will be forwarded by the insurers of the distribution of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 12/12/2022 10:37 (SGT) Reported by Both Date of Accident

10/12/2022 09:40 (SGT) **Exact Location of Accident** Singapore

Additional Location Information

AT ANG MO KIO AVE 10, OUTSIDE BLOCK 457 MAIN ROAD Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SND78P

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner NRIC No

Email Address Mobile Phone No.

Alternative Phone No.

No

POON YEN LING SXXXX450G

PAULINEP1403@HOTMAIL.COM (Phone) +65-98359535

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category Transmission

CC

Volkswagen

Sharan

Sharan Highline 2.0 TSI 162kW DSG Toulon

Private use

No - Claiming third party

Private car

Auto

2000

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number

AXA Insurance Pte Ltd P2430366

DRIVER

Name of Driver NRIC No Date Of Birth Occupation

POON YEN LING SXXXX450G 14/03/1978 Indoor



Date Of Driving Pass 27/09/2004 Driving experience 18 YEARS AND 3 MONTHS Female Gender (Phone) +65-98359535 Mobile Number Alt. Phone Number PAULINEP1403@HOTMAIL.COM Email Address 29 KOVAN ROAD Address #15-31 Address complement 545022 Postcode Yes Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface

Collision - Change/cross lane

Clear Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement

No 2

Yes

2

PASSENGER 1

Name Gender AMANDA YEO KAI QING

Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? Police Station Name Police Station Phone No. Alt. Police Station Phone No Police Station Address Was notice of intended Prosecution given? If yes, against whom?

Yes Ang Mo Kio Division Headquarters (Phone) +65-18002180000 (Fax) +65-64814246 51 Ang Mo Kio Avenue 9 Singapore 569784 No

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO POLICE REPORT AND SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Yes Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YQ2951G
Vehicle Manufacturer	3
Vehicle Model	
Vehicle Variant	
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	₩
Contact Number	
Address	B)
Address complement	-
Postcode	-
Insurance Company Name	<u> </u>
Nature Of Damage	•
Details of property damaged in accident	*
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wiful misrepresentation or withholding of material facts may allow insurance companies to repudrate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of poscy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- 6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of.
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any anguiries by me;
- (iv) administering my claims (including the mailing of correspondence, stalements, invokes, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the 'Purposes')
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect. use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Pérsonal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (encluding their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Actual Oriver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Course Personnel (Name as in NRICIID card)

Sketch Plan



Describe Circumstance of the Accident
Date: 12/12/2022
Time: 9.4) am Location. Any Mo Kio Ave 10, outside block 457 Main road.
After exited Any Mokin Avelo block 457 carpark, I was along street 44
and stopped behind a truck (XD2965Y) that parked along the street
whose herard light was switched on, to check for on coming
traffic. (It is a dual carriageway with single lane)
linched forward to move off Suddenly from my right side-
mirror, I saw the lorry (YQ29156) driving very fast around
the worner behind me travelling on the opposite lane against
traffic, the larry (YQ2915G) did not stop in time and hit
front to the
traffic, the larry (YQ2915G) did not stop in time and hit front to the My car (SND78P) from the right fender until front bumper
and bonnet.
Refer to police report number: F/20221210/7048

Declaration

(Windeclare the foregoing particulars are true in every respect

γ,

Policyholaer's Signature / Date & Time Actual Discerts Signature (if driver a not the policyholaer) Witnessed to Reporting Corne Personnell (Name as in NR.C. Discret)

Witnessed D. Resorting Corne Personnel

-j---2





1 of 3

Report No. F/20221210/7048

POLICE REPORT (NP299)

Police Station Of Origin Ang Mo Kio Division HQ 51 Ang Mo Kio Avenue 9 SINGAPORE 569784 Tel No:1800-2180000

Date/Time Report Made	Vide Rep	ort No.		Station Diary No
10/12/2022 18:24				
Name Of Informant	Address			
POON YEN LING	29 KOVA	N ROAD	#15-31 SINGAPO	RE 545022
ID Type / ID No. NRIC NO / S7807450G	Contact N Home/Of		Mobile: 98359535	1
Nationality SINGAPORE CITIZEN	Email Ad-		HOTMAIL.COM	
Occupation	Sex	Age	Date of Birth	Race
Human resource consultant (excluding executive search consultant)	Female	44	14/03/1978	Chinese
Institution/School Name	Language English			
Date/Time Of Incident 10/12/2022 09:40 - 10/12/2022 10:00	Location Of Incident 457 ANG MO KIO AVENUE 10 TECK GHEE GRANDEUR SINGAPORE 560457		GHEE	

After exiting Ang Mo Kio Street 44 of Block 457, I was driving along Street 44 and stopped behind a truck (XD2965Y) that parked along the street whose hazard light was switched on, to check for oncoming traffic. (It was a dual carriageway with single lane)

I was itching forward to check the traffic but suddenly from the right side mirror, I saw the lorry (YQ2915G) driving very fast around the corner behind me travelling on the opportunity lane against the

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 10/12/2022 18:24
Officer In-Charge Of Case:	Classification Of Case





2 of 3

Report No. F/20221210/7048

POLICE REPORT (NP299) CONTINUATION OF REPORT

traffic, the lorry (YQ2915G) did not stopped in time and hit my car (SND78P) from the right feeder to the front bumper and bonnet.

I was having dizziness, chest tightness and neck pain thus I was attended by the paramedic. I was sent to Sengkang Hospital for further medical attention and was given a thorough check by the doctor with Xray done. I was given medication on the spot and was sent home after observation with 3 days of medical leave given.

F/20221210/0116 IO Intan

Victim		The second section is	
Person Name	POON YEN LING		
ID Type	NRIC NO	ID No	S7807450G
Gender	Female	Age	44
Race	Chinese	Language	English
Occupation	Human resource consultant (excluding executive search consultant)	Address	29 KOVAN ROAD #15-31 SINGAPORE 545022
Mobile No	98359535	Is Informant A Victim?	Yes

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 10/12/2022 18:24
Officer In-Charge Of Case:	Classification Of Case:





Explained while his high state before

MARCH SENT WHITE KIND SHE

Signature Of Officer Recording The Report Not applicable

Signature Of Interpreter. Not applicable

Officer to Ocume Of Case

A. S. S. Charles of SVI 122 Comme

Signature Of Informant

The identity of the person making this report has been authenticated by Singuess No signature is required.

Date/Time 10/12/2022 18:24

Classification Of Case

Enquire PARF/COE Rebate for Registere	d Vehicle
Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	450G
Vehicle Details	
Vehicle No.:	SND78P
Vehicle to be Exported:	No No
Intended Deregistration Date:	15 Dec 2022
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SHARAN 2.0TSI
Primary Colour:	White
Manufacturing Year:	2020
Engine No.:	DED036063
Chassis No.:	WVWZZZ7NZMV002696
Maximum Power Output:	162.0 kW (217 bhp)
Open Market Value:	\$33,968.00
Original Registration Date:	26 Mar 2021
First Registration Date:	26 Mar 2021
Transfer Count:	0
Actual ARF Paid:	\$39,556.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARE Eligibility Expiry Date	25 Mar 2031

PARF Eligibility Expiry Date

PARF Rebate Amount: \$29,667.00 **Intended COE Rebate Details**

COE Expiry Date: 25 Mar 2031

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$47,001.00

COE Rebate Amount: \$38,902.00

\$68,569.00 Total Rebate Amount:

The information contained herein is correct as at 15 Dec 2022

Volkswagen Sharan 2.0A TSI Sunroof

<u>Overview</u> Fir	nancial Accessories Si	milar Research	Photos Map
Price	\$176,988		
Depreciation (2)	\$18,590 /yr View models with similar depre	Reg Date	28-May-2021 (8yrs 5mths 12days COE left)
Mileage	14,000 km (9k /yr)	Manufactured (7)	2020
Road Tax	\$1,194 /yr	Transmission	Auto
Dereg Value (\$80,465 as of today (change)	OMV 2	\$34,049
COE (7)	\$60,001	ARE	\$39,669
Engine Cap	1,984 cc	Power	162.0 kW (217 bhp)
Curb Weight (1,790 kg	No. of Owners	
Type of Vehicle	MPV		