ASS. FEC. BY: UNSWE REF: CS CT 22	1012460/RUP3
•	1 12001
ASS. Fac. 61: 20 DASME CS CT LZ	Wein No.: SNO 788 YE Regn: 2021 7 MAIL Type M.Carl M.Cycle I Bus I Vand Long I Taxil Prime Mover I Truck I Trailer or  Make: Volksum You SHARGN 20 Bloc 1984 Colour WHITE AC: Insured I Std I NI I NA Sp. Reading 3544 Tradio: Insured I Std I NI I NA Eng. No: C/No: WVW 2227 NZM V 80 2686 Gen. Cond: Good I Fair Poor I Burnt Steering: Inorder I Jammed I Leaked I Burnt or Brake: Inorder I Jammed I Leaked I Burnt or Modi: NII I Strin I STD Afrim or Tyre Size: F: 225 VSR 18
Benedit	R:
repair at the time of inspection.	BS1DUN1EXNOVA/GY1FS1LIZA/MICIOHTSU1PIR)SUMI1
Bal. or Market Value: 173K	~  <u>-</u>
IDAC Accident Rport: Consistent?: Yes or No	R/Bai. O mm R/Bai.
GIA / PR Seen: Consistent?: Yes or No	17Bal 17Dal 17Dal
Est Repairs: days Res.: Yes or No	D.O.A. 16/12/22 D.O.I. 14/1222
Lum Sum: % 3 Val.: Yes or No	Survey held at Volksugher
CA / REV / REP. / 24 HRS  Vehicle: IN 1-OU	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roottop er
	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction  REPAIR LINIT - 1044	
	<u></u>
Date/Time, File Pass to?	Days Of Repair:
1) : Final Report Date/Time, File Return to?	Reservey No. of Trip: Survey Fee:
2) Add Fe	Transportation:  Site Insp (\$ ) S+RS. SI
Report Format:	: Interview (\$ ) Photes
Lump Sum / I.B.I: (\$	rech. Invs (\$ ) Others
)	:Waakend (\$

### **VOLKSWAGEN CENTRE SINGAPORE**

247 Alexandra Road Singapore 159934 Biz. Reg. No.: 199101494Z GST No.: M200985052







Quotation Non binding - Preview

Page

1/4

Document no. Document date Customer no.

13-12-2022 5211033201

Customer GST-ID

30001

Dealer Job order number

2022036092/1

Job order date Service Advisor 12-12-2022 SHU SHI TANG

License plate SND78P

Ms.

POON

#15-31

YEN LING

29 KOVAN ROAD

Singapore 545022

Model code 7N24MYH2 First registration 26-03-2021

VIN WVWZZZ7NZMV002696 Model

Sharan Highline 2.0 TSI 162kW DSG Toulon

Mileage 35,440

NAME OF TAXABLE PARTY.			Unit	Unit price excl. GST	Tax code	Total amount T excl. GST	otal amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNES REPAIR	ss			#1	280.00	299.60
9801B005	<b>B&amp;P DIAGNOSIS AND PROGRAMMING</b>				#1	480.00	513.60
9801B002	<b>B&amp;P LEAKED CHECK, VACUUM &amp; REGA</b>	S			#1	420.00 ?	449.40
9801B002	A/C GAS				#1	60.00 ?	64.20
9801B003	B&P WHEEL ALIGNMENT				#1	360.00	385.20
9801B001	R&R RIM & BALANCE				#1	50.00	53.50
9801B001	TO ALIGN HEADLIGHT				#1	100.00	107.00
7N2819404B 9B9	Water Deflector Satin Bla RHS WIPER COWLING	1	pcs.	103.86	#1	103.86	111.13
7N0823031A	Hood La	1	pcs.	1,796,13	#1	1,796.13	1,921.86
8E0823429A	Jounce Bumper *** BONNET STOP BUFFER 7	ZI	pcs.	23.83	#1	47.66	51.00
7N0823301B	Flap Hinge	1	pcs.	194.26	#1	194.26	207.86
7N0823302B	Flap Hinge # /	1	pcs.	194.26	#1	194.26	207.86
1Q0823480	Hook BONNET LATCH } \	1	pcs.	105.83	#1	105.83	113.24
N 90820401	Bolt Hex. Hd. Au	3	pcs.	4.00	#1	12.00	12.84
7N1823509B	Hood Latch Lower Portion 2 4 / BONNET LOCK	1	pcs.	160.93	#1	160.93	172.20
7N0863831	Hood Silencer BONNET INSULATOR	1	pcs.	316.21	#1	316.21	338.34
7N0807217J GRU	Cover For Bumper Primed &	1	pcs.	2,212.59	#1	2,212.59	2,367.47
7N0805903 9B9	Front Spoiler Satin Black X	1	pcs.	180.73	#1	180.73	193.38
7N0807205 GRU	Cap Primed TOWING COVER 3	1	pcs.	71.34	#1	71.34	76.33
7N0807183A	Guide Piece BUMPER SIDE BRACKET LH	1	pcs.	44.68	#1	44.68	47.81
N0807184A	Guide Piece BUMPER SIDE BRACKET RH	1	pcs.	44.68	#1	44.68	47.81
N0807724	Support Part RHS NOZZLE CYLINDER BRACKET	1	pcs.	36.70	#1	36.70	39.27
N0807192	Guide Piece BUMPER CTR BRACKET	1	pcs.	160.06	#1	160.06	171.26
N0807109D	Bumper Bracket 3 K	1	pcs.	944.96	#1	944.96	1,011.11
N0955979	Pressure Cylinder RHS NOZZLE CYLINDER	1	pcs.	211.03	#1	211.03	225.80
N0955104	Jet Carrier With Jet 3× RHS NOZZLE	1	pcs.	48.98	#1	48.98	52.41
7N0807938A GRU	RHS NOZZLE COVER 3/1/1/2)	1	pcs.	70,36	#1	70.36	75.29

### **OLKSWAGEN CENTRE SINGAPORE**

47 Alexandra Road Singapore 159934

Ms.

POON

#15-31

YEN LING

29 KOVAN ROAD

Singapore 545022

Biz. Reg. No.: 199101494Z GST No.: M200985052







Quotation Non binding - Preview

Page

Document no. Document date Customer no. Customer GST-ID

13-12-2022 5211033201

Dealer

30001

2/4

Job order number Job order date

2022036092/1

Service Advisor

12-12-2022 SHU SHI TANG

License plate Model code First registration VIN SND78P 7N24MYH2 26-03-2021 WVWZZZ7N	Model Mileage WV002696 Sharan Highline 2.0 TSI 162kW DSG 35,440 Toulon
---	--

1	1 1			louion		1	
Position no.	Description	Quantity	/ Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
1J0955665E	Elbow L-JOINT 3×	1	pcs.	18.44	#1	18.44	19.73
8D0955873	Distributor Piece } ×	1	pcs.	20.77	#1	20.77	22.22
1J0955964F	Hose In Coils Of 5m 'Orde X	1	pcs.	34.73	#1	34.73	37.16
1J0955846	Clip ner/	6	pcs.	1.70	#1	10.20	10.91
1T0919297A GRU	PARKING SENSOR (SIDE) 7 -	1	pcs.	190.18	#1	190.18	203.49
1T0919133B 9B9	Seal Ring Satin Black 🖈	1	pcs.	0.87	#1	0.87	0.93
1S0919275C GRU		1	pcs.	190.18	#1	190.18	203.49
1T0919133C 9B9	Seal Ring Satin Black X	1	pcs.	0.87	#1	0.87	0.93
7N0853651F 9B9	Radiator Grille Satin Bla C	_ 1	pcs.	739.52	#1	739.52	791,29
7N0853600A FOD	Vw Sign Black High Gloss/ MY/	1	pcs.	141.79	#1	141.79	151.72
7N0853677 9B9	Grill Satin Black 7, BUMPER CTR LOWER GRILLE 7	<b>⋌</b> ¹	pcs.	251.12	#1	251.12	268.70
7N0853101 2ZZ	Decorative Moulding Brigh BUMPER CTR LOWER GRILLE C	× 1	pcs.	239.35	#1	239.35	256.10
7N0853666B 9B9	Cooling Air Grill Satin B RHS FOG LAMP GRILLE		pcs.	189.91	#1	189.91	203.20
7N0807244 2ZZ	Protective Strip Bright C RHS FOG LAMP GRILLE CHROMI Headlamps For Curve Light 2	Zne/1	pcs.	120.75	#1	120.75	129.20
7N2941753B	THE THE TOTAL STATE OF THE STAT		pcs.	2,669.12	#1	2,669.12	2,855.96
7N2941754B	Headlamps For Curve Light	1	pcs.	2,669.12	#1	2,669.12	2,855.96
N 10721806	Gas Discha	1	pcs.	634,25	#1	634.25	678.65
N 10320102	Halogen Bulb 'Longlife'	1	pcs.	40.84	#1	40.84	43.70
N 10256407	Bulb Yellow Glass 'Longli (	1	pcs.	9.63	#1	9.63	10.30
1T0941329A	Control Unit For Cornerin MI>	1	pcs.	695.74	#1	695.74	744.44
8K0941597E	Ballast For Gas Discharge M1	i	pcs.	946.95	#1	946.95	1,013.24
4G0907697	Power Module For Day Driv May	•	pcs.	469.86	#1	469.86	502.75
3C0973737	Flat Contact Housing With 1	, i	pcs.	21.54	#1	21.54	23.05
WHT000372	Hexagon Socket Head Bolt	2	200	4.22	#1	8.44	9.03
7N0941700C	Halogen Fog Lights With S	1	pcs. pcs.	4.22 372.13	#1	372.13	398.18
7N0805588D	Lock Carrier With Mountin 7.		222	4 047 05	114	4 047 05	1,335.20
7N0805567B	Support For Lock Carrier ?	!	pcs.	1,247.85	#1	1,247.85	142.11
7N0805932	Cross Support	1	pcs.	132.81	#1	132.81	
G 12E050A2	RHS H/LAMP TOP PANEL 376	-/ 1	pcs.	66.53	#1	66.53	71.19
3AA951221B	Coolant 1B	2	pcs.	22.95	#1	45.90	49.11
7N0951182C	Horn Cre	1	pcs.	151.73	#1	151.73	162.35
7N0821022B	Halter Fuer Signalhorn 764	1	pcs.	37.20	#1	37.20	39.80
1002 10220	RH hu	1	pcs.	714.05	#1	714.05	764.03

### **DLKSWAGEN CENTRE SINGAPORE**

7 Alexandra Road ingapore 159934

3iz. Reg. No.: 199101494Z GST No.: M200985052







Quotation

Non binding - Preview

Page

3/4

Document no.

Document date Customer no.

13-12-2022 5211033201

**Customer GST-ID** 

Dealer

30001

Job order number Job order date

2022036092/1

Service Advisor

12-12-2022 SHU SHI TANG

License plate	
SND78P	

Ms.

POON

#15-31

YEN LING

29 KOVAN ROAD

Singapore 545022

Model code **7N24MYH2**  First registration 26-03-2021

CHINA TAIPING DIRECT DOA: 10/12/2022 TP VEH: YQ2951G SURVEY BY:

WVWZZZ7NZMV002696

Model Sharan Highline 2.0 TSI 162kW DSG Toulon

Mileage 35,440

Total amount

incl. GST

56.75

185.76

12.71

8.47

208.65 5,392.80

5,136.00

85.60

428.00

535.00

Position no.	Description	Quantity	Unit	Unit price excl. GST		al amount excl. GST
7N0821136A	Cross Support RHS FENDER BRACKET	1	pcs.	53.04	#1	53.04
7N0805912B	Wheelhouse Liner RHS FENDER LINER	1	pcs.	173.61	#1	173.61
WHT004694	Expanding Nut A	6	pcs.	1.98	#1	11.88
N 90974701	Hexagon Socket Head Panel	6	pcs.	1.32	#1	7.92
	Towing assistance - AWP Taupt	1 _	pcs.	195.00	#1	195.00
	LABOUR	83	pcs.	840.00	#12520	5,040.00
	SPRAY PAINT	85	pcs.	800.00	#1 <b>(</b> 501 <b>)</b>	4,800.00
	FRT NUMBER PLATE 🗴	1	pcs.	80.00	#1 `	× 80.00
	SPRAY RHS FRT RIM 🚣 🖊	1	pcs.	400.00	#1	400.00
	COATING invola.  Colourgloss Respray	5	pcs.	100.00	#1	500.00

#### Quotation valid till 19-12-2022

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	1,750.00	31,301.07	7%	2,313.57	33,051.07	35,364.64
Total	1,750.00	31,301.07		2,313.57	33,051.07	35,364.64

Customer	Service Advisor

----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).---

### **DLKSWAGEN CENTRE SINGAPORE**

47 Alexandra Road singapore 159934

Biz. Reg. No.: 199101494Z GST No.: M200985052







Quotation
Non binding - Preview

Page

4/4

Document no.
Document date
Customer no.

13-12-2022 5211033201

Customer GST-ID Dealer

30001

Job order number Job order date Service Advisor 2022036092/ 1

12-12-2022 SHU SHI TANG

License plate SND78P

Ms.

POON

#15-31

YEN LING

29 KOVAN ROAD

Singapore 545022

Model code 7N24MYH2 First registration 26-03-2021

VIN WVWZZZ7NZMV002696 Model

Toulon

Sharan Highline 2.0 TSI 162kW DSG

Mileage 35,440

All invoices are denominated in SGD, unless otherwise stated.

## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Pasul Hp 90010068 8days 14/12/22 @1445 Resy before print

# SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver

- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this Porm by insurance companies is not an admission of policy habiting of the part of the insurance companies.
   5. Any false reporting may be referred to the Police for investigation.
   6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving of this report will be forwarded by the insurers of the CICA for a fee, be made available upon application by interested parties.

  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date of Submission 12/12/2022 10:37 (SGT) Reported by Both Date of Accident 10/12/2022 09:40 (SGT) **Exact Location of Accident** 

Singapore Additional Location Information

AT ANG MO KIO AVE 10, OUTSIDE BLOCK 457 MAIN ROAD Country/State of Loss

Singapore

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number SND78P

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner

NRIC No **Email Address** 

Mobile Phone No Alternative Phone No. No

POON YEN LING SXXXX450G

PAULINEP1403@HOTMAIL.COM

(Phone) +65-98359535

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category

Transmission

CC

Volkswagen

Sharan

Sharan Highline 2.0 TSI 162kW DSG Toulon

Private use

No - Claiming third party

Private car

Auto

2000

INSURANCE COMPANY

Name of Insurance Company

Policy Number / Cover Note Number

DRIVER

Name of Driver

NRIC No Date Of Birth

Occupation

Accident report SV1122CC0002

AXA Insurance Pte Ltd

P2430366

POON YEN LING SXXXX450G 14/03/1978 Indoor

27/09/2004 Date Of Driving Pass Driving experience 18 YEARS AND 3 MONTHS Female Gender (Phone) +65-98359535 Mobile Number Alt, Phone Number PAULINEP1403@HOTMAIL.COM Email Address 29 KOVAN ROAD Address #15-31 Address complement 545022 Postcode Yes Is the driver the policyholder? If No, Relationship of the Driver with the Insured No Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface

Collision - Change/cross lane

Clear Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement

2

Yes

2

#### PASSENGER 1

Name Gender

AMANDA YEO KAI QING

Female

#### **DETAILS OF POLICE ACTION**

Was the accident reported to the police? Police Station Name Police Station Phone No. Alt. Police Station Phone No Police Station Address Was notice of intended Prosecution given? If yes, against whom?

Yes Ang Mo Kio Division Headquarters (Phone) +65-18002180000 (Fax) +65-64814246 51 Ang Mo Kio Avenue 9 Singapore 569784 No

CIRCUMSTANCES OF ACCIDENT

### PLEASE REFER TO POLICE REPORT AND SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Yes Yes

### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	YQ2951G
Vehicle Manufacturer	•
Vehicle Model	E
Vehicle Variant	•
Vehicle Colour	•
Vehicle Category	Commercial vehicle
Name of Driver	•
Contact Number	-
Address	•
Address complement	-
Postcode	•
Insurance Company Name	<u>*</u>
Nature Of Damage	•
Details of property damaged in accident	
No. Of Passenger (Including Driver)	•

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as <u>truthful</u> and <u>accurate as possible</u>. Any wiful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of poscy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the
  report burns made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agencylauthority (such as the police), for the purpose(s) of.
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invokes, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the 'Purposes')
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


WV

Policyholder's Signature / Date & Time

Actual Oriver's Signature (if driver is not the policyholder) / Oate & Time

Witnessed by Reporting Contre Personnel (Name as in NRIC/ID card)

Sketch Plan



Describe Circumstance of the Accident
Date: 10/12/2022
Time: 9.4) am Location. Any Mo K.o Ave 10, outside block 457 Main road.
After exited Any Mokin Ave lo block 457 carpark, I was along street 44
and stopped behind a truck (XD2965Y) that parked along the street
whose hererd light was switched on, to check for on coming
traffic. (It is a dual carriageway with single lane)
linched forward to move off Suddenly from my right side-
mirror, I saw the lorry (YQ2915G) driving very fast around
the worner behind me travelling on the opposite lane against
traffic, the larry (YQ.2915G) did not stop in time and hit
front to the
traffic, the larry (YQ2915G) did not stop in time and hit front to the My car (SND78P) from the right fender until front bumper
and bonnet.
Refer to police report number: F/20221210/7048

Declaration

(Win declare the foregoing particulars are true in every respect

Policyholaer's Signature / Date & Time Actual Dever's Signature (if driver is not the policyholaer) Witnessed by Reporting Correl Personnell (Name as in NR.C...) curd)

december 1





1 of 3

Report No. F/20221210/7048

#### **POLICE REPORT (NP299)**

Police Station Of Origin Ang Mo Kio Division HQ 51 Ang Mo Kio Avenue 9 SINGAPORE 569784 Tel No:1800-2180000

Vide Report No.		Station Diary No.		
Address				
29 KOVA	N ROAD	#15-31 SINGAPO	RE 545022	
Contact No. Home/Office: Mobile: 98359535				
Email Address				
		Date of Birth	Race	
Female	44	14/03/1978	Chinese	
Language English				
Location Of Incident 457 ANG MO KIO AVENUE 10 TECK GHEE				
	Address 29 KOVA Contact N Home/Of Email Add PAULINE Sex Female Language English Location 0 457 ANG	Address 29 KOVAN ROAD Contact No. Home/Office:  Email Address PAULINEP1403@H Sex Age Female 44  Language English Location Of Inciden 457 ANG MO KIO A	Address 29 KOVAN ROAD #15-31 SINGAPO Contact No. Home/Office: Mobile: 98359535 Email Address PAULINEP1403@HOTMAIL.COM Sex Age Date of Birth Female 44 14/03/1978  Language English Location Of Incident	

After exiting Ang Mo Kio Street 44 of Block 457, I was driving along Street 44 and stopped behind a truck (XD2965Y) that parked along the street whose hazard light was switched on, to check for oncoming traffic. (It was a dual carriageway with single lane)

I was itching forward to check the traffic but suddenly from the right side mirror, I saw the lorry (YQ2915G) driving very fast around the corner behind me travelling on the opportunity lane against the

Signature Of Informant: The identity of the person making this report has been authenticated by Singpass No signature is required.
Date/Time: 10/12/2022 18:24
Classification Of Case





2 of 3

Report No. F/20221210/7048

### POLICE REPORT (NP299) CONTINUATION OF REPORT

traffic, the lorry (YQ2915G) did not stopped in time and hit my car (SND78P) from the right feeder to the front bumper and bonnet.

I was having dizziness, chest tightness and neck pain thus I was attended by the paramedic. I was sent to Sengkang Hospital for further medical attention and was given a thorough check by the doctor with Xray done. I was given medication on the spot and was sent home after observation with 3 days of medical leave given.

#### F/20221210/0116 IO Intan

Subjects Involved	d	LE CARRENTE D			
Victim		- Colored Francisco	Action of the second		
Person Name	POON YEN LING				
ID Type	NRIC NO	ID No	S7807450G		
Gender	Female	Age	44		
Race	Chinese	Language	English		
Occupation	Human resource consultant (excluding executive search consultant)	Address	29 KOVAN ROAD #15-31 SINGAPORE 545022		
Mobile No	98359535	Is Informant A Victim?	Yes		

Signature Of Officer Recording The Report:	Signature Of Informant:		
Not applicable	The identity of the person making this report has been authenticated by Singpass No signature is required.		
Signature Of Interpreter: Not applicable	Date/Time: 10/12/2022 18:24		
Officer In-Charge Of Case:	Classification Of Case:		





Explained while his high state before

MARCH SON STREET, KINGSTER

Signature Of Officer Recording The Report Not applicable

Signature Of Interpreter. Not applicable

Officer to Charge Of Case

A. S. S. Change of SVI 1991 Comm.

Signature Of Informant

The identity of the person making this report has been authenticated by Singuess No signature is required.

Date/Time 10/12/2022 18:24

Classification Of Case

Enquire PARF/COE Rebate for Registered Vehicle	
Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	450G
Vehicle Details	
Vehicle No.:	SND78P
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Dec 2022
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SHARAN 2.0TSI
Primary Colour:	White
Manufacturing Year:	2020
Engine No.:	DED036063
Chassis No.	WWWZZZ7NZMV002696
Maximum Power Output:	162.0 kW (217 bhp)
Open Market Value:	\$33,968.00
Original Registration Date:	26 Mar 2021
First Registration Date:	26 Mar 2021
Transfer Count:	0
Actual ARF Paid:	\$39,556.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Mar 2031
PARF Rebate Amount:	\$29,667.00
Intended COE Rebate Details	
COE Expiry Date:	25 Mar 2031

COE Category:

B - Car above 1600cc or 97kW (130bhp) 10

COE Period (Years):

\$47,001.00 QP Paid:

\$38,902.00 COE Rebate Amount:

\$68,569.00 Total Rebate Amount:

The information contained herein is correct as at 15 Dec 2022

# Volkswagen Sharan 2.0A TSI Sunroof

Overview Fin	ancial Accessories Sir	milar Research	Photos Map
Price	\$176,988		
Depreciation (2)	\$18,590 /yr View models with similar depre	Reg Date	28-May-2021 (8yrs 5mths 12days COE left)
Mileage	14,000 km (9k /yr)	Manufactured (7)	
Road Tax	\$1,194 /yr	Transmission	Auto
Dereg Value	\$80,465 as of today (change)	OMV (2)	\$34,049
COE ①	\$60,001	ARF	\$39,669
Engine Cap	1,984 cc	Power	162.0 kW (217 bhp)
Curb Weight ( )	1,790 kg	No of Owners	
Type of Vehicle	MPV		