

ASS. REC. BY: T. J. J. J.REF: CS CT122012464/Tnp3

## ASSIGNMENT

OE 20240d.

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$26K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: 55573427Yr Regn: 2009, out

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagenc.c. 1390Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 295209

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WVWZZZ13ZAV410762Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18R: 225/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. \_\_\_\_\_

D.O.I. 14/12/22Survey held at hipost

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

We will be advising our Principal a cost of repair of LS \$6,900/- with 6 days of repair  
(red, \$8653.66, 56%)

Date/Time, File Pass to?

☐

Preli. Report

1) 15/05/23☐

Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 6Resurvey No. of Trip: 2

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

Add Fee: ☐

Site Insp (\$ \_\_\_\_\_)

☐

Interview (\$ \_\_\_\_\_)

☐

Tech. Invs (\$ \_\_\_\_\_)

☐

Weekend (\$ \_\_\_\_\_)

Rep. Format: \_\_\_\_\_

Lump Sum / L.S. / F. \_\_\_\_\_

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	09/12/2022 16:32 (SGT)
Reported by	Both
Date of Accident	08/12/2022 18:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	SENG KANG WEST AVE TO JALAN KAYU
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS7342Z
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	KUHARAJ S/O JEYAPALAN
NRIC No	S9434617G
Email Address	KUHARAJ21@GMAIL.COM
Mobile Phone No	(Phone) +65-8948612
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Volkswagen
Model	Scirocco
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1400

#### INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5113738663-03

#### DRIVER

Name of Driver	KUHARAJ S/O JEYAPALAN
NRIC No	S9434617G
Date Of Birth	19/09/1994
Occupation	Indoor

Date Of Driving Pass	16/09/2015
Driving experience	7 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-8948612
Alt. Phone Number	-
Email Address	KUHARAJ21@GMAIL.COM
Address	BLK 236 YISHUN RING ROAD #10-1010
Address complement	-
Postcode	760236
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER SKETCH PLAN

#### REPAIR AT OWNER'S WORKSHOP

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJP9611A
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")


(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel


**Sketch Plan**

**Describe Circumstances of the Accident**

In the 8th December 2022 at about 6.30pm, I turned Right into Jln Kaye from Sengkang West Ave and there was some children jaywalking across the road so I slowed down and the vehicle behind me SJP4611A Toyota Wish knock into my vehicle Volkswagen Scirocco 1.4 TSI 515 7542 E rear. The driver could not stop as time and it was wet weather.

**Declaration**

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	617G
<b>Vehicle Details</b>	
Vehicle No.:	SJS7342Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	11 Dec 2022
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SCIROCCO 1.4L AT TSI 1372Q5
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	CAV108852
Chassis No.:	WVWZZZ13ZAV410762
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$23,937.00
Original Registration Date:	13 Oct 2009
First Registration Date:	13 Oct 2009
Transfer Count:	4
Actual ARF Paid:	\$23,937.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	12 Oct 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$15,287.00
COE Rebate Amount:	\$5,613.00
<b>Total Rebate Amount:</b>	<b>\$5,613.00</b>
<b>Message</b>	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 10 Dec 2022

OK

b/c OK

HEEEV

**BIFROST AUTO PTE LTD**

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

**Repair Estimate**

Vehicle number: SJS7342Z

Make &amp; Model: Volkswagen Scirocco

Chassis number: WVWZZZ13AV410762

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Tailgate	1	\$ <del>bt</del> 1,601.83
2	Tailgate centre emblem	1	\$ <del>net</del> 68.50
3	Tailgate lock	1	\$ <del>pm</del> 167.50
4	Tailgate lock catch	1	\$ x nn 74.30
5	Tailgate weatherstrip	1	\$ <del>fu</del> 214.60
6	Tailgate inner trim board	1	\$ <del>bn</del> 286.50
7	Tailgate wiper motor	1	\$ x nn 532.10
8	Rear bumper	1	\$ <del>de</del> 1,103.40
9	Rear bumper RH reflector	1	\$ x nn 78.90
10	Rear bumper LH reflector	1	\$ x nn 78.90
11	Rear bumper number plate RH lamp	1	\$ <del>cha</del> 55.70
12	Rear bumper number plate LH lamp	1	\$ <del>cha</del> 55.70
13	Rear bumper inner centre bracket	1	\$ <del>cha</del> 73.20
14	Rear bumper RH side retainer	1	\$ <del>mis</del> 41.20
15	Rear bumper LH side retainer	1	\$ x nn 41.20
16	Rear bumper reinforcement	1	\$ <del>bb</del> 453.17
17	LH taillamp	1	\$ <del>aut</del> 464.30
18	LH taillamp panel	1	\$ x nn 178.20
19	LH taillamp lock clips	1set	\$ x nn 28.00
20	RH taillamp	1	\$ <del>aut</del> 464.30
21	RH taillamp panel	1	\$ x nn 178.20
22	RH taillamp lock clips	1set	\$ x nn 28.00
23	End panel	1	\$ <del>bb</del> 785.90
24	End panel garnish	1	\$ <del>de</del> 119.80
25	Rear fender RH inner trim	1	\$ x nn 343.20
26	Rear fender LH inner trim	1	\$ x nn 343.20
27	Rear spare tyre panel top board	1	\$ x nn 287.50

528



28	Rear spare tyre panel	1	\$ <del>AK</del> 874.20
29	Exhaust silencer	1	\$ <del>761</del> 1,548.90
30	Exhaust silencer gasket	1	\$ <del>24</del> 67.00

1,459

\$ 10,637.40  
 Parts less 10% \$ 1,063.74  
 Total \$ 9,573.66

No.	Special Nett Items	Qty	Amount S\$
1	Tailgate inner trim board clips	1set	\$ <del>30m</del> 80.00
2	Tailgate windscreen glass sealant	1	\$ <del>40 over</del> 80.00
3	Tailgate windscreen glass inner seal	1	\$ <del>30 over</del> 60.00
4	Rear bumper clips	1set	\$ <del>20m</del> 80.00
5	Rear bumper reverse sensor	1set	\$ <del>200m</del> 350.00
6	Rear bumper reverse camera	1	\$ <del>X</del> 750.00
7	End panel garnish clips	1set	\$ <del>20m</del> 60.00
8	Rear fender LH inner trim clips	1set	\$ <del>X</del> 60.00
9	Rear fender RH inner trim clips	1set	\$ <del>X</del> 60.00
10	Rear number plate	1	\$ <del>20m</del> 80.00
11	End panel joint sealant	1	\$ <del>40 over</del> 80.00
12	End panel inner garnish	1	\$ <del>X</del> 60.00
13	RH taillamp panel joint sealant	1	\$ <del>X</del> 50.00
14	LH taillamp panel joint sealant	1	\$ <del>X</del> 50.00

45

Total: \$ 1,890.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,500.00
2	Spray painting on affected areas and panels	\$ 1,200.00
3	Check wiring and lighting system on affected areas	\$ 100.00
4	Apply rust coating chemical on affected areas and panels	\$ 120.00
5	Remove and reinstall tailgate windscreen glass and sealants to assist repair	\$ 200.00



6	Remove and replace tailgate inner mechanism to new tailgate	\$ 60	180.00
7	Remove and replace rear bumper reverse sensors to assist repair	\$ 30	100.00
8	Remove and replace rear inner trims, garnish and boards to assist repair	\$ 60	450.00
9	Remove and replace exhaust silencer and gasket to assist repair	\$ 80	240.00

Total: \$ 4,090.00

Agreed Amount: \_\_\_\_\_ (Part by Part / Lump sum)

Working days: \_\_\_\_\_

Spare Parts: \$ 9,573.66

Special Nett \$ 1,890.00

Labour: \$ 4,090.00

**Total Amount: \$ 15,553.66**

Taufiq 97795749

WP' 14/12/22 & 16/30

4/8 Rising after repair

Taufiq @ kharto.com

• 6 days

- To check consistency of accident
- To check part prices