

ASS. REC. BY: Taufik

REF:

CTI

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: RM14K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seent: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FBR 1104JYr Regn: 2020, Feb.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda PCX150c.c. 149Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: 4264

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MH/KF 2218KR 106660Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: U / S/Rim / STD A/Rim orTyre Size: F: 90/90 R14R: 110/80 R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CST

Front

Rear

R/Bal. 5

mm

R/Bal. 5

mm

L/Bal. _____

mm

L/Bal. _____

mm

D.O.A. _____

D.O.L. 14/2/23Survey held at KLIADes. of Damages: Front / Rear / O/S / N/S / U/G / Rooftop or

The U/G / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech Insp (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS. SI

Photos

Others

Date / Format:

吉维利企业 **KIVILE ENTERPRISE**

BLK 3007 UBI RD 1 #01-408, SINGAPORE 408701

TEL: 6748 8645 FAX: 6748 2533

EMAIL: kivilepc@gmail.com

ROC NO.: 53114844X GST REG NO.: M90370110N

Vehicle No.: FBR1104J

Model: HONDA PCX 150

Description

Handlebar	\$	220	bt
Handlebar Holder	\$	195	? bt ✓
Cover set	\$	600 800	cu ✓
Mudguard	\$	160	cu ✓
Fork set	\$	680	? bt ✓
Fork Lower Brake	\$	380	? bt ✓
Steering Cone	\$	160	? nu ✓
Rim	\$	350	dd ✓
Disc	\$	220	2 nu
Headlamp	\$	750	cu ✓
Headlamp Stay	\$	150	? bt ✓
Mainstand	\$	135	x nu
Foot Pedal LH	\$	95	x nu
Foot Pedal RH	\$	95	ant ✓
Exhaust Pipe Cover	\$	95	ant ✓
Rearbox	\$	280	ant ✓
Body Frame Repair	\$	350	200 ? photo sn
Body Frame Respray	\$	550	200 ? photo sn
Labour	\$	600	300
Transport	\$	150	60

Let Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Resurvey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date

TOTAL

\$ 6,415

Tanfiah 9749 5749 / 6256 3561

np 14/12/22E Rpm

4/5 Resurvey after report

Tanfiah @ khando.com

04 days

Parts - 4115
10% - 3703.50
Labour - 760

4463.50

4583.50

4 days