

REC BY: T. [Signature]

REF: 033 / CA12201247/Typ3

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

OD / CP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop no: _____

of _____

Insured: CB 7140L

Policy No: DMB1SNW00014382104

Claims No: SNM22D207888/C02/TANCHC

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: \$105K

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP' PPS'

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: G659949C Yr Regn: 2019 / Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Pick-up

Make: Mitsubishi L200 D/Cab. cc 2442

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 229148 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MMCJYKLL0KH015303

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: GT / S/Rim / STD A/Rim or

Tyre Size: F: 205 / R16
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI / TOYO / YOKO, or

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 2/11/2022 D.O.L. 14/12/22 e17pm

Survey held at Yap Motor

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or Fnt MS

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
16/2/23	Repair Range: \$4,000-95000 & 5 days.

Date/Time, File Pass to? : Prel. Report

1) : Final Report

Date/Time, File Return to? 2 16/2/23-typist

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee:	_____
Transportation:	_____

Add Fee: : Site Insp (\$) : Interview (\$) : Test Drive (\$)

Large Burn / B.H. / E