

Our Job Ref No : 305539355

Date : 17/12/22

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508989  
Fax: 6546 8156**FINALIZATION FORM**

To : LKK

Fax :

Attn : Mr Naz

Vehicle Reg No. : SHA9191Y

13.12.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: INCOME -- SJT5665A
2. The finalized amount shall be:
- (a) Spare Parts after List discount
- (b) Labour Charges \$0.00
- Total for Part-By-Part Repair Cost**
- (c.) Lumpsum Repair (if applicable)
- Total for Lumpsum repair cost after Less: 20% \$1,000.00 \$800.00
- Final Lumpsum Repair cost \$1,000.00 \$800.00
3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.
- We confirm the estimates and finalized amount

Signature : 

Name : Ms. Loke YY

Tel : 62148355

Fax : 65468156

Signature : 

Name : NAZ LKK

Date : 6/1/2023

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: