ASS	SIGNMENT
From:	Veh No: 3mP9288P Yr Regn: 2019, Ayn
From: Date: Estimated Cost:	Type: (M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
	Make: Toyola Steuta. c.c /496.
To Inspect Vehicle No:	
at Workshop m/s	9.0
of	
Insured:	Eng/No:
Policy No.	C/No: MHFZ28H3500064490.
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modí: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 185/60R15
(Policy Condition)	R: 185/60R15
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MHC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or
Bal. or Market Value:	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 06 mm R/Bal. 06 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 06 mm L/Bal. mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 14/12/22
Lum Sum: % 3 Val.: Yes or No	Survey held at MG Solution.
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OU	Т
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	
TP Chymi.	THE RESERVE ASSESSED.
M1/ .	
MV:	Control of the contro
Nett:	
7101	
	7281
Силининай	120+
Date/Time, File Pass to? : Preli. Report-	Days Of Repair:
1) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add Fe	
	F F 1
Peport Formet:	: Interview (\$) Photos : Tech. Inve (\$) Office