

Enquire Vehicle's Insurance Particulars

Enquire Vehicle's Insurance Particulars (As At 27 Aug 2022 / 01:50:00)

Vehicle Insurance Details



Vehicle No.:

SHC2542D

Make Description/Model:

TOYOTA / PRIUS 5DR HATCHBACK (AUTO)

Insurance Company Name:

AXA INSURANCE PTE LTD

Business Transaction Reference No.:

20220830091713739137

Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).

Save as PDF

OK →

Print



You have successfully logged out.

Your last login date and time was 30 Aug 2022, 09:15:09.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No [ⓘ]	Asset Type [ⓘ]	Asset ID [ⓘ]	Transaction Type [ⓘ]	Transaction Amount(S\$) [ⓘ]	Log Date/Time [ⓘ]
1	Vehicle	SHC2542D	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	30 Aug 2022 /
2	Vehicle	XE4588J	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	30 Aug 2022 /

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 30/08/2022 15:07 (SGT)
Reported by Driver
Date of Accident 27/08/2022 01:50 (SGT)
Exact Location of Accident Yishun Ave 3, Singapore
Additional Location Information -
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number XE1395T

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner SG SAGAWA AMERIOD PTE. LTD.
Company Reg No 1XXXXX423D
Email Address SGSA-claim@sgh-global.com
Mobile Phone No (Phone) +65-66029932
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Mitsubishi
Model Fp51jdr4rdea
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Commercial vehicle
Transmission Manual
CC 11967

INSURANCE COMPANY

Name of Insurance Company MSIG Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number J400001447MKF

DRIVER

Name of Driver OH POH HIN
NRIC No SXXXX314F
Date Of Birth 14/06/1954
Occupation Outdoor

Date Of Driving Pass	09/04/1984
Driving experience	38 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-83323559
Alt. Phone Number	-
Email Address	SGSA-claim@sgh-global.com
Address	BLK 134 YISHUN ST 11 #05-171
Address complement	-
Postcode	760134
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT T/20220828/7000

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC2542D
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	LIM SU TONG
NRIC No	SXXXX165Z
Contact Number	(Phone) +65-97524155
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the LKA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data, personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police statement

DECLARATION

I hereby declare that the information provided is true and correct.



Driver's signature
(If driver is not the policyholder)
Date & Time

29/8/2022
1305

- ☐ Claim own policy
- ☒ Claim third party
- ☐ Claim other workshop
- ☐ For record purposes

Policy No.


*Insurer

Ref No.

3400001447 MKF
MSIG XE1395T


1/C
[Signature]


Reporting Centre Personnel's Signature
Name
NAIC/PIA No.























**SINGAPORE
POLICE FORCE**



T/20220828/7000

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 4

Report No. T/20220828/7000

CONTINUATION OF REPORT

We then went to the road side ,at that moment a police vehicle who was also travelling on the same road saw us and came to ask us what happen. They then took our particular but they did not gave us any case card.

The taxi driver then informed that he might be sleepy .Both myself and the taxi driver agree to settle through insurance.



SINGAPORE POLICE FORCE



T/20220828/7000

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 4

Report No. T/20220828/7000

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/08/2022 00:38		Vide Report No.:	Station Diary No.:
Informant's Particulars			
Name of Informant: OH POH HIN		Address: 134 YISHUN STREET 11 #05-171 SINGAPORE 760134	
ID Type / ID No.: NRIC NO / S0172314F		Contact No.:	
Nationality: SINGAPORE CITIZEN		Home/Office:	Mobile: 82275929
Sex: Male Age: 68 Date of Birth: 14/06/1954		Email: pohhin1954@gmail.com	
Race: Chinese		Type of Informant: Driver	Institution / School Name:
Occupation: driver		Driving Licence Information: Class: 3,4,5	Date of Expiry:

General Information of the Accident				
Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 27/08/2022 01:50	Type of Location: cross junction
Location: yishun ave 2 > yishun ave 3				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of
SHC2542D	Car	TOYOTA	PIRUS	Blue	Seriously Damaged	1
XE1395T	Lorry	MITSUBISHI	Hero 5	Blue	Seriously Damaged	0



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20220828/7000

2 of 4

Report No. T/20220828/7000

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Passenger			
Name	Unknown Passenger	ID No.	NIL
Related Vehicle	SHC2542D (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL
Driver			
Name	OH POH HIN	ID No.	S0172314F
Related Vehicle	XE1395T (Lorry)	Contact No.	82275929
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: 3,4,5 Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL
Driver			
Name	LIM SU TONG	ID No.	S2184165Z
Related Vehicle	NIL	Contact No.	97524655
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL

Brief Details.

On 27/08/2022 at around 0150hrs, i was travelling on my lorry bearing plate number XE1395T. As i approach the cross junction between yishun ave 2 and yishun ave 3. While i was stationary waiting for the traffic light, a taxi bearing Plate number SHC2542D hit onto my rear. Initially i only hear a lot bang at my rear, i then went down to see. The taxi driver did not sustain any injury but i am unsure if there is any injury for the passenger in his car. The taxi sustain a serious damage in his front and my lorry also sustain serious damage at the rear.

**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20220828/7000

4 of 4

Report No. T/20220828/7000

CONTINUATION OF REPORTSketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TP1B /
VILTON HIA WEE SIANG
Contact No.: 65476232

This report is lodged at Yishun North NPC Kiosk 1
NP168

Signature Of Informant:

The identity of the person making this report has
been authenticated by Singpass. No signature is
required.

Date/Time:
28/08/2022 00:38

Classification Of Case:

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

INVOICE

To: SG Sagawa Ameroid Pte Ltd
15 Pioneer Walk
#02-01 Pioneer Hub
Singapore 627753

Date : 19/10/2022

Invoice No : IV22-10012/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of: Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle XE 1395T (Inclusive Of Photographs And Transport Charges) Our reference : CAS/22-10/012	\$758.00
Total	\$758.00

E. & O.E

Constant Appraiser Services



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: SG Sagawa Ameroid Pte Ltd
15 Pioneer Walk
#02-01 Pioneer Hub
Singapore 627753

Date : 19/10/2022

Reference No : CAS/22-10/012

General Information

Registration No. : XE 1395T
Accident Date : 27/08/2022

Particulars of Damaged Vehicle

Colour	: Blue	Make & Model	: Mitsubishi Fuso FP51SDR3VDEA
Engine Capacity	: 11967 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 471447	Engine No.	: OM457310137
Chassis No.	: FP51SDA20003	Steering	: In Order
Registration Date	: 01/02/2016	Brake	: In Order

Tyre Condition

	Size	Make	Balance
R/H Front Tyre	295/80R22.5	ROVELO	70%
L/H Front Tyre	295/80R22.5	ROVELO	70%
R/H Rear Tyre	295/80R22.5 (D)	KPATOS	80% / 80%
L/H Rear Tyre	295/80R22.5 (D)	KPATOS	80% / 80%

Inspection

Repairer : LYS Engineering
65 Chestnut Avenue, #18-15, Singapore 679524

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate	: \$12,076.74
Revised Amount	: \$9,100.00
Less Excess	: -
Nett Total	: \$9,100.00

Remarks

- (A) Survey was done on 07/09/2022
(B) Re-survey was done on 08/09/2022
(C) Re-survey after repair was done on 09/09/2022
(D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
(E) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>			
1	2pcs	Rear brake chamber pump air hose RH @ \$287.33	Bent/Cut	574.66	574.66 ✓
2	2pcs	Rear brake chamber pump air hose LH @ \$287.33	Bent/Cut	574.66	574.66 ✓
3	3pcs	Rear axle brake tube air hose @ \$320.64	Bent/Twisted	961.92	961.92 ✓
4	4pcs	Rear clutch air line joint center @ \$43.69	Necessary	174.76	174.76 ✓
5	1pc	Rear center clutch air line joint bracket (big)	Bent	834.70	834.70 ✓
6	2pcs	Rear number plate lamp @ \$76.40	Broken	152.80	152.80 ✓
7	1pc	Rear number plate	Dented/Bent	40.00	40.00 ✓
8	1pc	Rear number plate bracket	Bent	85.00	85.00 ✓
9	1pc	Rear plug screw	Necessary	80.00	80.00 40 ✓
10	1pc	Rear cylinder pump brake chamber assy RH	Dented/Air leaked	1,483.61	1,483.61 X nn
11	1pc	Rear cylinder pump brake chamber assy LH	Dented/Air leaked	1,483.61	1,483.61 X nn
12	1pc	Rear load sensing valve rod	Bent	53.18	53.18 X nn
13	1pc	Rear center brake air tank	Dented/Air leaked	1,358.44	1,358.44 ✓
14	1pc	Rear load sensing valve damper	Bent	1,580.42	1,580.42 X nn
15	2pcs	Rear connector @ \$75.39	Necessary	150.78	150.78 ✓
16	1pc	Rear wheel cowling RH	Torn	456.20	456.20 ✓
17	1pc	Rear wheel cowling bracket RH	Twisted	115.00	115.00 ✓
18	1pc	Rear wheel mud flap RH	Broken	72.00	72.00 ✓
19	1pc	Rear wheel mud flap bracket RH	Twisted	45.00	45.00 ✓
			Sub total	10,276.74	10,276.74
		<u>LABOUR & MISC. CHARGES</u>			
1		To spray painting on the affected area		800.00	500.00 400
2		Labour charges to repair & replace above damaged parts		1,000.00	600.00 500
			Grand total	12,076.74	11,376.74
Recommended cost of lump sum repair (To its pre-accident condition)					9,100.00

3 days

Constant Appraiser Services

Vehicle No : XE 1395T

Our ref : CAS/22-10/012

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$9,100.00** on a contractual basis. Under normal circumstances, the repair period would be about **3 (Three)** working days.

Yours faithfully,

Constant Appraiser Services



Lim Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA

INVOICE

65 Chestnut Ave #18-15, Singapore 679524
Tel: 6674 8965 Fax: 6674 8965 Hp: 9730 8695
Email: lys88@yahoo.com.sg

Specialise in Motor Repairing, Welding, Panel Beating, Spray Painting, Side Guide, Accident Claims, General Insurance Agents, ROV Inspection, Insurance Claim.

[illegible]

Invoices not paid within 30 days of date, interest at the rate of 1.5% interest per month will be carry out until settled.
All cheques should be crossed & made payable to "LYS ENGINEERING".

LYS ENGINEERING

For **LYS ENGINEERING**



MSIG

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
Co.Reg No. 200412212G, GST Reg. No. 20-0412212G
A Member of  INSURANCE GROUP

CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA), ROAD TRANSPORT (AMENDMENT) ACT 2019 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 169 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1995 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

COMMERCIAL VEHICLE Comprehensive

Certificate No. J 400001447 MKF

Excess : SGD2,000

Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle

XE1395T

2. Name of Policyholder

SG Sagaya Ameroid Pte Ltd

3. Effective Date of the Commencement of Insurance for the purposes of the Act

01/04/2022

4. Date of Expiry of Insurance

31/03/2023

5. Persons or Classes of Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

*Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

6. Limitations as to Use *

Use in connection with the Policyholder's business. Whilst the Motor Vehicle is being so used the carriage of passengers is permitted. The Policy does not cover

(1) Use for racing pace-making reliability trial or speed-testing.

(2) Use for the carriage of passengers for hire or reward.

(3) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 3 of the Motor Vehicles (Third-Party Risk and Compensation) Act (Chapter 169) and Chapter 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 169).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 169) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.

Approved Insurers

Mack Eng
Chief Executive Officer

SGSGFCYZ202204131455

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company Card No.	199100423D
Owner ID Type	Company
Owner Name	SG SAGAWA AMERCO PTE. LTD
Registered Address	15 PIONEER WALK #02-01 PIONEER HUB SINGAPORE 627753
Mailing Address	
Birth Date	

Vehicle Particulars

Vehicle No.	XE 13951
Previous Vehicle No.	-
Effective Date of Ownership	01 Feb 2016
Original Regn Date	01 Feb 2016
Registration Date	01 Feb 2016
Year of Manufacture	2015
Vehicle Type	Goods (Open) Panel Motor
Vehicle Scheme	
Vehicle Attachment 1	No Attachment
Vehicle Attachment 2	
Vehicle Attachment 3	-
Vehicle Make	MITSUBISHI
Vehicle Model	FUSO FP51SDR3V8LA
Primary Colour	White
Secondary Colour	
Passenger Capacity	2
Chassis No.	FP51SDA20003
Engine No.	GM457310137
Engine Capacity/Power Rating	11507 cc
Maximum Power Output	
Propellant	Diesel
Max Unladen Weight	7200 kg
Maximum Laden Weight	95000 kg
Current Market Value	\$78,992.00
PARR Eligibility	No
PARR Eligibility Expiry Date	-
Maximum PARR Benefit	-
No. of Transfers	0
ID Label No.	2010511978
COE No.	2016010105000263R
COE Expiry Date	31 Jan 2026
COE Category	C - Goods Vehicle & Bus
COE Registration	

https://vrl.lta.gov.sg/ita-vrl-action/searchVehicleByOwner?FUNCTION_ID=F1801091... 07-Oct-16

Vehicle Registration Detail Information

Page 2 of 2

Category	C - Goods Vehicle & Bus
Quota Premium (QP) / Prevailing Quota Premium	\$46,001.00
Actual QP Paid	\$46,001.00
QP (Regn Can)	\$46,001.00
QP Cash Rebate Eligibility	No
QP during COE Bidding Exercise	\$46,001.00
Additional Registration Fee Rate	\$ 00
Actual ARF Paid	\$3,950.00
Vehicle Lifespan Expiry Date	31 Jan 2036
CO2 Emission	-
Message	To renew the COE, the Prevailing Quota Premium payable is that of Category C