

ASIS REC BY: Taujau

REF: CS3/AIS226/2491/Tag3

ASSIGNMENT

OPC

2029 Apr 7

From: _____ Date: _____

Estimated cost: _____

OD / PP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: Q47K.

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS Wl' PRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SSR4561H Yr Regn: 2009 June

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mitsubishi Lancer C.C. 1584

Colour: Silver A/C: Insured / Std / Nil / NA

Sp. Reading: 148082 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: July STCS3A9 400568

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 195/60K15
R: 20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____ D.O.I. 14/12/22 0130pm

Survey held at Precise Auto.

Des. of Damages: Frt Repr / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

Repair Range: \$5000 - \$6000 7 days

19/12/22 submit PRS / repair range :\$5k-6k and 7 days

Date/Time, File Pass to?

☐ : Prel. Report

1) 19/12/22

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. invs (\$ _____)

☐ : Weekend (\$ _____)

S + RS \$ _____

Photos _____

Others _____

Repair Form: prs

Lum. Sum: 1584