ASS. REC. BY: Kenneth

REF: CTZ / 22012506 / KV

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Aabe

of 5035 01-385

Insured: 6791

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 884k

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4-5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLA 3910G Yr Regn: 02, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or (A)

Make: Mc C180 c.c 1595

Colour M. Red A/C: Insured / Std / NI / NA

Sp.Reading 124672 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD 2050402R 143390

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : NII / S/Rim / STD A/Rim or _____

Tyre Size: F: 225/60R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front		Rear	
R/Bal.	3 mm	R/Bal.	6 mm
L/Bal.	3 mm	L/Bal.	6 mm
D.O.A.	8/12/22	D.O.I.	14/12/2022

Survey held at _____

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
/	PRS
	Eh repair cost 86-7k

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Prell. Report

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ Tech Invs ($)

☐ Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:

Transportation: $ + RS. SI

Others

TOTAL