

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD INV No. AC2303604

300 BEACH ROAD INV Date 07/06/2023

#17-04/07 THE CONCOURSE Reference CC4/LPC22012533/Kpa3q2

SINGAPORE 199555 Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMV 2470T

Insured Veh. GBH 7105U

Claim No. 22/22/VC05/026711

Policy No. Z22VC05010179

Accident Date 05/12/2022

Inspection Date 15/12/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile								
	LONPAC INSURAN	ICE BHD		Ref:	CC4/LPC22012533/Kpa3q2			
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555		Date:	07/06/2023			
				Code:	LPC2			
1.		Policy Particulars :	- THIRD PARTY	CLAIM				
	Insured Veh.	GBH 7105U	Veh. Inspected	l	SMV 2470T			
	Policy No.	Z22VC05010179	Coverage (\$)		0.00			
	Claim No.	22/22/VC05/026711	Excess (\$)		0.00			
	Assign From	GERALD	Assign Date		15/12/2022			
2.		Vehicle Partic	ulars & Conditi	on				
	Make & Model	TOYOTA NOAH (A)	c.c		1797			
	Engine No.	HIDDEN	Year of Reg.		2020			
	Chassis No.	ZWR800430135	Colour		METALLIC SILVER			
	Odometer	140977 KM	Steering		IN ORDER			
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM			
	General	GOOD						
3.		Condition	ons of Tyres					
		Size	Make		Balance			
	R/H Front Tyre	195/65 R15	DAVANTI		9 mm			
	L/H Front Tyre	195/65 R15	DAVANTI		9 mm			
	R/H Rear Tyre	195/65 R15	DAVANTI		9 mm			
	L/H Rear Tyre	195/65 R15	DAVANTI		9 mm			
4.		<u> </u>	on of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S DOOR MIRROR.							
	DAMAGES SEE DETAILS.							
5.		General	Information					
	Accident Date	05/12/2022	Inspection Dat	е	15/12/2022			
	Survey held at	KUM CHEW MOTOR WORKSHO	OP .					
		160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722						
5a.		Re	emarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.							
5b.	Estimate Days of Repair							
	ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days							



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMV 2470T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SIDE MIRROR -RH	CRACKED	721.40	721.40
1	SIDE MIRROR COVER -R/H	MISSING	109.77	109.77
	LESS 25% DISCOUNT		-207.79	-207.79
			623.38	623.38
	<u>LABOUR</u>			
	TO DISMANTLE & CHARGE THE ABOVE PART.		150.00	60.00
	TO SPRAY PAINT ON SIDE MIRROR.		180.00	60.00
	TO CHECK WIRING FUNCTIONS.		80.00	20.00
			410.00	140.00
	GRAND TOTAL		1,033.38	763.38

Report Ref No. CC4/LPC22012533/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R


PHOTOGRAPHS FOR VEHICLE NO. SMV 2470T

INSPECTION
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMV 2470T

RE-INSPECTION







