

Our Job Ref No : 305539562
Date 19.12.22

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :


Attn : Mr NAZ

Vehicle Reg No. SHA 953A

Date of Accident : 13.12.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill 703A TOKIO --- SLN7559T
- The finalized amount shall be:
 - Spare Parts after List discount
 - Labour Charges
 - Total for Part-By-Part Repair Cost
 - Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$1,000.00
Final Lumpsum Repair cost
- Estimated normal period for repairs: 2 working days.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
- Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 
Name : JUMANI
Tel : 62148315
Fax : 65468156

Signature : 
Name : NAZ
Date : 6/1/2023

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	----	NO		
3. Survey Fees	----	---		
LTA Search Fee	\$7.49 / \$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 19.12.2022
Time: 14:03:01
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305539562
REGN NO : SHA 953A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 17.08.2018
DATE/TIME IN : 13.12.2022 13:10
ACCIDENT DATE : 13.12.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	COVER-RR BUMPER#	1	0.00	0.00	0.00
0002 28-01-0104-2029-A	VEHICLE NUMBER PLATE REAR	1	0.00	0.00	0.00
0003 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	0.00	0.00	0.00

SUB-TOTAL : 0.00

JOB NATURE

0000 L	LUMPSUM (SHA953A)TP	1000.00
--------	---------------------	---------

SUB-TOTAL : 1,000.00

TOTAL : 1,000.00

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CCPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	13/12/2022
Vehicle Reg. No.:	SHA953A	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	17/08/2018
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	G4LEJU076598	Chassis No:	KMHC851CVKU106590
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,473.16
Miscellaneous Items	11.00
Labour	750.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,234.16
+ GST 7.00% (S\$)	156.39
Nett Amount (S\$)	2,390.55

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 13 Dec 2022)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA953A/13/12/2022 15:50**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER ASSY	CRA ✓ 20.00	0.00	*459.40 FL
2	1		*REAR BUMPER BEAM	SVC X? 20.00	0.00	*394.80 FL
3	10		*REAR BUMPER CLIPS	NN X 20.00	0.00	*22.00 FL
4	1		*REAR BUMPER UNDER COVER	SVC X? 20.00	0.00	*451.25 FL
5	1		*REAR NUMBER PLATE	CRA ✓ 0.00	0.00	30 *50.00 F 50
6	1		*REAR FOG LAMP	SVC X? 20.00	0.00	*201.50 FL
7	1		*ADVERTISEMENT LOGO - FENDER	NEL ✓ 0.00	0.00	*200.00 F
Sub Total (\$\$)						1,778.95
- List Item Discount on L Items (\$\$)						305.79
Total Parts (\$\$)						1,473.16

F=Franchise part, L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHA953A/13/12/2022 15:50. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	350 400.00
2	SPRAYPAINT	New	250 300.00
3	REMOFE/REFIX REVERSE SENSOR	New	30 50.00
Gross Labour Cost (S\$)			750.00

ComfortDelGro Engineering Pte Ltd/SHA953A/13/12/2022 15:50. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

N/A2 LKK

13/12/2022 1630

L/S

2 DAYS

CHECK ITEM PHOTO

AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: