

(96/17)

ASS. REC. BY: NAZ

REF:

INC

LOKE LIS

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 2651Y Yr Regn: 19 JUL 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) Prime Mover /

Truck / Trailer or _____

Make: HYUNDAI IONIQ G2 c.c. 1,580

Colour: BLUE A/C: (Insured) Std / NI / NA

Sp. Reading: 707,685 T/Radio: (Insured) Std / NI / NA

Eng/No: _____

C/No: KMHC851CV Jul 03691

Gen. Cond: Good / Fair / Poor / Burnt

Steering: (Inorder) / Jammed / Leaked / Burnt or _____

Brake: (Inorder) / Jammed / Leaked / Burnt or _____

Modl: NII / S/Rim / (STD) A/Rim or _____

Tyre Size: F: 195/65R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WESTLAKE

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 22/7/2022 D.O.I. 14/12/2022

Survey held at CDGE LOYANG

Des. of Damages: Frt / (Rear) O/S / N/S / U/C / Rooftop or

O/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

INC LIS

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: _____

1) _____
Date/Time, File Return to?

: Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: : Site Insp (\$ _____) S + RS SI

: Interview (\$ _____) Photos

: Tech. Invs (\$ _____) Others

: Weekend (\$ _____)

Report Format : _____
Lump Sum / I.B.I: (\$ _____)

Survey Fee:	
Transportation:	
Photos	
Others	
TOTAL	