

(96/11/11)

ASS. REC. BY:

NA2

REF:

NS/INC22012551/Nnp3

INC

LOKE LIS

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. MT/1204379-001

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of Inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHC 2651Y Yr Regn: 19 JUL 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HYUNDAI IONIQ G2 c.c. 1,580Colour BLUE A/C: Insured / Std / NI / NASp. Reading 707,685 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHC851KVJUL03691

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WESTLAKE

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 22/7/2022 D.O.I. 14/12/2022Survey held at CDGE LOYANGDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orO/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

INC LIS

Nazz confirmed lump sum: \$1350 and 3 days
(red, \$1739.12, 56%)

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: 3

1) 09/01/23

☐

Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format : TPLump Sum / I.B.I: (\$ 1350)