

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD			Ref:	NS/INC22012552/Nnp3e2		
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	12-01-2023 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SMJ 4076Z	Veh. Ir	nspected	SHA 9346T	
	Policy No.		Covera	age (\$)	0.00	
	Claim No.	MT/1203973-002	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	14/12/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI I40	c.c		1685	
	Engine No.	HIDDEN	Year o	f Reg.	2016	
	Chassis No.	KMHLB41UMGU092601	Coloui	r	YELLOW	
	Odometer	459021	Steerii	าg	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	WEST	LAKE	5 mm	
	L/H Front Tyre	205/60 R16	WEST I	LAKE	5 mm	
	R/H Rear Tyre	205/60 R16	WEST	LAKE	4 mm	
	L/H Rear Tyre	205/60 R16	WEST	LAKE	4 mm	
4.						
	THE VEHICLE SU	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE D	DAMAGES SEE DETAILS.				
5.	General Information					
	Accident Date	13/12/2022	Inspec	tion Date	14/12/2022	
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.		Remarks				
	A)THE INSPECTION B)IN ACCORDANCE	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					