

PRESTIGE APPRAISER SERVICES

Insurance Loss Adjusters and Licensed Appraisers Regn.52868584L
Blk 131 Rivervale Street #05-872 S'pore 540131Tel:96824663
E-mail: prestigeappraiserservices@yahoo.com.sg

No. 23752

INVOICE

Customer

To Mr Muhammad Hidhir Bin Mohamed Nastron
c/o Blk 1016 Yishun Industrial Park A
#01-218
Singapore 768758

Date 31-Aug-22
Our ref PS/030/08/22
Your Ref

VEHICLE REGISTRATION NO : FBR 2342 G

VEHICLE MAKE/MODEL : Yamaha FZS

INSPECTION REPORT FEES
(inclusive of photographs & transport charges)

\$450.00

DOLLARS: Four Hundred And Fifty Only

○
E. & O. E.

for PRESTIGE APPRAISER SERVICES



PRESTIGE APPRAISER SERVICES

Insurance Loss Adjusters and Licensed Appraiser Regn. 652868584L

Blk 131 Rivervale Street #05-872 S'pore 540131 Tel:96824663

E-mail: prestigeappraiserservices@yahoo.com.sg

Our ref : PS/030/08/22

Date : 31st August 2022

Mr Muhammad Hidhir Bin Mohamed Nastron

c/o Blk 1016 Yishun Industrial Park A

#01-218

Singapore 768758

Dear Sir,

Re : THIRD PARTY CLAIM

We refer to your instruction to appraise the vehicle **FBR 2342 G** on 24th August 2022.

A static inspection was conducted during our survey and our report is enclosed for your perusal. The estimated repair cost submitted by **Messrs. Brother Motors** for **\$8,890.00** as per our attached schedule have been inspected thoroughly each and every item and revised by us against the actual damages found on the vehicle which have been recommended by us accordingly.

The repairer has agreed to undertake repairs at our revised amount of **\$5,000.00 lump sum** corresponding to supply of parts, labour charges and spray-painting. However, we have not given instruction to authorize the repairs.

Under normal circumstances, the estimated period of repairs would be **THREE (3) days**. Photographs of the damaged vehicle taken by us during our inspection are enclosed.

We are reverting the matter to you for a decision.

Please do not hesitate to contact us if you need any clarification.

Assuring you of our best services.

Yours faithfully,

PRESTIGE APPRAISER SERVICES



LOUIS S C NG CAE AMIMI

Dip. MTM. Automotive Engineer

Licensed Appraiser

Encl.

PRESTIGE APPRAISER SERVICES

VEHICLE INSPECTION REPORT

To: Mr Muhammad Hidhir Bin Mohamed Nastron
c/o Blk 1016 Yishun Industrial Park A
#01-218
Singapore 768758

Date : 31st August 2022
Our Ref : PS/030/08/22
Policy No :
Sum Insured :
Excess : T/P Claim

Assigned By : Mr Muhammad Hidhir Bin Mohamed Nastron
Assignment Date : 24th August 2022
Accident Date : 17th August 2022
Inspection Date : 24th August 2022
Workshop Name : Brother Motors
Survey Conducted At : Blk 1016 Yishun Industrial Park A
#01-218
Singapore 768758

PARTICULARS OF VEHICLE

Registration No	: FBR 2342 G	Mileage	: 26904km
Make/Model	: Yamaha FZS	Engine No	: HIDDEN
Type Of Body	: Motorcycle	Chassis No	: ME1RG44B8K0052959
Year Of Manu./Regn.	: 2019/2020	Passenger Cap.	: 1 Passenger
Colour	: Blue	Others	: -

CONDITION OF TYRES

Front Tyre : 5mm 110/70-17 Pirelli
Rear Tyre : 5mm 130/70-17 Pirelli

The above represent the estimated remaining life of the tyre treads.

PRE-ACCIDENT CONDITION (Static tests only)

Handbrake	: Serviceable	Body Work	: Good
Footbrake	: Serviceable	Paint Work	: Good
Steering	: Serviceable	Others	: -

POINT OF IMPACT

The vehicle sustained an impact on the front, L/H & R/H portion.

GENERAL DESCRIPTION OF DAMAGES

The front fork, handle bar, exhaust muffler, main body frame were dented.

For details of damages please refer to schedule attached.

REMARKS :

This survey was conducted strictly without prejudice.

PRESTIGE APPRAISER SERVICES

Vehicle No : FBR 2342 G

Our Ref : PS/030/08/22

Qty	Descriptions	Conditions	Repairer's Est.	Our Revised.
<u>LIST ITEMS</u>				
2	front fork	dented/bent	\$ 580.00	\$ 580.00
1	under bracket	dented	102.00	102.00
1	steering cone w/bearing	cracked	186.00	186.00
1	front mudguard	sliced	185.00	185.00
1	front wheel rim	dented/warped	585.00	585.00
1	front wheel screw	bent	25.00	25.00
1	headlamp	serviceable	325.00	-
1	headlamp cowling	sliced	168.00	168.00
1	handle bar	dented/bent	195.00	195.00
2	handle grip	necessary	84.00	84.00
2	handle balancer	sliced	76.00	76.00
1	L/H front signal lamp	sliced	85.00	85.00
1	brake lever	sliced	85.00	85.00
1	clutch lever	fractured	85.00	85.00
2	mirror	sliced	136.00	136.00
1	speedometer	dented/sliced	592.00	592.00
1	fuel tank	dented - repair	689.00	-
1	L/H fuel tank side cover	sliced	132.00	132.00
1	L/H fuel tank lower cover	sliced	95.00	95.00
1	R/H fuel tank side cover	sliced	132.00	132.00
1	R/H fuel tank lower cover	cracked	95.00	95.00
1	R/H front foot rest	sliced	72.00	72.00
1	R/H rear foot rest	sliced	72.00	72.00
1	L/H front foot rest	sliced	72.00	72.00
1	L/H rear foot rest	sliced	72.00	72.00
1	gear pedal	bent	82.00	82.00
1	exhaust muffler	dented/bent	580.00	580.00
1	exhaust muffler cover	sliced	95.00	95.00
1	rear wheel rim	serviceable	580.00	-
1	cushion seat	cut	320.00	320.00
			<u>6,582.00</u>	<u>4,988.00</u>
		Less 10%	-	498.80
			\$ <u>6,582.00</u>	\$ <u>4,489.20</u>
<u>S/NETT ITEMS</u>				
1	front number plate	dented	28.00	22.00
1	front tyre	wall cut	250.00	150.00
1	rear box	sliced	250.00	180.00
1	rear box bracket	dented/bent	200.00	160.00
1	IU unit	sliced	160.00	156.00
<u>Labour Charges & Misc</u>				
	To dismantle & replace damaged parts, panel beat where necessary.		650.00	520.00
	To putty, apply primer & spray-paint on the affected portion.		400.00	300.00
	To align main body frame.		300.00	220.00
	Transportation charges.		70.00	50.00
			\$ <u><u>8,890.00</u></u>	\$ <u><u>6,247.20</u></u>

PRESTIGE APPRAISER SERVICES

Vehicle No : FBR 2342 G

Our Ref : PS/030/08/22

Qty	Descriptions	Conditions	Repairer's Est.	Our Revised.
-----	--------------	------------	-----------------	--------------

Note: The repairer has agreed to undertake the repairs at our adjusted amount of **\$5,000.00 lump sum** corresponding to supply of parts, labour and spray-painting charges.

Under normal circumstances, the estimated repair period would be **THREE (3)** days.
Pursuant to your instruction we have **not** authorised repairs on your behalf.

PRESTIGE APPRAISER SERVICES



LOUIS S C NG CAE AMIMI (UK)
Licensed Appraiser
Dip. MTM. Automotive Engineer



































