

000177

ASS. REC. BY:

REF:

NS/INC22012579/Sqp3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3 days

Res: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SH7567T

Yr Regn: 17 Jul 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

hyundai

C.C. 180

Colour

Blue

A/C: Insured / S / NI / NA

Sp. Reading

274705

T/Radio: Insured / S / NI / NA

Eng/No:

C/No:

Kmh 1851 CVKV 164679

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / Rim: or

Tyre Size:

F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

webHake

Front

Rear

R/Bal. 6 mm

R/Bal. 5 mm

L/Bal. 6 mm

L/Bal. 5 mm

D.O.A. 1/12/22

D.O.I. 2/12/22 pm

Survey held at

comfort

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

L/S

IRFAN finalised LS \$1600, 3 days. (Red \$1141.52, 42%)

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format :

TP

Lump Sum (\$ 1600)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	821R

Vehicle Details

Vehicle No.:	SH7567T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	08 Dec 2022
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV 1.6 DCT
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	G4LEKU297737
Chassis No.:	KMHCH851CVKU164679
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$25,367.00
Original Registration Date:	17 Jul 2019
First Registration Date:	17 Jul 2019
Transfer Count:	0
Actual ARF Paid:	\$12,514.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Jul 2027
PARF Rebate Amount:	\$9,385.00

Intended COE Rebate Details

COE Expiry Date:	16 Jul 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$24,410.00
COE Rebate Amount:	\$14,050.00
Total Rebate Amount:	\$23,435.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 08 Dec 2022

OK

Date/Time: 01.12.2022 15:15

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5367979

JC NO: 305538420

CUSTOMER
NAME: COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO: 7010045
ADDRESS: 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)
COUNT CARD NO.

REGN NO.: SH 7567T	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL: IONIQ(G2)	DATE/TIME IN 01.12.2022 13:35
YR OF MANU. 17.07.2019	TARGET DATE
CHASSIS CODE: KMHC851CVKU164679	COMPLETION DATE/TIME:

Accident Date: 01.12.2022
NATURE: 3P 01.12.2022


JOB DESCRIPTION

/NO

LABOR CODE

DESCRIPTION

FRONT



BOOKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.: SH 7567T YY

Vehicle No.: SH 7567T

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard