

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 02.12.2022

Time: 10:12:00

Page: 1

Income (Hsum)

Jn

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305538423
 REGN NO : SHC2059H
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 13.12.2017
 DATE/TIME IN : 02.12.2022 08:30
 ACCIDENT DATE : 01.12.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-2322-A	BUMPER FRT COVER+	1	1,052.20	20.00	841.76	cut
0002	04-01-0103-0640-G	BRACKET-FR BUMPER SIDE RH	1	44.80	20.00	35.84	? nn
0003	04-01-0101-0111-G	BUMPER COVER CLIP	10 L	22.00	20.00	17.60	NEC
0004	04-01-0103-0782-A	LAMP ASSY-HEAD RH#	1	1,388.00	20.00	1,110.40	? nn
0005	04-01-0103-0573-A	PANEL-FENDER RH+	1	663.00	20.00	530.40	BUC
0006	04-01-0103-2934-A	GUARD ASSY-FRONT WHEEL RH	1	174.90	20.00	139.92	Br
0007	28-01-0103-0003-A	FRT DOOR LOGO CTPL	1 N	75.00	10.00	67.50	NEC/cut
0008	04-01-0103-0658-G	CAP ASSY-WHEEL HUB	1	217.20	10.00	195.48	cut

SUB-TOTAL : 2,938.90

JOB NATURE

0000	PB	PANEL BEATING	600.00	560
0001	SP	SPRAYPAINT CHARGE	600.00	750
0002	17-01	CHECK ALL LIGHTING	50.00	30

$\frac{23132}{20\%} = 626$
 $\frac{2506}{20\%} = 2506$
 $\frac{2506}{20\%} = 2506$
 $\frac{2506}{20\%} = 2506$

$\frac{3332}{666.40} = 2666$
 $\frac{3332}{666.40} = 2666$
 $\frac{3332}{666.40} = 2666$
 $\frac{3332}{666.40} = 2666$

1 rfm 2/12/22
 440pm 3 days
 L/S
 [Signature]

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305538423
REGN NO : SHC2059H
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 13.12.2017
DATE/TIME IN : 02.12.2022 08:3
ACCIDENT DATE : 01.12.2022

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0003	20-00 TUFF COAT ON AFFECTED PARTS.	50.00	X	NN		
0004	20-05 ADVERTISEMENT STICKER-DOOR	100.00	/	NEL		
0005	20-05 ADVERTISEMENT STICKER-FENDER	100.00	/	NEL		
SUB-TOTAL						: 1,500.00
TOTAL						: 4,438.90

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Total = 3332
20% = 666

FT = 2666

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

= 2650