

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD			Ref:	NS/INC22012582/Snp3m4		
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	17-01-2023 INC4		
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHC 6964T	Veh. Ir	spected	SHD 6811X	
	Policy No.		Covera	age (\$)	0.00	
	Claim No.	MT/1200934-002	Exces	,	0.00	
	Assign From		Assign	n Date	02/12/2022	
2. Vehicle Particulars & Condition						
	Make & Model	MERCEDES BENZ E220	C.C		2143	
	Engine No.	HIDDEN	Year o	f Reg.	2016	
	Chassis No.	WDD2120012B309203	Colou	•	WHITE	
	Odometer	482615	Steerin	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/55 R16	GITI		6 mm	
	L/H Front Tyre	225/55 R16	GITI		6 mm	
	R/H Rear Tyre	225/55 R16	GITI		5 mm	
	L/H Rear Tyre	225/55 R16	GITI		5 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
	DAMAGES SEE DETAILS.					
5. General Information						
	Accident Date	02/12/2022	Inspec	tion Date	02/12/2022	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD					
		59 LOYANG DRIVE SINGAPORE 508969				
5a.						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					