

(98/11/11)

ASS. REC. BY:

REF:

NS/INC22012582/Snp3

EST

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Comfort

of

Insured:

HOC Income

Policy No.

Claims No.

MT/1200934-002

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SH06811X

Yr Regn:

08 APR 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes Benz E220 c.c. 2143

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

482615

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDP21200123309203

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / Rim; or

Tyre Size:

F: 225 / 55 R16

R: 225 / 55 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

giti

Front

Rear

R/Bal.

6

mm

R/Bal.

5

mm

L/Bal.

6

mm

L/Bal.

5

mm

D.O.A.

2/12/22

D.O.I.

2/12/22 430pm

Survey held at

Comfort

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

L/S

L/S = 2250

Irfan confirmed lump sum : \$2250 and 3 days
(red, \$1585.26, 41%)

Date/Time, File Pass to?



Preli. Report

1) 16/01/23



Final Report

Date/Time, File Return to?

2)

Report Format :

TP

Lump Sum / I.B.I.: (\$

2250

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	821R

Vehicle Details

Vehicle No.:	SHD6811X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	08 Dec 2022
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E220 BLUETEC
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	65192433209399
Chassis No.:	WDD2120012B309203
Maximum Power Output:	130.0 kW (174 bhp)
Open Market Value:	\$44,046.00
Original Registration Date:	08 Apr 2016
First Registration Date:	08 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$46,165.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Apr 2024
PARF Rebate Amount:	\$30,007.00

Intended COE Rebate Details

COE Expiry Date:	07 Apr 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$36,862.00
COE Rebate Amount:	\$6,134.00
Total Rebate Amount:	\$36,141.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 08 Dec 2022

OK

Date/Time: 02.12.2022 15:31

Page : 1

Job: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5369074

JC NO: 305538532

Customer

IS COMFORT TRANSPORTATION PTE LTD
Customer NO. 7010045
Address 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)

REGN NO. SHD6811X	MILEAGE
MAKE MERCEDES BENZ	FUEL E.....1/2.....F
MODEL E220CDI (E6)	DATE/TIME IN 02.12.2022 13:10
YR OF MANU. 08.04.2016	TARGET DATE
CHASSIS CODE WDD2120012B309203	COMPLETION DATE/TIME


Amount CARD NO.

Accident Date: 02.12.2022
Accident Time: 3P.02.12.22

JOB DESCRIPTION

Job NO LABOR CODE

DESCRIPTION



Worked & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Payment Slip

Exit Pass

SHD6811X

JU INCOME

Vehicle No.:

SHD6811X

Service Advisor

Signature/Date

Name of Service Advisor

Date

Handed to Service Reception upon collection

To be kept by Security Guard