

COMFORTDELGRO ENGINEERING PTE LTD

Date: 02.12.2022

Time: 15:38:52

REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305538532
 REGN NO : SHD6811X
 MILEAGE : 0000000000
 MAKE : MERCEDES BENZ
 MODEL : E220CDI(E6)
 DATE OF REGN : 08.04.2016
 DATE/TIME IN : 02.12.2022 13:10
 ACCIDENT DATE : 02.12.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0202-2292-G	FRONT BUMPER ASSY	1	1,890.50	20.00	1,512.40	cut ✓
0002 04-01-0202-0574-G	FRT FENDER LH	1	966.08	20.00	772.86	Dent + R

SUB-TOTAL : 2,285.26

JOB NATURE

0000 PB	PANEL BEATING	900.00	800
0001 SP	SPRAYPAINT CHARGE	600.00	500
0002 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	X NN

SUB-TOTAL : 1,550.00

TOTAL : 3,835.26

MYA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

T = 2812.40
 20% = 562.48
 FT = 2249.92
 ≈ 2250

1. Refer 90097659
 2/12/22 430pm
 3 days
 L/S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: