
AS	SSIGNMENT		
stimated Cost:  Do TP/WS/TP RES/OD RES/EVA/INV/MV	Veh No: SMO 9359 A Yr Regn: Dol 9 / MAC  Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  Truck / Trailer or		
o Inspect Vehicle No: Sno 9959 A	Make: MERCEDES ALMZ CLA 180 COUPE C.C 1595		
nsured: SNE 9994E CT\ Policy No. DMPCSNW00031882200	Colour BLUE A/C: Insured / Std / NI / NA Sp.Reading 673/4 T/Radio: Insured / Std / NI / NA Eng/No: C/No: WOUTS 422N 747384		
Claims No. SNM22D208902/C02/TANCHC	Gen. Cond: Good / Fair Poor / Burnt		
Sum Insured: Excess:  (Client's Record)  Make of Veh:	Steering: Inorder Jammed / Leaked / Burnt or  Brake: Inorder / Jammed / Leaked / Burnt or  Modi: Nii / S/Rim / STD A/Rim or  Tyre Size: F: 225/foR &		
(Policy Condition)  Remark: The veh had commenced its repair at the time of inspection.	R: 1.		
Bal. or Market Value:  IDAC Accident Rport:  Consistent?: Yes or No  Consistent?: Yes or No  Est. Repairs:  days  Res.: Yes or No	Front   Rear   R/Bal.   mm   R/Bal.   mm   L/Bal.   mm   L/Bal.   mm   L/Bal.   mm   D.O.I.   30/01/23		
Lum Sum: % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rea / O/S / N/S / U/C / Rooftop or		
Vehicle: IN / O Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.		
Date / Time Action / Instruction  REPAR LIMIT - LOTAL  6/2/23 Final fig \$4080.06 confirmed by email (1)	Red 1566.74, 27%)		
Date/Time, File Pass to? : Prelli. Report	Days Of Repair: 3		
Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee:		
g 6/2/23-typist Add F	Harrison /6		
Report Format: Merimen	: Interview (\$ ) Photos		



## **ESTIMATE FOR SMD9959A**

Cycle & Carriage Industries Pte Limited **Authorised Dealer** Company No. 196400367W GST Reg No. MR-8500111-X

CHINA TAIPING INSURANCE (S) PTE

LTD

ATTN: MOTOR CLAIM DEPARTMENT

3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909

62222366

Vehicle & Document Information

WIP No 61385

Reg No/Reg Date

/ 20/03/2019 SMD9959A

Date In/Mileage

Chassis No

NDD1173422N7473649

**Engine No** 

27091031811995

Make/Model

MB/MB CLA 180

Colour/Trim

028 890 Cavansite B/ 041 151 ARTICO Spor

Account No Terms Date/Time Printed CSE Operator WC000668 Credit 30/11/2022/ 16:20 301 / Kerlyn Ong K0 Amount Description of Goods / Services LKK Auto Consultants hence notify Z REQUEST the Repairer of the following: Customer Request To result before/after spray painting
 To display damaged part(s) during resurvey M BPNSUN // 30/11/2022 POLICY NO/ACC DATE : Parts prices are subject to confirmation DRIVE IN/EXCESS : 30/11/2022 // SNE9994E -. Third party survey is on a "Without Prejudice" basis DATE IN/DATE SURVEY: No illegal modification(s) is allowed BY/AUTHRIZED ON Supplementary item(s) must be resurveyed and is subject to final approval from loadrance Company A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH A BPIRES ledged by Repa RESPRAY REAR BUMPER 0.1 A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL IDENTIFICATION STANDARD. NETT 120.00 A BPILAB LEAKAGE. NETT CHECK REAR LIGHTING SYSTEM AND WATER 1.00 1240.00 00.00 1252.411240.00 REAR BUMPER de 323.69 00.00 358.12 323.69 1.00 REAR BUMPER LOWER TRIM SA 190.21 00.00 CTR/ REAR BUMPER MOULDING 1.00 209.53 190,21 1.00 33.02 00.00 33.02 LH/ REAR BUMPER MOUNTING RALL RH/ REAR BUMPER MOUNTING RAIL 1.00 40.96 00.00 40.96 1.00 132.76 00.00 132.76 CTR/ BASIC MOUNTING FOR BUMPER Kerlyn Ong Kai Li DID: 6771 4420 HP: 9186 5113 Email: kerlyn.ong@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd Customer Service Centre - Pandan Loop

Hy 90010068 3 clays 30/01/23@1110 Rem Sefore print

Confirmed & accepted by

Nett

5,580.64 390.64

5646.80

7% GST on

5580.64

**Total Payable** 

5,971.28

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

## > Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
	062F
Vehicle No.:	SMD9959A
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jan 2023
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	CLA180 COUPE URBAN (R18 LED)
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	27091031811995
Chassis No.:	WDD1173422N747364
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value	\$28,763.00
Original Registration Date: First Registration Date:	20 Mar 2019
Transfer Count:	20 Mar 2019
Actual ARF Paid:	\$32,269,00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Mar 2029
PARF Rebate Amount:	\$24,201.00
COE Expiry Date:	19 Mar 2029
COE Category: COE Period(Years):	A - Car up to 1600cc & 97kW (130bhp)
OP Paid:	10 \$25,556.00
COE Rebate Amount:	\$15,677,00 \$15,677,00
Total Rebate Amount	\$39,878.00
The information contained herein is correct as at 31 Jan 2023	\$37,070,tW

## Mercedes-Benz C-Class C180 Coupe

Price	\$149,888			
Depreciation ⑦	\$20,300 /yr View models with similar depre	Reg Date	27-Mar-2019 (6yrs 1mth 23days COE left)	
Mileage	N.A.	Manufactured ②	2018	
Road Tax 🕖	\$740 /yr	Transmission	Auto	
Dereg Value ⑦	\$60,202 as of today (change)	OMV ②	\$41,388	
COE ⑦	\$36,961	ARF()	\$49,944	
Engine Cap	1,595 cc	Power	115.0 kW (154 bhp)	
Curb Weight 🕖	1,550 kg	No. of Owners 🕖	2	
Type of Vehicle	Sports Car			