



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



### AUTOMOBILE INSPECTION REPORT

INCOME INSURANCE LTD

Ref: NS/INC22012605/Nqp3m4

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

Date: 18-01-2023

Code: INC4

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLX 286Z	Veh. Inspected	SHB 4932D
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1202431-003	Excess (\$)	0.00
Assign From		Assign Date	15/12/2022

#### 2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ G3	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMHC851CVLU178604	Colour	YELLOW
Odometer	372572	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	3 mm
L/H Front Tyre	195/65 R15	WEST LAKE	3 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	4 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	4 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S BODY. DAMAGES SEE DETAILS.
---

#### 5. General Information

Accident Date	14/12/2022	Inspection Date	15/12/2022
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------