

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. MT/1202431-003  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 6 4 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHB 4932D Yr Regn: 24 SEP 2019  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: HYUNDAI IONIQ G3 c.c. 1,580  
 Colour: YELLOW A/C: (Insured) / Std / NI / NA  
 Sp. Reading: 372,572 T/Radio: (Insured) / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: KMH C851CVLU1-78604  
 Gen. Cond: Good / (Fair) / Poor / Burnt  
 Steering: (norder) / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: (norder) / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modl: NII / S/Rim / (STD) / Rim or \_\_\_\_\_  
 Tyre Size: F: 195/65 R15  
 R: 11  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or WESTLAKE  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 3 mm R/Bal. 4 mm  
 L/Bal. 3 mm L/Bal. 4 mm  
 D.O.A. 15/12/2022 D.O.I. 15/12/2022  
 Survey held at CDGE LOYANG  
 Des. of Damages: Frt / Rear / (O/S) / N/S / U/C / Rooftop or \_\_\_\_\_  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Nazz confirmed lump sum: \$9700 and 6 days  
 (red, \$4659.76, 32%)

Date/Time, File Pass to?

1) 17/01/23

Date/Time, File Return to?

2)

Report Format : tp  
 Lump Sum / I.B.I.: (\$ 9700)

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation: \_\_\_\_\_ \$ + RS \_\_\_\_\_ \$

Photos

Others

TOTAL