

Our Job Ref No : 305539733

Date 30.12.22

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr NAZ

Vehicle Reg No. SHB4932D

Date of Accident : 14.12.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill 703A **INCOME** — **SLX286Z**
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% **\$9,800.00**
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 6 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 62148315

Fax : 65468156

Signature : 

Name : NAZ

Date : 11/1/2023

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	NO		
3. Survey Fees	---	---		
LTA Search Fee	\$7.49 / \$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

TOWING FEE - KING DOLLY