

Our Job Ref No : 305539712
Date : 17/12/22

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr Naz


Vehicle Reg No. : SHA8078Z


14.12.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: INCOME -- GBB4352Z
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost** \$0.00
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$2,150.00
Final Lumpsum Repair cost \$2,150.00
3. Estimated normal period for repairs: 3 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : Ms. Loke YY
Tel : 62148355
Fax : 65468156

Signature : 
Name : NAZ LKK
Date : 6/1/2023

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR ESTIMATE

Model : Prius

MVA: MS. LOKE YY

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

AFTER RFP AND PHOTO

Date: