

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
CHEONG YUNHUI, CLARISSA
BATES STEFANIE YOLANDA

Unique Entity Number: 200721148H

Address: 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

TEL : (65) 65342811 (Hunting)
FAX : (65) 65356802 (General) ✓
 : (65) 65355905 (Litigation)
E-mail : yvonnelim@visionlawllc.com
Conveyancing & Family Law Practices
TEL : (65) 63580703
FAX : (65) 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE

Our Ref : DA1-ylv-Ins-D11-118205-22-fg
Your Ref : YQ 222 R

Date : 16 December 2022

LONPAC INSURANCE PTE LTD

300 Beach Road
#17-04/07, The Concourse
Singapore 199555

Attention: Motor Claims Department

**WITHOUT PREJUDICE
BY EMAIL ONLY**

mt_claim@lonpac.com

BAN HENG AQUATIC SUPPLIES PTE LTD

175 Pandan Loop
Singapore 128459

**CERTIFICATE OF POSTING
(For your information only)**

Dear Sirs,

**CLAIMANT : SUMMER TRANSPORTER PTE LTD
ACCIDENT INVOLVING YQ 4760 C & YQ 222 R & GBF 1865 J ON 25-AUG-2022 ALONG AYE
TOWARDS TUAS BEFORE JURONG PORT ROAD AT ABOUT 0910 HOURS**

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on **25-Aug-2022 ALONG AYE TOWARDS TUAS BEFORE JURONG PORT ROAD AT ABOUT 0910 HOURS** involving our client's vehicle registration number **YQ 4760 C** and vehicle registration number **YQ 222 R** driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your/your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

1. Costs of Repair	\$22,150.00
2. Loss of use (8 days x \$350.00 per day)	\$ 2,800.00
3. Pre-repair Loss of use (3 days)	\$ 1,050.00
4. LTA/GIA/TP report/search fees	\$ 41.00
5. Survey report fees	\$ 1,255.00
6. Costs (with GST)	\$ 1,605.00
7. Incidentals (with GST)	\$ 107.00
	<u>\$29,008.00</u>

.../2 to be continued next page

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

Our Ref : DA1-ylv-Ins-D11-118205-22-fg
Your Ref : YQ 222 R

Date : 16 December 2022

LONPAC INSURANCE PTE LTD
Attention: Motor Claims Department

BAN HENG AQUATIC SUPPLIES PTE LTD
Singapore

We enclose a copy of each of the following documents for your consideration:-

- (a) Police/GIA report lodged by driver of YQ 4760 C;
- (b) LTANet Search;
- (c) Certificate of Insurance;
- (d) Registration Card;
- (e) Final Repair Bill;
- (f) Surveyor's report & invoice; and
- (g) **60 scanned color photographs** depicting the damages to motor vehicle YQ 4760 C.

We have notified your insurers of the accident and a pre-repair inspection of our client's vehicle was carried out by your insurers.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim herein is quantified based on supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully



DIANE ANG
Encl.

cc: YQ 4760 C- By email: jeromyng@gmail.com only
{As per your instruction we have submitted your claim as set out above to the third party insurance company. Please do notify us if there is any discrepancy, if any, particularly, the number of days claimed for rental charges and/or loss of use as soon as possible. Thank you.}

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	26/08/2022 11:18 (SGT)
Reported by	Driver
Date of Accident	25/08/2022 09:10 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	AYE TOWARDS TUAS BEFORE JURONG PORT RD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number YQ4760C

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	SUMMER TRANSPORTER PTE LTD
Company Reg No	2XXXXX325z
Email Address	yvonne@summer.com.sg
Mobile Phone No	(Phone) +65-98578208
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Fuso
Variant	FUSO FM65FM6RDEA
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	7545

INSURANCE COMPANY

Name of Insurance Company	Great Eastern General Insurance Limited
Policy Number / Cover Note Number	v0118901-vcv

DRIVER

Name of Driver	JI HUAN
Passport No/FIN	GXXXX979M
Date Of Birth	28/07/1988
Occupation	Outdoor

Date Of Driving Pass	01/02/2016
Driving experience	6 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96288945
Alt. Phone Number	-
Email Address	YVONNE@SUMMER.COM.SG
Address	151 SERANGOON NORTH AVE 2
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

AS PER SKETCH PLAN ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YQ222R
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-

Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GBF1865J
Vehicle Manufacturer -
Vehicle Model -
Vehicle Variant -
Vehicle Colour -
Vehicle Category Commercial vehicle
Name of Driver -
Contact Number -
Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the date and time of the accident.
2. This form must be completed by the Police Officer attending the scene.
3. Information provided must be accurate and correct. Any false information will be treated as a criminal offence.
4. The police will investigate the circumstances of the accident and will issue a report to the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded to the insurers of the vehicle and the driver involved in the accident. The General Insurance Association and the Motor Vehicle Association will also be notified.
7. By the signing of this report, the driver, the insured, the insurer and the police officer agree to the terms and conditions of the report.
8. Consent under the Personal Data Protection Act (PDPA) - I consent to the collection, use and disclosure of my personal information for the purposes of the investigation of the accident and the preparation of the report.

I, the driver, do hereby consent to the collection, use and disclosure of my personal information for the purposes of the investigation of the accident and the preparation of the report.

I, the insured, do hereby consent to the collection, use and disclosure of my personal information for the purposes of the investigation of the accident and the preparation of the report.

I, the insurer, do hereby consent to the collection, use and disclosure of my personal information for the purposes of the investigation of the accident and the preparation of the report.

I, the police officer, do hereby consent to the collection, use and disclosure of my personal information for the purposes of the investigation of the accident and the preparation of the report.



By the driver of the vehicle
Name

[Signature]
Name

[Signature]
Name

SKETCH PLAN



A: 3R 1760C
 B: 9Q 222R
 C: GBF 1865J

A/E towards T/AS
 before Jersey Post Rd.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was traveling along when the traffic in front of me came to a stop. I slowed down my vehicle. A red car came to a stop a few minutes later. I felt an impact from the rear of my vehicle. The impact pushed my vehicle and lightly touch the vehicle C in front. We all came down and vehicle C said there was no damage and left the scene. We exchanged information and left. Vehicle B was unable to drive after.

* Kindly take note that you have 14 days to revert to Own Insurance Claim (own damage).

Claim OD / TP At Falcon-Air

Claim OD / TP Own W/shop

Reporting Only

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature & Name



Driver's signature (If driver is not the policyholder) Date & Time




Reporting Centre Personnel's Signature Name & Time































==

Enquire Vehicle Owner Details

Enquire Vehicle Owner Details (As At 25 Aug 2022 / 09:10:00)

Vehicle Owner Details

Owner ID Type:

Company

Owner ID:

200801644E

Owner Name:

BAN HENG AQUATIC SUPPLIES PTE. LTD.

Registered Address Type:

Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.:

175

Registered Street Name:

PANDAN LOOP

Registered Unit No.:

-

Registered Building Name:

-

Registered Postal Code:

128459

Vehicle Insurance Details

Vehicle No.:

YQ222R

Make Description/Model:

MINIBUS / CANTER FEB21ER4SDEN (CBU)

Insurance Company Name:

LONPAC INSURANCE BHD

Save as PDF

OK →

Print

For Customer Service please visit

1 Pickering Street

#01-01 Great Eastern Centre

Tel: +65 6248 2888 Fax: +65 6327 3080

Certificate of Insurance

ORIGINAL

The Motor Policy to which this Certificate relates is issued in accordance with the provisions of the following Legislation :

Motor Vehicles (Third-Party Risks and Compensation) Act (Cap.189 of the Revised Edition) (Singapore)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1996 Edition (Singapore)
Motor Vehicles (Third-Party Risks) Rules, 1959 (of Federation of Malaya)
Road Transport Act 1987 (of Malaysia)
Road Transport (Amendment) Act 2019 (of Malaysia)

FORM M2300

Policy No. : 2021-V0118901-VCV
Policy Type : Commercial Vehicle

Risk# : 0001
Cover : Comprehensive

DESCRIPTION OF VEHICLES:

Vehicle Registration : YQ4760C
Vehicle Make & Model : MITSUBISHI FUSO FM65FM6RDEA

Name of Insured : SUMMER TRANSPORTER PTE LTD

Period of Insurance : 08-10-2021 (0000HRS) to 07-10-2022

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE *

Any person who is driving on the Policyholder's order or with their permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

LIMITATIONS AS TO USE


- (1) Use in Connection with the Policyholder's business.
- (2) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.
- (3) Use for social, domestic and pleasure purposes.

The policy does not cover :-

- (1) Use for racing, pace-making, reliability trial or speed-testing.
- (2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.
- (3) Use for the carriage of passengers for hire or reward.

Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (of Malaysia) are not to be included under these headings.

Signed for and on behalf of the Company



Authorised Signature

Annex

Transaction ref 20211008154812921758

Please check that the owner and vehicle details are correct:

1. Name : SUMMER TRANSPORTER PTE.
LTD.
2. Identification No. Type : Company
3. Identification No. : 201103325Z
4. Country/Region : -
5. Registered Address : 50 SERANGOON NORTH
AVENUE 4
#07-06
FIRST CENTRE
SINGAPORE 555856
6. Mailing Address : -
7. Vehicle Registration No. : YQ4760C
8. Effective Date of Ownership : 08 Oct 2021
9. Original Registration Date : 08 Oct 2021
10. First Registration Date : 08 Oct 2021
11. Vehicle Type : B30 - Goods (Open) Lorry (Wooden
Body)
12. Vehicle Scheme : Normal
13. Attachment 1 : With Hood
14. Attachment 2 : With Power Tailboard
15. Attachment 3 : -
16. Vehicle Make : MITSUBISHI
17. Vehicle Model : FUSO FM65FM6RDEA
18. Year of Manufacture : 2021
19. Primary Colour : White
20. Secondary Colour : -
21. Passenger Capacity : 2
22. Chassis/Trailer Chassis No. : FM65FMA40103 / -
23. Propellant/Emission Standard : Diesel / Euro VI
24. Engine No./Motor No. : 6M60275845 / -
25. Engine Capacity(cc)/Power Rating(kW) : 7545 / -
26. Maximum Power Output(kW/bhp) : - / -
27. Unladen Weight(kg) : 8100
28. Maximum Laden Weight(kg) : 16000
29. Open Market Value : \$71,095.00



100097702-5001919

Annex

Transaction ref 20211008154812921758

Please check that the owner and vehicle details are correct:

30. PARF Eligibility	: No
31. PARF Eligibility Expiry Date	: -
32. Minimum PARF Benefit	: \$0.00
33. IU Label No.	: -
34. COE No.	: 2021100805000320K
35. COE Expiry Date	: 07 Oct 2031
36. COE Category	:
37. Quota Premium/Prevailing Quota Premium	: \$40,004.00
38. Actual Quota Premium/PQP Paid	: \$38,373.00
39. Actual ARF Paid	: \$3,555.00
40. CO2 Emission(g/km)	: -
41. CO Emission(g/km)	: -
42. HC Emission(g/km)	: -
43. NOx Emission(g/km)	: -
44. PM Emission(mg/km)	: -
45. Actual CEVS/VES Rebate Utilised	: -
46. CEVS/VES/CVES Surcharge Paid	: -
47. Actual Green Vehicle Rebate Utilised	: -
48. Actual EV Rebate Utilised	: -
49. CVES Incentive Eligible	: -
50. Total CVES Incentive Disbursed	: -
51. Vehicle Lifespan Expiry Date	: 07 Oct 2041
52. Road Tax Amount	: \$245.00
53. Road Tax Start Date	: 08 Oct 2021
54. Road Tax End Date	: 07 Apr 2022
55. Remarks	: The vehicle is registered under Early Turnover Scheme.

Derrick Motor Works

Blk 9002, Tampines Street 93 #01-72 / Tampines Industrial Park A Singapore 528836

INVOICE

To: Motor Claims Dept
Attn:

Invoice No: 3148
Date: 13/12/2022

DESCRIPTION	AMOUNT
Services rendered to repair vehicle YQ4760C, which was involved in a chain collision accident on the 25/08/2022 along AYE towards Tuas.	
Cost of repairs on a Lumpsum Basis	SGD 22,150.00
Total	SGD 22,150.00
Registration no: YQ4760C	
Make/Model: MITSUBISHI FUSO FM65FM6RDEA	
Our reference: 3148	
<i>All payments made payee to: DERRICK MOTOR WORKS</i>	

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Professional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Reliance Appraisal Pte Ltd© 272D, Sengkang Central Singapore 544272
Co. Reg. No. 202214158E Email: info@ra-appraisal.com Tel: (65) 9010 7765

INVOICE

To: Derrick Motor Works
Attn: Blk 9002, Tampines Street 93 #01-72, Tampines
Industrial Park A
Singapore 528836

Invoice No.: 202209001
Date: 15/11/2022

DESCRIPTION	AMOUNT
Service rendered for appraisal / inspection report: YQ4760C	
Professional inspection fees	SGD 1,055.00
Photographs 60 pcs	SGD 60.00
Transport fees	SGD 60.00
Re-inspection fees (work in progress, post repair inspection)	SGD 80.00
Total	SGD 1,255.00
Singapore Dollars One Thousand Two Hundred Fifty Five Only	
Registration no.: YQ4760C	
Make/Model: MITSUBISHI FUSO FM65FM6RDEA	
Our reference: 202209001	
All payments made payee to:-	
Reliance Appraisal Pte Ltd	



for Reliance Appraisal Pte Ltd

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Professional
Motor Vehicle Appraiser and Insurance Loss Adjuster

Reliance Appraisal Pte Ltd© 272D, Sengkang Central Singapore 544272
Co. Reg. No. 202214158E Email: info@ra-appraisal.com Tel: (65) 9010 7765

VEHICLE DAMAGE ASSESSMENT REPORT

Attn: Derrick Motor Works
Blk 9002, Tampines Street 93 #01-72, Tampines Industrial Park A
Singapore 528836

Adjuster Ref: 202209001
Date: 15/11/2022
Type of Claim: TP

CLAIM DETAILS

Claim No: Handling Repairer: Derrick Motor Works
Claimant Vehicle No: **YQ4760C** Insured Vehicle No: **YQ222R**
Claimant: SUMMER TRANSPORTER PTE LTD
Date of Loss: 25/8/2022 Policy No: NA

VEHICLE DETAILS

Vehicle No: YQ4760C Colour: White
Model: FUSO FM65FM6RDEA Make: MITSUBISHI
Registration Date: 08/10/2021 (Man. Year: 2021) Engine No: 6M60275845
COE Category: C - Goods Vehicle & Bus Chassis No: FM65FMA40103
Market Value/ N/A Engine Capacity: 7545
New Car Price (S\$):
Sum Insured (S\$): **Market Value/New Car Price** Odometer (km): 42,754

CONDITION OF VEHICLE DURING INSPECTION

General Condition: Fair Steering: In Order Footbrake: In Order
Pre-accident Condition: Good Engine Modification: No Handbrake: In Order

CONDITION OF TYRES

Front Tyre Brand: DUNLOP Rear Tyre Brand: DUNLOP
Front Left Size: 11R22.5 6mm Rear Left Size: 11R22.5 6mm
Front Right Size: 11R22.5 6mm Rear Right Size: 11R22.5 6mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer	Adjuster	Difference	Diff%
Part(s)	31,852.52	23,741.18	8,111.34	25.47
Labour	2,570.00	1,830.00	740.00	28.79
Paintwork Labour	2,800.00	2,100.00	700.00	25.00
Gross Total (S\$)	37,222.52	27,671.18	9,551.34	25.66
(Lump Sum) Adjusted Total (S\$)		22,150.00	15,072.52	40.49
- Excess (S\$)	NA	NA	0.00	0.00
Sub Total (S\$)	37,222.52	22,150.00	15,072.52	40.49
+ 7% GST (S\$)	2,605.58	1,550.50	1,055.08	40.49
Nett Repair Cost + 7% GST (S\$)	39,828.10	23,700.50	16,127.60	40.49
Nett Liability (S\$)	39,828.10	23,700.50	16,127.60	40.49

INSPECTION DETAILS

Date of Assignment: 5/9/2022
Date Inspected: 5/9/2022
Estimated Repair Period: 8.0 day(s)
Surveyed on a "without prejudice" basis

Inspected At: Derrick Motor Works
Blk 9002, Tampines Street 93 #01-72,
Tampines Industrial Park A
Singapore 528836



Adjuster: Ho Too Boon

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

RA
RELIANCE APPRAISAL Pte Ltd
Proper Precise Professional
Motor Vehicle Appraiser and Insurance Loss Adjuster

Reliance Appraisal Pte Ltd© 272D, Sengkang Central Singapore 544272
Co. Reg. No. 202214158E Email: info@ra-appraisal.com Tel: (65) 9010 7765

Adjuster Ref: 202209001

WITHOUT PREJUDICE

Dear Sir,

Re : Third Party Claim For Vehicle Registration No. YQ4760C

We refer to your instruction to appraise the above-mentioned vehicle on 05/09/2022
Which was involved in a chain accident that happen on the 25/08/2022@0910hrs along AYE towards Tuas before Jurong Port Road.

A static inspection was carried out and our report is enclosed for your perusal. The estimated cost of repair submitted by Messrs. Derrick Motor Works for SGD 37222.52 as per our attached schedule has been inspected thoroughly by us against the actual damages sustained on the above-mentioned vehicle and we recommend the replacement and rectification accordingly.

Our revised quotation for the repair is SGD 27671.18. In our opinion, it to be excessive. Therefore, we recommend a contract lump-sum repair cost. This is more economical than to have the above-mentioned vehicle repaired on parts by/for parts basis. Invariably, the repairer has the prerogative/option for the recommended replacement parts to either be repaired or be replaced.

We have negotiated with the repairer and they have agreed to repair the above-mentioned vehicle for SGD 22150 NETT. Which, in our opinion is fair and reasonable.

The repairer has agreed to undertake the repairs to your requirement at the recommended contract lump-sum. However, we have not given any instruction and authorisation to the repairer to proceed with the repairs.

Under normal circumstances, the entire repair of the damaged vehicle should be completed within a reasonable period of 8 days.

In accordance, we have **Not Authorised** the repair to the damaged vehicle and the survey was conducted strictly on a "**WITHOUT PREJUDICE**" basis.

We are reverting the matter to you for a decision, and enclosed is our vehicle inspection report, appraisal schedule and invoice for services rendered.

Please do not hesitate to contact us if you have any queries on this matter.

Yours faithfully,
Reliance Appraisal Pte Ltd©

Ho Too Boon
Motor Vehicle Appraiser



Encls. :

The information contained in these document may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you received this document by error, please contact us immediately to arrange for its return.

Recommended Part(s)						
No	Qty	Part N	Description	Condition	Repairer	Adjuster
1	1		Front bumper	Bent	1,244.90	N 1,244.90 N
2	2		Front bumper bracket	Distorted	326.60	N 326.60 N
3	1		Front bumper lamp o/s	Cut	175.70	N 175.70 N
4	2		Front headlamp	Cut/Distorted	1,468.60	N 1,468.60 N
5	2		Front headlamp garnish	Cut/Distorted	770.20	N 770.20 N
6	1		Front radiator grille	Necessary	556.30	N 556.30 N
7	1		Front radiator grille logo	Not Necessary	79.30	N 0.00 N
8	1		Front radiator grille clips	Not Necessary	60.00	S 0.00 S
9	1		Rear tailgate door	Repair	7,200.00	S 0.00 S
10	2		Rear tailgate hydraulic lifter	Jam / Malfunction	13,600.00	S 13,600.00 S
11	2		Rear tailgate hydraulic lifter garnish	Necessary	490.00	S 490.00 S
12	2		Rear tailgate hydraulic lifter control valve	Distorted / Malfunction	972.00	S 972.00 S
13	1		Rear tailgate hydraulic lifter bracket	Necessary	960.00	S 960.00 S
14	1		Rear tailgate hydraulic lifter oil	Bent	180.00	S 180.00 S
15	2		Rear reinforcement side beam	N/S - Bent	1,360.00	N 680.00 N
16	2		Rear reinforcement side beam reflective sticker	Necessary	150.00	S 80.00 S
17	1		Rear centre beam	Bent	1,480.00	S 1,480.00 S
18	2		Rear centre beam bracket	Bent	840.00	N 840.00 N
19	1		Rear centre beam reflective sticker	Necessary	280.00	S 220.00 S

L=List Item. N=Nett Item. S=Special Nett Item.

Sub Total (\$\$)	32,193.60		24,044.30
- List Item Discount (\$\$)	0.00	10%	0.00 10%
- Nett Item Discount (\$\$)	341.08	5%	303.12 5%
+ F Item Margin (\$\$)	0.00	0%	0.00 0%
Part(s) Total (\$\$)	31,852.52		23,741.18
- Betterment (\$\$)	0.00	0%	0.00 0%
Part(s) Total after Betterment (\$\$)	31,852.52		23,741.18



Recommended Labour

No	Description	Repairer	Adjuster
1	To dismantle / renew the Front accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$350.00 per day)	1,050.00	700.00
2	To disconnect rear wire harness of electrical component to facilitate repairs, reconnect and check functions.	120.00	80.00
3	Supply spray paint material and necessary items to respray Front bumper, radiator grille, side panel, headlamp panel and etc... (\$350.00 per panel)	1,400.00	1,050.00
4	To dismantle / renew the Rear accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$350.00 per day)	1,400.00	1,050.00
5	Supply spray paint material and necessary items to respray Rear beam, bracket, side beam and etc... (\$350.00 per panel)	1,400.00	1,050.00
Labour Total (S\$)		5,370.00	3,930.00

COST OF REPAIRS		Repairer	Adjuster
	Part(s)	31,852.52	23,741.18
	Labour	2,570.00	1,830.00
	Paintwork Labour	2,800.00	2,100.00
	Gross Total (S\$)	37,222.52	27,671.18
	(Lump Sum) Adjusted Total (S\$)		22,150.00
	- Excess (S\$)	NA	NA
	Sub Total (S\$)	37,222.52	22,150.00
	+ 7% GST (S\$)	NA	NA
	Nett Total (S\$)	37,222.52	22,150.00

<END OF ESTIMATE>



RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Professional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 1



Photo 2

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Profesional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 3



Photo 4

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Professional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 5



Photo 6

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Professional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 7



Photo 8

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Professional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 9



Photo 10

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Profesional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 11



Photo 12

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Profesional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 13



Photo 14

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Professional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 15



Photo 16

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Profesional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 17



Photo 18

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Profesional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 19



Photo 20

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Profesional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 21



Photo 22

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Professional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 23



Photo 24

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Profesional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 25



Photo 26

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Profesional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 27



Photo 28

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Professional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 29




Photo 30

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Profesional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 31



Photo 32

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Professional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 33



Photo 34

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Professional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 35



Photo 36

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Profesional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 37



Photo 38

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Profesional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 39



Photo 40

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Professional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 41



Photo 42

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Professional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 43



Photo 44

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Profesional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 45



Photo 46

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Profesional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 47



Photo 48

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Profesional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 49



Photo 50

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Profesional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 51



Photo 52

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Professional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001




Photo 53



Photo 54

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Professional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 55



Photo 56

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Professional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 57



Photo 58

RA

RELIANCE APPRAISAL Pte Ltd

Proper Precise Professional

Motor Vehicle Appraiser and Insurance Loss Adjuster

Our Ref: 202209001



Photo 59



Photo 60