



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22012658/Awy3e2 Date: 13/02/2023 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJV 5421B	Veh. Inspected	SLR 9294Y	
Policy No.	D22MTPV01014638	Coverage (\$)	0.00	
Claim No.	CMTD2204627/GPL	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	19/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN JETTA	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WWWZZZ16ZGM019810	Colour	GOLD	
Odometer	174253 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	CONTINENTAL	6 mm	
L/H Front Tyre	225/45 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/12/2022	Inspection Date	20/12/2022	
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	