

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305539719
Date : 16-12-22
Time of Fax : _____

Via Fax : EMAIL
Your Insured : 8MHA 55651A
Date of Acc : 16.12.22

Attn: Motor Claims Department

ALLIANZ

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH 9UDOK

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
◆ <u>Jumani Bin Masudin</u>	<u>Tel: 6214 8315 or HP: 9635 5305</u>
◆ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
◆ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006

} **jumanibm@cdge.com.sg**
Fax no. 6546 8156

→ If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President
Taxi Accident Repair

Date/Time: 16.12.2022 14:33

Page : 1

Job: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5434992

JC NO: 305539719

OWNER

REGN NO:

SH 9120K

MILEAGE

S

COMFORT TRANSPORTATION PTE LTD

7010045

OWNER NO

ESS

383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

(R)

(O)

(P)

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ

16.12.2022 10:55

YR OF MANU

17.03.2017

TARGET DATE

CHASSIS CODE

KMHC851CVHU022742

COMPLETION DATE/TIME:

IDENTIFICATION CARD NO.

JOB DESCRIPTION


Accident Date: 16.12.2022

ATURE: 3P.16.12.22

/NO

LABOR CODE

DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Confirmation Slip

Exit Pass

No.:

SH 9120K

JU ALLIANZ

Vehicle No.:

SH 9120K

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SH 9120K
 MAKE HYUNDAI
 MODEL IONIQ

DATE: 16.12.22
 MVA JUMANI
 DOA: 16.12.22

ALLIANZ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			\$459.40
10	REAR BUMPER CLIPS			\$22.00
	REAR BUMPER CENTER MOULDING			\$451.25
	REAR BUMPER BEAM			\$394.80
	REAR BUMPER STAY LH			\$138.10
	REAR REFLECTOR LH			\$41.45
	REAR BUMPER SIDE BRACKER LH			\$55.80
	BSD -BLIND SPORT RADER			\$1,784.40
	REAR BUMPER CENTRE UNDER COVER			\$225.00
	REAR BUMPER SIDE UNDER COVER LH			\$108.00
	SUB TOTAL			\$3,680.20
	LESS 25%			\$920.05
	DISCOUNTED TOTAL			\$2,760.15
	REVERSE SENSOR			\$180.00
				\$180.00
	Labour Charge			
	PANEL BEATING			\$400.00
	SPRAY PAINT			\$300.00
	REMOVE / REFIX REVERSE SENSOR			\$50.00
	TOTAL LABOUR			\$750.00
	ESTIMATE TOTAL			\$3,690.15
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

NET