



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Ref: CS/AGI22012703/Uvy3e2

Date: 08/03/2023

Code: AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLF 8748A	Veh. Inspected	SJH 9559K
Policy No.	P10787932R00	Coverage (\$)	0.00
Claim No.	C10019352/CD	Excess (\$)	0.00
Assign From	FRAULEINE KHOO	Assign Date	20/12/2022

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	RU11207811	Colour	WHITE
Odometer	66080 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50Z R17	MICHELIN	6 mm
L/H Front Tyre	225/50Z R17	MICHELIN	6 mm
R/H Rear Tyre	225/50Z R17	MICHELIN	6 mm
L/H Rear Tyre	225/50Z R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/12/2022	Inspection Date	20/12/2022
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**