



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD	Ref: CS/ASM22012704/Gnp3m4
8 SHENTON WAY #24-01 AXA TOWER	Date: 12/01/2023
SINGAPORE 068811	
ATTN: ANG YVONNE	Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8078M	Veh. Inspected	FBM 8405X
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S2M04EPM	Excess (\$)	0.00
Assign From	ANG YVONNE	Assign Date	20/12/2022

2. Vehicle Particulars & Condition

Make & Model	HONDA CB190X	c.c	184
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	LWBPCL1A2H1004528	Colour	BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	110/70 R17	MAXXIS	2 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/70 R17	MAXXIS	2 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT AND N/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/11/2022	Inspection Date	22/12/2022
Survey held at	3POINTS ENTERPRISE 50 BUKIT BATOK STREET 23, #02-22, MIDVIW BUILDING, SINGAPORE 659578		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**