

08/11/13) wof

ASS. REC. BY: Marcus

REF:

CS/CT/22012719/Uq3

### ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

SJM 4045H

at Workshop m/s

Car city Pan

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

of

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

46k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

5086

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJM 4045H

Yr Regn:

31/11/08

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

Hyundai Avante

c.c

15-91

Colour

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

178059

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMH DU 41BR9U 650329

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/45-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

05/11/22

D.O.I.

16/02/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

248k.  
COR UAT/ 30-12-2028 LTA 16202 asat 13-02-23  
L/S 15-20

LS 1300 (Red 1747.66, 57%)

Date/Time, File Pass to?

☐

: Preli. Report

1) 13/3 12/12/22  
Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

MER-00

Lump Sum / I.B.I. (\$

1300

TOTAL

**Car City Auto Centre Pte Ltd**  
**#01-198, Blk 9006 Tampines Street**  
**93,**  
**528840**

**Insurer Reference: SJM4045H**  
**Repairer Reference: TP/22071-OD**  
**Date calculated: 20/12/2022 12:38 PM**

**Full Report**  
**Registration: SJM4045H**  
**Printed: 20/12/2022 12:41 PM**

## Summary Information

### Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Anson Seah	Currency:	SGD
Claim Reference:	SJM4045H	Date of Incident:	05/11/22
Estimated Repair Time:	5	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

## Vehicle Details

### Vehicle

Manufacturer:	HYUNDAI
Model:	AVANTE (HD)
Sub Model:	BASIS
Model Sheet Number:	30 22 50
Registration:	SJM4045H
VIN number:	
Odometer:	146333

### Model Specs

TWO COAT METALLIC	PREPARE OFF VEHICLE	CLEAR COAT HARD
-------------------	---------------------	-----------------

*not AdAmb  
du  
wears  
16/2/23  
Success?  
1/5 → 4 days*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## Vehicle Condition


### Vehicle Status

Pre-Accident Damage:

Date of Inspection:

### Damage Areas

All ☐  
Underbody ☐



## Tyres Condition

Tyre Brand	Tread (Left Middle), Tread (Left Outer), Tread (Left Inner), Tread (Right Inner), Tread (Right Outer), Tread (Right Middle), mm						Condition
	mm	mm	mm	mm	mm	mm	Fair
							Fair

Spare Tyre Brand      Tread (Spare), mm  
5

## Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
86510R00	RENEW COMPLETE FRONT BUMPER INCLUDES: FRONT BUMPER, FRONT BUMPER REINFORCEMENT AND REQUIRED ATTACHED PARTS R + R AND IF NECESSARY RENEW.		6.0	25.20
92000R0B	REMOVE/REFIT BOTH HEADLIGHT UNITS INCLUDES: SET HEADLIGHT BEAMS		3.0	12.60
NO NUMBER	R + R FRONT PANEL		20.0	84.00
86520R00	RENEW REAR BUMPER CPL INCLUDES: REAR BUMPER, REAR LAMPS, REINFORCEMENT REAR BUMPER AND REQUIRED TRIMS REMOVE AND REFIT ATTACHED PARTS ASSEMBLE IF NECESS RENEW		8.0	33.60

Code	Description	WU	Price SGD
NO NUMBER	RENEW REAR END PANEL	63.0	264.60
97606R00	R + R AIR CONDITIONING CONDENSER	10.0	42.00
85731R00)	R + R LEFT BOOT TRIM	1.0	4.20
85731R0R)	R + R RIGHT BOOT TRIM	1.0	4.20
85710R00	R + R LUGGAGE COMP FLOOR CARPET	2.0	8.40
25300R00)	R + R RADIATOR	7.0	29.40
	INCLUDES: R + R COMPLETE RADIATOR SHROUD		
NO NUMBER	DRAIN/REFILL COOLING SYSTEM	3.0	12.60
09760A00	DRAIN + REFILL AIR CONDITIONING	5.0	21.00
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>		<b>12.90</b>	<b>129.0</b>
<b>Total of Labour</b>			<b>541.80</b>

## Paint

Paint Work		SYSTEM AZT		Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC	WU		Price	SGD
	REAR PANEL NEW PART PAINTING	22.0			
	FRONT BUMPER NEW PART PAINT K1R	10.0			
	REAR BUMPER NEW PART PAINT K1R	10.0			

## Paint Material Per Part

Code	Description	Price SGD
2711	REAR PANEL NEW PART PAINTING	26.40
0283	FRONT BUMPER NEW PART PAINT K1R	47.23
2583	REAR BUMPER NEW PART PAINT K1R	47.23

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		42.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.50	5.0	21.00
<b>Total</b>	<b>10 WU/h</b>	<b>72.0</b>	<b>302.40</b>

Material Cost - Paint	Price SGD
New Part Painting	26.40
New Part Painting - Plastic K1R	94.46
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
<b>Total</b>	<b>158.46</b>

## Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01	Price SGD
0283	FRONT BUMPER	865112H000	Original	De/torn	270.00/
0315	FRT BUMPER ABSORBER	865202H010	Original	Torn	65.00/



Code	Description	Part Number	Part Source	Price SGD
0340	FRT BUMPER SUPPORT	865302H010	Original 17 X	160.00X
0410	GRILLE	863502H000	Original 20 X	130.00X
1009	INNER FRT PANEL CPL	641012H000	Original 2 X	290.00X
2583	REAR BUMPER	866102H000	Original 22/22 X	280.00X
2640	REAR BUMPER SUPPORT	866312H010	Original 17 X	140.00X
2644	REAR BUMPER DAMPER	866202H010	Original 10.1 X	60.00X
2711	REAR PANEL	691002H010	Original 2 X	180.00X
1004	FRONT NUMBER PLATE	NUMBER PLATE	Original 50 X	35.00X

f: OEM Parts  
n: Non-OEM Parts  
u: Used parts

**Savings**  
**Subtotal**  
**Fixed Sundry Parts Price**

**0.00**  
**1,610.00**  
**100.00**

**Total** **1,710.00**

## Extras

Code	Description	Price SGD
1000	PARKING SENSOR SENSOR 1 Set	200.00*
1001	ANTI-FREEZE 3 LITRE ANTI-FREEZE	60.00*
1002	AIR-CON GAS AIR-CON GAS	50.00*
1003	CHECK WIRING CHECKING WIRING	25.00*
<b>Total Extras</b>		<b>335.00</b>

## Final Calculation

	SGD	SGD
<b>Parts</b>		
Fixed Sundry Parts Price	1,610.00	
<b>Total Parts</b>	100.00	<b>1,710.00</b>
<b>Labour Time Base 10 WU/h</b>		
Total 129.0 WU X 42.00 SGD/h	541.80	
<b>Total of Labour</b>		<b>541.80</b>
<b>Total Of Extras</b>		<b>335.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 72.0 WU X 42.00 SGD/h	302.40	
Material Cost	158.46	
<b>Total Paint Including Material</b>		<b>460.86</b>
<b>Repair Cost Excludes GST</b>		<b>3,047.66</b>
GST (+8.0%)		<b>243.81</b>
<b>Repair Cost Included GST</b>		<b>3,291.47</b>

**Comments**

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

**Assessment Note**

---

No assessment notes entered.

## Vehicle Condition


### Vehicle Status

Pre-Accident Damage:

Date of Inspection:

### Damage Areas

All ☐  
Underbody ☐



## Tyres Condition

Tyre Brand	Tread (Left Middle), Tread (Left Outer), Tread (Left Inner), Tread (Right Inner), Tread (Right Outer), Tread (Right Middle), mm						Condition
	mm	mm	mm	mm	mm	Middle), mm	
							Fair
							Fair

Spare Tyre Brand      Tread (Spare), mm  
5

## Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
86512R00	RENEW FRONT BUMPER INCLUDES: BUMPER AND REQUIRED ATTACHED PARTS R + R NOT INCLUDED: REINFORCEMENT BUMPER REMOVE AND REFIT		8.0	33.60
92000R0B	REMOVE/REFIT BOTH HEADLIGHT UNITS INCLUDES: SET HEADLIGHT BEAMS		3.0	12.60
NO NUMBER	R + R FRONT PANEL		20.0	84.00
86651R00	RENEW REAR BUMPER INCLUDES: R + R REAR BUMPER, TAIL LAMPS AND NECESSARY TRIMS, CONVERT ATTACHED PARTS, RENEW IF NECESSARY		8.0	33.60



Code	Description	WU	Price SGD
	DOES NOT INCLUDE: R + R REAR BUMPER REINFORCEMENT		
97606R00	R + R AIR CONDITIONING CONDENSER	10.0	42.00
25300R00)	R + R RADIATOR	7.0	29.40
	INCLUDES: R + R COMPLETE RADIATOR SHROUD		
NO NUMBER	DRAIN/REFILL COOLING SYSTEM	3.0	12.60
09760A00	DRAIN + REFILL AIR CONDITIONING	5.0	21.00
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>		6.40	64.0
<b>Total of Labour</b>			268.80

## Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	FRONT BUMPER NEW PART PAINT K1R	10.0
	REAR BUMPER NEW PART PAINT K1R	10.0

## Paint Material Per Part

Code	Description	Price SGD
0283	FRONT BUMPER NEW PART PAINT K1R	47.25
2583	REAR BUMPER NEW PART PAINT K1R	47.25

### Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			20.0	
Preparation Comp. Work Plastic		1.50	15.0	63.00
<b>Total</b>	<b>10 WU/h</b>	<b>3.50</b>	<b>35.0</b>	<b>147.00</b>

### Material Cost - Paint

	Price SGD
New Part Painting - Plastic K1R	94.40
Material-constant Plastic	28.60
<b>Total</b>	<b>123.00</b>

## Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01	Price SGD
0283	FRONT BUMPER	865112H000	Original		270.00
0315	FRT BUMPER ABSORBER	865202H010	Original		65.00
0410	GRILLE	863502H000	Original		130.00
1009	INNER FRT PANEL CPL	641012H000	Original		<del>290.00</del>
2583	REAR BUMPER	866102H000	Original		280.00
2644	REAR BUMPER DAMPER	866202H010	Original		60.00
1004	FRONT NUMBER PLATE	NUMBER PLATE	Original		35.00

f: OEM Parts  
n: Non-OEM Parts  
u: Used parts

### Savings

0.00



<b>Subtotal</b>	<b>1,130.00</b>
<b>Fixed Sundry Parts Price</b>	<b>100.00</b>
<b>Total</b>	<b>1,230.00</b>

### Extras

Code	Description	Price SGD
1000	PARKING SENSOR SENSOR	200.00*
1003	CHECK WIRING CHECKING WIRING	25.00*
	<b>Total Extras</b>	<b>225.00</b>

### Final Calculation

	SGD	SGD
<b>Parts</b>	1,130.00	
Fixed Sundry Parts Price	100.00	
<b>Total Parts</b>		<b>1,230.00</b>
<b>Labour Time Base 10 WU/h</b>		
Total 64.0 WU X 42.00 SGD/h	268.80	
<b>Total of Labour</b>		<b>268.80</b>
<b>Total Of Extras</b>		<b>225.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 35.0 WU X 42.00 SGD/h	147.00	
Material Cost	123.06	
<b>Total Paint Including Material</b>		<b>270.06</b>
<b>Repair Cost Excludes GST</b>	1703.86	<b>1,993.86</b>
GST (+8.0%)		159.51
<b>Repair Cost Included GST</b>		<b>2,153.37</b>
<b>Deductions (Excludes GST)</b>		
Repair Cost Discount (+20.00%)	-398.77	
<b>Total Of Deductions (Excludes GST)</b>		<b>-398.77</b>
<b>Grand Total Excludes GST</b>	4/5 815.20	<b>1,595.09</b>
GST (+8.0%)		127.61
<b>Grand Total Included GST</b>		<b>1,722.70</b>

### Comments

\* - USER SUPPLIED DATA  
 NN - NO MANUFACTURERS CODE EXISTS  
 ) - WU PARTIAL INCL IN OTHER POSITIONS

### Assessment Note

No assessment notes entered.

**Car City Auto Centre Pte Ltd**  
**#01-198, Blk 9006 Tampines Street**  
**93,**  
**528840**

**Insurer Reference: SJM4045H**  
**Repairer Reference: TP/22071-OD**  
**Date calculated: 20/02/2023 9:02 AM**

**Full Report**  
**Registration: SJM4045H**  
**Printed: 20/02/2023 9:03 AM**

### Summary Information

#### Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Anson Seah	Currency:	SGD
Claim Reference:	SJM4045H	Date of Incident:	05/11/22
Estimated Repair Time:	<del>5</del>	Hire Car Start:	
Actual Repair Days:	<u>4/5</u>	Hire Car End:	

#### Vehicle Details

##### Vehicle

Manufacturer:	HYUNDAI
Model:	AVANTE (HD)
Sub Model:	BASIS
Model Sheet Number:	30 22 50
Registration:	SJM4045H
VIN number:	
Odometer:	146333

##### Model Specs

AUTO AIR CON	1.6 LTR 90 KW	TWO COAT METALLIC	PREPARE OFF VEHICLE
CLEAR COAT HARD			

4/5      \$ 1334.26      9

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	07/11/2022 09:45 (SGT)
Reported by	Both
Date of Accident	05/11/2022 11:00 (SGT)
Exact Location of Accident	Near KPE, Singapore
Additional Location Information	TOWARDS CITY
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJM4045H
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	CHAN YEE MAN
NRIC No	SXXXX508G
Email Address	CHAN_EMAN@HOTMAIL.COM
Mobile Phone No	(Phone) +65-97316288
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Avante
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1600

#### INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMPCSNW00139542201

#### DRIVER

Name of Driver	CHAN YEE MAN
NRIC No	SXXXX508G
Date Of Birth	19/02/1991
Occupation	Indoor



Date Of Driving Pass	17/05/2010
Driving experience	12 YEARS AND 6 MONTHS
Gender	Female
Mobile Number	(Phone) +65-97316288
Alt. Phone Number	-
Email Address	CHAN_EMAN@HOTMAIL.COM
Address	BLK 619B PUNGGOL DR #11-767
Address complement	-
Postcode	822619
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Raining
Road Surface	Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### PASSENGER 1

Name	CHOW LAI CHU
Gender	Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO SKETCH PLAN

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SNA8725T
Vehicle Manufacturer	Toyota
Vehicle Model	Vios
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	WONG KUM FAI
NRIC No	SXXXX911H
Contact Number	(Phone) +65-82231138
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	3

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SNG5164A
Vehicle Manufacturer	Toyota
Vehicle Model	Vanguard
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	ONG SOO PENG
Passport No/FIN	FXXXX532P
Contact Number	(Phone) +65-91003803
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

**Describe Circumstance of the Accident**

Vehicle SVA 8725T e broke on the road (near eye to city).  
 my ~~vehicle~~ vehicle SVA 8725T has break in time.  
 Vehicle behind SVA 5164A has hit me while I was stationary and  
 caused the car to go forward and hit the first car in front 8725T.


After the incident has happened, all parties came down to take photo.  
 Owner of the last car, SVA 5164A has urged me and the first car  
 owner SVA 8725T to settle on ~~our~~ our own ~~to~~ as he believed  
 that there were very limited damages done to my car.


The first car owner and myself didn't reach a conclusion when the  
 police team arrive. They ask us to exchange our contacts and ~~leave~~ to  
 leave the place.


No one has any injuries, hence, no police report.

**Declaration**

We declare the foregoing particulars are true in every respect.

X  05/11/22  
 Policyholder's Signature / Date & Time  
 2 pm

  
 Actual Driver's Signature (if driver is not the policyholder)  
 / Date & Time

  
 Witnessed by Reporting Centre Personnel  
 (Name as in NRIC/ID card)



**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
  2. This Form must be completed by the Policyholder and/or the Actual Driver.
  3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
  5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
  6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

X

05 November 2022 2PM  
Policyholder's Signature / Date & Time

ANSON  
Actual Driver's Signature (if driver is not the policyholder) / Date & Time

ANSON  
Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

**Sketch Plan**

--

vJun2022

1