

Ass. Rec. By:

REF: CS/EGI22012720/Avy3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: **XE 2641B**

Policy No. _____

Claims No. **CDMCG22002741**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SNA 6378A** Yr Regn: **2015, Nov**

Type: **M. Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Mit Outlander** C.C. **2360**

Colour: **Silver** A/C: Insured / Std / NI / NA

Sp. Reading: **1210** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **JMYXT6F3W6200699**

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **Inorder** / Jammed / Leaked / Burnt or

Brake: **Inorder** / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **235/50R18**

R: **235/50R18**

BS / DUN / EXNOVA / GY / FS / LIZA **MIC** / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. **06** mm R/Bal. **06** mm

L/Bal. **06** mm L/Bal. **06** mm

D.O.A. **19/12/2022** D.O.I. **20/12/22**

Survey held at **HD Perfect**

Des. of Damages: Frt / **Rear** / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Ergo
20/2/23	Adrian confirmed LS \$7100 (red 14,654.39, 67%)
	MV:
	PV:
	Nett:

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 2/3/23-typist

Days Of Repair: - 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

8 + RS. \$

Photos

Others

A & C Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

Report Form: Merimen

LS \$7100

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	20/12/2022 11:24 (SGT)
Reported by	Both
Date of Accident	19/12/2022 12:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	JUNCTION OF SUNGAI TENGAH ROAD AND OLD CHOA CHU KANG ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNA6378A
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LIU HONG MEI
NRIC No	SXXXX005H
Email Address	6hongmei@gmail.com
Mobile Phone No	(Phone) +65-93722365
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Outlander
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2360

INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	SP2003036639-01

DRIVER

Name of Driver	LIU HONG MEI
NRIC No	SXXXX005H
Date Of Birth	26/01/1976

Occupation	Indoor
Date Of Driving Pass	26/08/2003
Driving experience	19 YEARS AND 4 MONTHS
Gender	Female
Mobile Number	(Phone) +65-93722365
Alt. Phone Number	-
Email Address	6hongmei@gmail.com
Address	12 JALAN ASAS
Address complement	-
Postcode	678772
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE2641B
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-

Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

CITY AUTO PTE LTD
Blk 8 Sin Ming Road
#01-58/60/62 Sin Ming Ind Est
Singapore 575643
Tel: 6453 1235 Fax: 6453 7944
(Claims Section)
Witnessed by Reporting Centre
Personnel

刘红梅
Policyholder's Signature / Date & Time

刘红梅
Driver's Signature (If driver is not the policyholder) / Date & Time

Sketch Plan



Describe Circumstances of the Accident

Refer to Attached

Declaration

I/We declare the foregoing particulars are true in every respect

刘红梅
Policyholder's Signature / Date & Time

刘红梅
Driver's Signature (If driver is not the policyholder) / Date & Time

CITY AUTO PTE LTD
51x 8 Sin Ming Road
#01-53/50/52 Sin Ming Ind Bldg
Singapore 575543
Tel: 6453 1235 Fax: 6453 7944
(Claims Section)

Witnessed by Reporting Centre
Personnel

On 19.12.2022 at about 12:00 hours at Junction of Sungai Tengah Road and Old Choa Chu Kang Road, I was travelling straight on lane 3 (along Sungai Tengah Road towards Brickland Road) and when the traffic light turned amber from green, I slowed down and stopped my vehicle (A).

Suddenly, I heard a loud bang and felt a great impact from behind. When I alighted, I then realised it was vehicle (B) that collided onto the rear portion of my vehicle (A).

Vehicle (A): SNA 6378A

刘红梅

Vehicle (B): XE 2641B