

Our Job Ref No : 305539963

Date : 22/12/22

**COMFORTDELGRO**  
**ENGINEERING**

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

**FINALIZATION FORM**

To : LKK

Fax :

Attn : Mr Naz

Vehicle Reg No. : SH7177K

17.12.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **INCOME** -- **SKP313H**
2. The finalized amount shall be:
  - (a) Spare Parts after List discount
  - (b) Labour Charges
  - Total for Part-By-Part Repair Cost** **\$0.00**
  - (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20% **\$2,350.00**  
**Final Lumpsum Repair cost** **\$2,350.00**
3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 

Name : Ms. Loke YY

Tel : 62148355

Fax : 65468156

Signature : 

Name : Naz LKK

Date : 9/1/2023

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

## COMFORT TRANSPORTATION PTE LTD

**REPAIR ESTIMATE**

Vehicle No. : SH7177K

Date: 19.12.2022

Make : HYUNDAI

Insurance: INCOME

Model : IONIQ(G3)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT BUMPER			\$ 481.10
1	FRT BUMPER MOULDING CENTRE UPPER			\$ 368.50
10	FRT BUMPER CLIPS			\$ 22.00
1	HEADLAMP RH			\$ 2,110.30
1	FENDER EMBLEM BLUE-DRIVE RH			\$ 26.60
1	FRT WHEEL HUB CAP RH			\$ 346.40
	<b>SUB TOTAL</b>			\$ 3,354.90
	<b>LESS 20%</b>			\$ 670.98
	<b>DISCOUNTED TOTAL</b>			\$ 2,683.92
	<b>RENEW ADVERTISEMENT STICKER</b>			\$ 100.00
				\$ 100.00
	<b>Labour Charge</b>			
	PANEL BEATING			\$ 550.00
	SPRAY PAINTING CHARGE			\$ 600.00
	CHECK ALL LIGHTING			\$ 60.00
	<b>TOTAL LABOUR</b>			\$ 1,150.00
	<b>Emblem-Blue Drive (LH/RH)</b>			
	<b>ESTIMATE TOTAL</b>			\$ 3,933.92

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NA2 LKK  
 (19/12/2022) 1806  
 L/S  
 2 DAY  
 AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: