

Our Job Ref No : 305539943
Date : 22/12/22

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : Mr Naz
Vehicle Reg No. : SH7686H

Fax :

15.12.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: INCOME -- SJG1337S
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost** \$0.00
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$1,400.00
Final Lumpsum Repair cost \$1,400.00


3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed If there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : Ms. Loke YY
Tel : 62148355
Fax : 65468156

Signature : 
Name : NAZ LKK
Date : 9/1/2023

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SH7686H

Date: 19/12/2022

Make : Toyota

Insurance: INCOME

Model : Prius

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			\$ 586.18
1	FRONT BUMPER SIDE BRACKET LH			\$ 82.30
10	FRONT BUMPER CLIPS			\$ 22.00
1	HEADLAMP LH			\$ 2,735.28
1	FOG LAMP LH			\$ 920.00
SUB TOTAL				\$ 4,345.76
LESS 25%				\$ 1,086.44
DISCOUNTED TOTAL				\$ 3,259.32
				\$ -
Labour Charge				
PANEL BEATING				\$ 400.00
SPRAY PAINTING CHARGE				\$ 300.00
CHECK ALL LIGHTING				\$ 60.00
TOTAL LABOUR				\$ 760.00
ESTIMATE TOTAL				\$ 4,019.32

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NA2 LKK
19/12/2022 1750
L1
2 DAY
CHECK ITEM PHOTO
AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: