

Date/Time: 19.12.2022 15:44

Page : 1

Job: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 5465372

JC NO 305540154

Customer:

Company: COMFORT TRANSPORTATION PTE LTD

Customer NO: 7010045

Address: 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

Document NO.

REGN NO.:

SH 7830H

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE/TIME IN

19.12.2022 13:00

YR OF MANU.

23.06.2016

TARGET DATE

CHASSIS CODE

KMHLB41UMGU091480

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 16.12.2022

Accident Time: 3P.16.12.22

Job NO

LABOR CODE

DESCRIPTION



Job KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Damage Report Slip

Exit Pass

Job: SH 7830H

JU INCOME

Vehicle No.:

SH 7830H

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard