

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305540154
 REGN NO : SH 7830H
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 23.06.2016
 DATE/TIME IN : 19.12.2022 13:00
 ACCIDENT DATE : 16.12.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0595-G	PANEL ASSY-RR DR RH#	1	2,416.80	20.00	1,933.44	X R
0002 04-01-0103-0658-G	CAP ASSY-WHEEL HUB	1	217.20	20.00	173.76	✓ SCR
0003 28-01-0103-0003-A	FRT DOOR LOGO SONATA CTPL	1 N	75.00	10.00	67.50	✓ NEL
0004 28-01-9999-2032-A	ZIG BOOK NOW APP LOGO REA	1 N	80.00	10.00	72.00	✓ NEL

SUB-TOTAL : 2,246.70

JOB NATURE

0000 PB	PANEL BEATING	900.00	840
0001 SP	SPRAYPAINT CHARGE	1200.00	950
0002 L	TRANSFER DOOR PARTS	120.00	X N J

SUB-TOTAL : 2,220.00

TOTAL : 4,466.70

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

NAZ CLK
 19/12/2022 1833
 LLS
 3 Days
 AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: