

Our Job Ref No : 305540154

Date 22.12.22

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508989
Fax: 6546 8156**FINALIZATION FORM**

To : LKK

Fax :

Attn : Mr NAZ

Vehicle Reg No. SH7830H

Date of Accident : 16.12.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill 703A INCOME --- SJC8339L
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$1,700.00
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 62148315

Fax : 65468156

Signature : 

Name : NAZ

Date : 9/1/2023

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	NO		
3. Survey Fees	---	---		
LTA Search Fee	\$7.49 / \$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305540154
 REGN NO : SH 7830H
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 23.06.2016
 DATE/TIME IN : 19.12.2022 13:00
 ACCIDENT DATE : 16.12.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0595-G	PANEL ASSY-RR DR RH#	1	2,416.80	20.00	1,933.44	XR
0002 04-01-0103-0658-G	CAP ASSY-WHEEL HUB	1	217.20	20.00	173.76	SR
0003 28-01-0103-0003-A	FRT DOOR LOGO SONATA CTPL	1 N	75.00	10.00	67.50	NEL
0004 28-01-9999-2032-A	ZIG BOOK NOW APP LOGO REA	1 N	80.00	10.00	72.00	NEL

SUB-TOTAL : 2,246.70

JOB NATURE

0000 PB	PANEL BEATING	900.00	840
0001 SP	SPRAYPAINT CHARGE	1200.00	950
0002 L	TRANSFER DOOR PARTS	120.00	82.50

SUB-TOTAL : 2,220.00

TOTAL : 4,466.70

MVA NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

NAZ CLK

19/12/2022 1833

LIS

3 Days

AFTER REPAIR PHOTO

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: