



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22012762/Avy3m4 Date: 28/02/2023 Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLV 2251X	Veh. Inspected	SLB 1039E	
Policy No.	D22MTPV01011933	Coverage (\$)	0.00	
Claim No.	CMTD2204679/SYH	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	21/12/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN X-TRAIL	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JN1JANT32Z0001517	Colour	WHITE	
Odometer	158370 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/60 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	225/60 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/60 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/60 R18	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	20/12/2022	Inspection Date	21/12/2022	
Survey held at	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	