

T K LEE AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

Email: Tklee0247@gmail.com

Vehicle Number: SMN9578M

Vehicle Model: KIA CERATO

Not Adhered
der
21/12/22
4/s \$ 3700
4 days

PARTICULAR	AMOUNT
QTY	S\$

LIST PRICE

1	1	FRONT BUMPER	cur/To. n	\$	686.00	✓
2	2	FRONT BUMPER SIDE RETAINER RH/LH@38.00	11	\$	76.00	X
3	1	FRONT FENDER RH	20/surf	\$	486.00	✓
4	1	FRONT FENDER INNER SHIELD RH	11	\$	132.00	X
5	1	FRONT SHOCK ABSORBER RH	11	\$	426.00	X
6	1	FRONT SHOCK ABSORBER TOP MOUNT	11	\$	189.00	X
7	1	FRONT LOWER ARM	surf	\$	396.00	✓
8	1	FRONT KNUCKLE ARM	surf	\$	415.00	✓
9	1	FRONT WHEEL HUB BEARING	20/ye	\$	432.00	✓
10	1	FRONT ANIT ROLL BAR	11	\$	226.00	X
11	1	FRONT ANIT ROLL BAR LINK	11	\$	89.00	X
12	1	FRONT HEADLAMP RH	11	\$	1,895.00	X
				\$	5,448.00	
				LESS 10%	\$	544.80
					\$	4,903.20

SPECIAL NETT ITEMS

1	1	FRONT BUMPER LOWER SPOILER	cur/oe	\$	850.00	✓
2	1	(SET) FRONT BUMPER CLIP	der	\$	45.00	✓
3	1	FRONT WHEEL	cur	\$	550.00	400
4	1	FRONT TYRE	8u	\$	250.00	X
				\$	1,695.00	

LABOUR CHARGES

TO CHECK ELECTRICAL WIRING	\$	40.00	20
TO REMOVE AND REAPLCE FRONT UNDERCARRIAGE PARTS	\$	300.00	120
TO PERFORM 4 WHEEL ALIGHTMENT	\$	120.00	100
TO TUFF KOTE	\$	50.00	30
TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	\$	800.00	300
TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	\$	800.00	600
		\$	2,110.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL :

\$ 8,708.20

p-2415

LKK Auto Consultants hence notify
the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMPUTERISED 4 WHEEL ALIGNMENT HUNTER DSP700

Company: T K LEE AUTOMOTIVE P/L
VIN: SMN 9578 M
Date: 20.12.22 13:05



SMN 9578 M

Kia : Cerato/Forte : 2013-19 (YD/YDm)

Front : Left

Actual	Before	Specified Range
-0°42'	-0°42'	-0°52' 0°08'
4°20'	4°20'	3°31' 4°31'
-0°07'	-0°07'	-0°03' 0°09'
15°40'	15°41'	13°06' 14°06'
14°58'	14°58'	12°14' 14°14'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-1°15'	-1°15'	-0°52' 0°08'
3°54'	3°54'	3°31' 4°31'
-0°10'	-0°10'	-0°03' 0°09'
11°55'	11°55'	13°06' 14°06'
10°40'	10°40'	12°14' 14°14'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°33'	0°32'	
0°27'	0°27'	
3°45'	3°45'	
-0°17'	-0°17'	-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-1°43'	-1°43'	-2°00' -1°00'
0°06'	0°06'	0°00' 0°27'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°24'	-1°25'	-2°00' -1°00'
0°08'	0°08'	0°00' 0°27'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°18'	-0°18'	
0°15'	0°15'	0°00' 0°54'
-0°01'	-0°01'	

COMPUTERISED 4 WHEEL ALIGNMENT HUNTER DSP700

Company: T K LEE AUTOMOTIVE P/L
VIN: SMN 9578 M
Date: 23.12.22 11:29



Kia : Cerato/Forte : 2013-19 (YD/YDm)

Front : Left

Actual	Before	Specified Range
-0°22'	-0°22'	-0°52' 0°08'
4°15'	4°15'	3°31' 4°31'
0°01'	0°01'	-0°03' 0°09'
20°44'	20°44'	13°06' 14°06'
20°22'	20°22'	12°14' 14°14'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°15'	-0°15'	-0°52' 0°08'
4°01'	4°01'	3°31' 4°31'
0°01'	0°01'	-0°03' 0°09'
6°17'	6°17'	13°06' 14°06'
6°02'	6°02'	12°14' 14°14'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°07'	-0°07'	
0°15'	0°15'	
14°27'	14°27'	
0°02'	0°02'	-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-1°42'	-1°42'	-2°00' -1°00'
0°11'	0°11'	0°00' 0°27'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°23'	-1°23'	-2°00' -1°00'
0°10'	0°10'	0°00' 0°27'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°19'	-0°19'	
0°21'	0°21'	0°00' 0°54'
0°00'	0°00'	