

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |  |   |                 |            |                       |  |
|---|--|---|-----------------|------------|-----------------------|--|
|   | LIBERTY INSURAN  | NCE PTE LTD   | Ī               | Ref:       | CS/LIP22012779/Aqy3e2 |  |
|   | 51 CLUB STREET,<br>LIBERTY HOUSES  | I   | Date:           | 22/03/2023 |                       |  |
|   |  |   | (               | Code:      | LIP                   |  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM  |   |                 |            |                       |  |
|   | Insured Veh.   | SLX 1008D   | Veh. Inspected  |            | SJF 6415Y             |  |
|   | Policy No.   |   | Coverage (\$)   |            | 0.00                  |  |
|   | Claim No.  | IVS22/2216  | Excess (\$)     |            | 0.00                  |  |
|   | Assign From  | TED SEAH  | Assign Date     |            | 22/12/2022            |  |
| 2. Vehicle Particulars & Condition                                |  |   |                 |            |                       |  |
|   | Make & Model   | HONDA FIT   | c.c             |            | 1339                  |  |
|   | Engine No.   | HIDDEN  | Year of Reg.    |            |                       |  |
|   | Chassis No.  | GE61080042  | Colour          |            | BLUE                  |  |
|   | Odometer   | 221529 KM   | Steering        |            | IN ORDER              |  |
|   | Brakes   | IN ORDER  | Modification    |            | SPORTS RIM            |  |
|   | General  | GOOD  |                 |            |                       |  |
| 3. Conditions of Tyres  |  |   |                 |            |                       |  |
|   |  | Size  | Make            |            | Balance               |  |
|   | R/H Front Tyre   | 195/55 R15  | CHAMPIRO        |            | 6 mm                  |  |
|   | L/H Front Tyre   | 195/55 R15  | CHAMPIRO        |            | 6 mm                  |  |
|   | R/H Rear Tyre  | 195/55 R15  | CHAMPIRO        |            | 6 mm                  |  |
|   | L/H Rear Tyre  | 195/55 R15  | CHAMPIRO        |            | 6 mm                  |  |
| 4.  | Description of Damages   |   |                 |            |                       |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.   |   |                 |            |                       |  |
|   | DAMAGES SEE DETAILS.   |   |                 |            |                       |  |
| 5.  | General Information  |   |                 |            |                       |  |
|   | Accident Date  | 20/12/2022  | Inspection Date | )          | 22/12/2022            |  |
|   | Survey held at   | AUTO UNITED SG PTE LTD  |                 |            |                       |  |
|   |  | 13 KAKI BUKIT ROAD 4,<br>#03-29, BARTLEY BIZ CENTRE, SINGAPORE 417807 |                 |            |                       |  |
| 5a.   | . Remarks  |   |                 |            |                       |  |
|   | A)REGISTRATION DATE: 05 JUN 2008<br>B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                 |            |                       |  |
| 5b.   | Estimate Days of Repair  |   |                 |            |                       |  |
|   | ESTIMATED NORM   | ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days                    |                 |            |                       |  |