



Your Ref: 202222009048/JK

Date: 12th May 2023

Our Ref: CS6/AIS22012786/Twy3e2

M/s Allianz Insurance Singapore Pte Ltd

79 Robinson Road #09-01

Singapore 068897

Dear Sir / Madam,

DESKTOP SURVEY OF ACCIDENT VEHICLE SML 7704P ACCIDENT ON 20/12/2022

We thank you for your instruction on 22/12/2022.

The following vehicle information was recorded:

Registration Number	: SML 7704P
Make & Model	: Opel Insignia Grand Sport
Chassis Number	: W0VZM6EF0K1035006
Year of Registration	: 2019
Engine Capacity	: 1598 cc

1. The vehicle sustained damages at the front portion. (Details see photographs enclosed)
2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.