

ASS. REC. BY:

REF:

AIG/ 22012805/KP

- 128GB 550

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SLH3851T

Yr Regn:

11.15

Type: M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

c.c

1496

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

109875

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RU1

1102749

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

20/12/22

Rear

R/Bal.

4

mm

L/Bal.

4

mm

D.O.I.

28/12/2022

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. SI

Fees

Others

TOTAL

Add Fee:

Site Insp (\$

Interview (\$

Tech Invs (\$

Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M/s : **AIG Asia Pacific Insurance Pte. Ltd**
78, Shenton Way,
#11-16, Singapore 079120

Estimate bill : TT 47 / 22 / TP / WT

Registration No : SLH5851T

Make / model : Honda Vezel

Attn : Motor Claims Department
Tel : 64193000
Fax : 62256772

Not Authorised
11 Day @
Puttying New Paint
3 days

Mileage :

Date : 22 / 12 / 2022

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SMK5861L AND SLH5851T ALONG SLE HEADING TOWARDS CTE BEFORE THOMSON ROAD ON 20 DECEMBER 2022 AT ABOUT 1857HRS.

1pc	Rear boot		\$	16,129.00	✓
1pc	Rear boot 'Vezel' designation		\$	76.00	✓
2pcs	Rear boot hinge		\$	190.00	X
1pc	Rear bumper	(Each \$95.00)	\$	486.00	✓
1set	Rear bumper parking sensor kit		\$	280.00	2001
	Sub A total :		\$	17,161.00	
	Less 20% discount :		\$	3,432.20	
	A total :		\$	13,728.80	

Remove and transfer rear boot necessary attachment spart part items.

Remove and transfer rear bumper necessary attachment spart part items.

Remove and refit rear boot, rear boot 'Vezel' designation, rear boot hinges, rear bumper, rear bumper parking sensor kit.

Heat / weld / beating / pull / straighten / align rear chassis frame by Chassis Alignment jack.

Diagnostic and reset rear bumper parking sensor fault error by HHT

To check and refit rear tail lamp wiring harness.

Under coating on rear damaged portion.

Putty / primer application, spray painting rear boot, rear boot hinges, rear bumper, rear bumper parking sensors kit.

400
\$ 600.00
80.00 50
80.00 150
200.00 300
2200
\$ 900.00

Tropical Tech Automobile Services


(Authorised Signature)
William Tan



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


Acknowledged by Repairer

Signature:

Date.

Date of accident: 20 Dec 2022 Time: 3:50 PM Location: 9 towards ITE
My Vehicle A: SLE 5051 Vehicle B: SLE 5051 Vehicle C:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 20th December 2022, along SLE (before Harrison Road exit). I stopped my car due to traffic. The car behind did not stop in the time and hit the rear of my car.

☐ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☒ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop:

Email address:

& myself:

Email address:

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Ah Lim Motor Company
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

AH LIM MOTOR COMPANY

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 21/12/2022 14:21 (SGT)
Reported by Both
Date of Accident 20/12/2022 18:57 (SGT)
Exact Location of Accident SLE, Singapore
Additional Location Information SLE TWDS CTE BEFORE THOMSON RD
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLH5851T

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner LAU KUAN SENG JONATHAN
NRIC No SXXXX383H
Email Address JONATHANLAUKS@GMAIL.COM
Mobile Phone No (Phone) +65-94779498
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Honda
Model Vezel
Variant VEZEL 1.5X A
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Reporting only
Vehicle Category Private car
Transmission Auto
CC 1496

INSURANCE COMPANY

Name of Insurance Company FWD Singapore Pte. Ltd.
Policy Number / Cover Note Number PNPV2022-00003539

DRIVER

Name of Driver LAU KUAN SENG JONATHAN
NRIC No SXXXX383H
Date Of Birth 20/04/1987
Occupation Indoor

