

ASS. REC. BY: Tan Min

REF: CS/CT122012817/IVY3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: DMPCSNW00120022201

Claims No: SNM22D209113/C01/TANCHC

Sum Insured: _____ Excess: \$500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$115K.

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMW4590L Yr Regt: 2019, Nov.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: BMW 216i Gran Tourer cc 1499

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 29534 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA6V120705W97663

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modl: Nil / STD A/Rim or _____

Tyre Size: F: 205/55R17

R: 7-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 17/12/2022

Survey held at: Performance Motor

Des. of Damages: Fit / Rear / O/S / N/S / UIC / Rooftop or

Fit N/S.

The UIC / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Date / Time	Action / Instruction
17/4/23	Final fig \$10,806.65 confirmed by email (Red 9955.45, 47%)

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? 2) 17/4/23-typist

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Test. mvs (\$ _____)

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

Report Formed: Merimen

Lum Sum / F.B. / F. \$10,806.65

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
 Toll-Free Number (1800-2255269)



303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64756601 (AfterSales)
 64756624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 64465 Date Estimated : 22/12/2022 Prepared By : Inthiran A/L Thurasamy	Page No. : 1 of 5
--	-------------------

- ESTIMATE REPAIR FOR - Soh Sim Karn 235 Tembeling Rd #04-03 Singapore 423720	- ACCOUNT - 135 China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMW4590L	WBA6V120705N97663	21/11/2019	216i Gran Tourer	26680

DESCRIPTION	VALUE
To replace front bumper, support left, reinforcements, attachments and make good of bonnet and front left door.	1700 5,100.00
To painting front bumper, fender left, bonnet and front left door.	1972 4,412.00
To check electrical wiring system at the front section for proper function including adjustment of headlights.	168 177.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168 177.00
To replace left or right headlight.	AS7 481.00
To carry out body cavity preservation. (Per panel).	112 118.00
Sundries.	? 150.00

Total Labour 1: **10,615.00**

DESCRIPTION	QTY	PRIC	VALUE
FRT LH FENDER	1	639.70	bt 639.70
LH EXTENSION WHEEL HOUSING STRUT	1	173.00	? 173.00
LH CROSS SUPPORT SIDE PANEL	1	33.10	? 33.10
LH FOG LAMP SUPPORT	1	80.55	? 80.55
LH MOULDING (LUXURY)	1	69.15	? 69.15
LH FINISHER	1	53.30	at 53.30
FRT BUMPER PRIMED PANEL (PMA)	1	950.80	de 950.80
LH GRID LATERAL (LINES/PDC)	1	96.95	cut 96.95
GROMMET	2	0.80	rel 1.60
LH SUPPORT HEADLIGHT ARM	1	78.50	? 78.50
FRT LH WHEEL ARCH COVER	1	138.40	? 138.40
LH AIR DUCT DISPLACED RADIATOR	1	72.65	? 72.65
PLAQUE 82MM	1	72.85	rel 72.85

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
 Toll-Free Number (1800-2255269)

303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64798601 (AfterSales)
 64798624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Page No. : 2 of 5

Estimate No. : b1 64465
 Date Estimated : 22/12/2022
 Prepared By : Inthiran A/L Thurasamy

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMW4590L	WBA6V120705N97663	21/11/2019	216i Gran Tourer	26680

Total Parts : 2,460.55

Tanflm 9745749
 Not advise Rent.
 23/12/22 @ 1145
 Ex: \$500
 Resurvey before paint
 - 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



Labour 1	:	10,615.00
Parts	:	2,460.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	915.29
Grand Total	:	13,990.84

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
 ** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Actual Driver**
3. Information provided must be as truthful and accurate as possible. Any **wilful misrepresentation or withholding of material facts** may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	19/12/2022 14:51 (SGT)
Reported by	Both
Date of Accident	17/12/2022 23:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	SLIP ROAD PIE EXIT TO EUNOS
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMW4590L
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	SOH SIM KERN
NRIC No	SXXXX905E
Email Address	victorsohsk@yahoo.com
Mobile Phone No	(Phone) +65-81261604
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	BMW
Model	216i
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1499

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMPCSNW00120022201

DRIVER

Name of Driver	SOH SIM KERN
NRIC No	SXXXX905E
Date Of Birth	28/05/1973
Occupation	Indoor

Date Of Driving Pass	27/01/1994
Driving experience	28 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-81261604
Alt. Phone Number	-
Email Address	victorsohsk@yahoo.com
Address	235 TEMBELING ROAD #04-03
Address complement	-
Postcode	423720
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	SOH GUAN SHUN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACH

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD4646U
Vehicle Manufacturer	Hyundai
Vehicle Model	Ioniq
Vehicle Variant	-

Vehicle Colour
Vehicle Category
Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

Blue
Taxi
BALDEV SINGH
(Phone) +65-90588800
BLK 346 UBI AVE 1 #03-1075
-
400346
-
REAR
-
5

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any inquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information to be collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time: 19-Dec-2022
 12:21 p.m.


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 19-Dec-2022
 12:21 p.m.


 Reporting Centre Person's Signature
 Name:
 NRIC / ID No: