

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKE 10883

at Workshop m/s Volkswagen

of 2017 Volkswagen RS

Insured: CTI

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

11AM

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 126K

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SKE 10883 Yr Regn: 2019 7 Auk

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: SKODA OCTAVIA RS 2.0 TSI c.c. 1984

Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: 60279 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: TMDBM TNE 2K0 161 365

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NH / S/Rim / STD A/Rim or

Tyre Size: F: 225/40ZR18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 21/12/22 D.O.I. 21/12/22

Survey held at Volkswagen

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 78K

Date/Time, File Pass to?

: Preli. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Photos

Others

Report Format :

Lump Sum / I.B.I.: (\$ \_\_\_\_\_)

# ŠKODA Centre Singapore

26 Leng Kee Rd  
Singapore 159104  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation

Non binding - Preview

Page 1/3

Company  
CHINA TAIPING INSURANCE (S) PL  
3 ANSON ROAD  
#18-00 SPRINGLEAF TOWER  
Singapore 079909

Customer Details:  
Ms.  
GOH  
SOR ENG  
MRS JENNIFER HONG  
9 ALNWICK ROAD  
Singapore 559963

Document no.  
Document date 22-12-2022  
Customer no. 5211001170  
Customer GST-ID 200208384E  
Dealer 30001  
Job order number 2022037192/ 1  
Job order date 21-12-2022  
Service Advisor Dass Anthonidas  
Christopher

License plate	Model code	First registration	VIN	Model	Mileage
SKE1088J	5E36UDR1	27-08-2019	TMBBU7NE2K0161365	Octavia RS 2.0 I TSI 180kW DSG	38,828

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
9801B003	B&P WHEEL ALIGNMENT				#1	360.00	385.20
9801B001	R&R RIM & BALANCE				#1	50.00	53.50
9801B001	R&R RHR U/CARRIAGE <i>? photo?</i>				#1 <i>840</i>	2,520.00	2,696.40
5E0821106C	Fender	1	pcs.	767.75	#1	767.75	821.49
	RHS FRT FENDER <i>? repair</i>						
N 90959602	Rivetted Cap Nut <i>X</i>	4	pcs.	2.64	#1	10.56	11.30
5E0809958E	Wheelhouse <i>X</i>	1	pcs.	194.61	#1	194.61	208.23
	RHS FENDER LINER <i>??</i>						
5E0831056A	Unbekannt <i>??</i>	1	pcs.	2,879.34	#1	2,879.34	3,080.89
	RHS FRT DOOR <i>??</i>						
5E0837698C	Door Seal <i>ac</i>	1	pcs.	85.59	#1	85.59	91.58
D 378500A2	Alu-Lamin. Insulation	1	pcs.	43.65	#1	43.65	46.71
	DOOR INSULATOR <i>??</i>						
N 90263103	Unbekannt <i>??</i>	4	pcs.	0.53	#1	2.12	2.27
	RIVET NUT <i>??</i>						
WHT002541	Hexagon Socket Flat Head <i>ac</i>	2	pcs.	1.98	#1	3.96	4.24
5E0853814D TQ3	Molding Fo	1	pcs.	245.67	#1	245.67	262.87
	RHS FRT SCUFF PLATE <i>??</i>						
5E5809602C	Sectional	1	pcs.	1,134.51	#1	1,134.51	1,213.93
	ROCKER PANEL RH <i>??</i>						
D 506KD1A4	2k-Insert Foam <i>ac</i>	1	pcs.	163.23	#1	163.23	174.66
D 476KD1M2	Sealant Can Be Sprayed <i>ac</i>	1	pcs.	66.78	#1	66.78	71.45
D 007500A2	Zinc Spray <i>ac</i>	1	pcs.	72.86	#1	72.86	77.96
D 180003M2	2k-Body Adhesive <i>ac</i>	1	pcs.	469.52	#1	469.52	502.39
D 314D36M2	Long-Life Underseal <i>ac</i>	1	pcs.	92.69	#1	92.69	99.18
5E0000279	Unbekannt	1	pcs.	239.78	#1	239.78	256.56
	STICKER ( CHASSIS NO ) <i>ac</i>						
5E0807906B	FOIL	1	pcs.	44.93	#1	44.93	48.08
	RHR FENDER FOIL <i>ac</i>						
5E5833056B	Unbekannt	1	pcs.	2,879.34	#1	2,879.34	3,080.89
	RHS REAR DOOR <i>? repair</i>						
D 378500A2	Alu-Lamin. Insulation	1	pcs.	43.65	#1	43.65	46.71
	DOOR INSULATOR <i>??</i>						
5E5839698C	Door Seal <i>X</i>	1	pcs.	103.06	#1	103.06	110.27
5E0839717B 5AP	Door Seal <i>X</i>	1	pcs.	72.78	#1	72.78	77.87
	RHR DOOR SEAL ( SIDE ) <i>??</i>						
N 90263103	Unbekannt	4	pcs.	0.53	#1	2.12	2.27
	RIVET NUT <i>??</i>						
WHT002541	Hexagon Socket Flat Head <i>X</i>	2	pcs.	1.98	#1	3.96	4.24
5E0601025AJHA7	Alloy Whee <i>??</i>	1	pcs.	1,465.00	#1	1,465.00	1,567.55
311601361	Rubber Valve <i>ac</i>	1	pcs.	3.85	#1	3.85	4.12
5Q0501529F	Tie Rod <i>?</i>	1	pcs.	139.18	#1	139.18	148.92

# ŠKODA Centre Singapore

26 Leng Kee Rd  
Singapore 159104  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation

Non binding - Preview

Page 2/3

Company  
CHINA TAIPING INSURANCE (S) PL  
3 ANSON ROAD  
#18-00 SPRINGLEAF TOWER  
Singapore 079909

Customer Details:  
Ms.  
GOH  
SOR ENG  
MRS JENNIFER HONG  
9 ALNWICK ROAD  
Singapore 559963

Document no.  
Document date  
Customer no.  
Customer GST-ID  
Dealer  
Job order number  
Job order date  
Service Advisor  
22-12-2022  
5211001170  
200208384E  
30001  
2022037192/ 1  
21-12-2022  
Dass Anthonidas  
Christopher

License plate	Model code	First registration	VIN	Model	Mileage
SKE1088J	5E36UDR1	27-08-2019	TMBBU7NE2K0161365	Octavia RS 2.0 TSI 180kW DSG	38,828

  

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
N 10628301	Bolt Hex. Hd. With Should	1	pcs.	10.10	#1	10.10	10.81
N 10106402	Shouldered Hex. Nut Self-	1	pcs.	3.60	#1	3.60	3.85
N 10640301	Bolt Hex. Hd. With Should	1	pcs.	11.07	#1	11.07	11.84
N 10286110	Shouldered Hex. Nut Self-	2	pcs.	3.38	#1	6.76	7.23
N 10776501	Hexagon Flange Screw	2	pcs.	5.62	#1	11.24	12.03
N 90183803	Shouldered Hex. Nut Self-	2	pcs.	3.38	#1	6.76	7.23
5Q0505224D	Trailing Arm	1	pcs.	340.42	#1	340.42	364.25
N 10769501	Screw Hex. Hd. ?	1	pcs.	11.33	#1	11.33	12.12
WHT005749	Fitted Bolt Hex. Head ?	2	pcs.	9.05	#1	18.10	19.37
N 90648402	Bolt Hex. Hd. ?	4	pcs.	6.02	#1	24.08	25.77
5WF501611	Unbekannt WHEEL BEARING }?	1	pcs.	509.74	#1	509.74	545.42
WHT007150	Bolt ?	1	pcs.	11.33	#1	11.33	12.12
1J0501249C	Cap ?	1	pcs.	9.46	#1	9.46	10.12
5QA505434B	Wheel Bearing Housing ?	1	pcs.	762.91	#1	762.91	816.31
1K0505553A	Bonded Rubber Mounting ?	1	pcs.	31.73	#1	31.73	33.95
N 10640501	Bolthex.Hd.With Shoul. ?	1	pcs.	9.53	#1	9.53	10.20
N 10106402	Shouldered Hex. Nut Self- ?	1	pcs.	3.60	#1	3.60	3.85
N 91197801	Bolt Hex. Hd. ?	1	pcs.	9.62	#1	9.62	10.29
N 10401801	Shouldered Hex. Nut ?	1	pcs.	6.02	#1	6.02	6.44
5Q0505323C	Track Control Arm RHR UPPER ARM }?	1	pcs.	325.56	#1	325.56	348.35
WHT000227	Eccentric Screw }?	1	pcs.	17.97	#1	17.97	19.23
N 10106402	Shouldered Hex. Nut Self- ?	1	pcs.	3.60	#1	3.60	3.85
5Q0505311J	Track Control Arm RHR LOWER ARM }?	1	pcs.	294.48	#1	294.48	315.09
WHT000228	Eccentric Screw ?	1	pcs.	18.54	#1	18.54	19.84
N 10106402	Shouldered Hex. Nut Self- ?	1	pcs.	3.60	#1	3.60	3.85
N 10628301	Bolt Hex. Hd. With Should ?	1	pcs.	10.10	#1	10.10	10.81
N 10106402	Shouldered Hex. Nut Self- ?	1	pcs.	3.60	#1	3.60	3.85
VWLM3318	DEGREASER CLEANER 500ml ?	1	pcs.	18.80	#1	18.80	20.12
	LABOUR		pcs.	840.00	#1	840.00	7,190.40
	SPRAY PAINT		pcs.	800.00	#1	800.00	5,992.00
	TRANSFER DOOR MECHANISM		pcs.	840.00	#1	840.00	1,797.60
	CHINA TAIPING DIRECT						
	DOA:21/12/2022						
	TP VEH NO:SML5983M						
	SURVEY BY:						

Quotation valid till 28-12-2022

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	3,690.00	27,724.14	7%	2,198.99	31,414.14	33,613.13
Total	3,690.00	27,724.14		2,198.99	31,414.14	33,613.13

Handwritten notes:  
 - Front Fender - Repair - Front Panel Replanned  
 - Seal Door - Replaced  
 - Rear Door - Repair - Rear Fender Spray Paint (Repair)

# SKODA Centre Singapore

26 Leng Kee Rd  
Singapore 159104  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation

Non binding - Preview

Page 3/3

Company  
CHINA TAIPING INSURANCE (S) PL  
3 ANSON ROAD  
#18-00 SPRINGLEAF TOWER  
Singapore 079909

Customer Details:  
Ms.  
GOH  
SOR ENG  
MRS JENNIFER HONG  
9 ALNWICK ROAD  
Singapore 559963

Document no.  
Document date  
Customer no.  
Customer GST-ID  
Dealer  
Job order number  
Job order date  
Service Advisor  
22-12-2022  
5211001170  
200208384E  
30001  
2022037192/ 1  
21-12-2022  
Dass Anthonidas  
Christopher

License plate SKE1088J	Model code 5E36UDR1	First registration 27-08-2019	VIN TMBBU7NE2K0161365	Model Octavia RS 2.0 I TSI 180kW DSG	Mileage 38,828
---------------------------	------------------------	----------------------------------	--------------------------	---	-------------------

Customer

*Amis*  
Service Advisor

---VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).---

All invoices are denominated in SGD, unless otherwise stated.

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Rasu*  
*Hp 90010068*  
*14 days*  
*27/12/22 @ 1130*  
*Resy before part*

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Singapore NRIC  
Owner ID: 946J

Vehicle No.: SKE1088J  
Vehicle to be Exported: No  
Intended Deregistration Date: 28 Dec 2022  
Vehicle Make: SKODA  
Vehicle Model: OCTAVIA RS 2.0 TSI  
Primary Colour: Black  
Manufacturing Year: 2019  
Engine No.: DLB030833  
Chassis No.: TMBBU7NE2K0161365  
Maximum Power Output: 180.0 kW (241 bhp)  
Open Market Value: \$26,501.00  
Original Registration Date: 27 Aug 2019  
First Registration Date: 27 Aug 2019  
Transfer Count: 0  
Actual ARF Paid: \$29,102.00

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 26 Aug 2029  
PARF Rebate Amount: \$21,826.00

COE Expiry Date: 26 Aug 2029  
COE Category: B - Car above 1600cc or 97kW (130bhp)  
COE Period (Years): 10  
QP Paid: \$38,602.00  
COE Rebate Amount: \$25,713.00  
Total Rebate Amount: \$47,539.00

The information contained herein is correct as at 28 Dec 2022

OK

# Skoda Octavia 2.0A TSI RS

[Overview](#)

[Financial](#)

[Accessories](#)

[Similar](#)

[Research](#)

[Photos](#)

[Map](#)



<b>Price</b>	<b>\$126,800</b>		
<b>Depreciation</b> ⓘ	\$16,850 /yr <a href="#">View models with similar depre</a>	<b>Reg Date</b>	28-Aug-2019 (6yrs 7mths 30days COE left)
<b>Mileage</b>	48,496 km (14.5k /yr)	<b>Manufactured</b> ⓘ	2019
<b>Road Tax</b> ⓘ	\$1,194 /yr	<b>Transmission</b>	Auto
<b>Dereg Value</b> ⓘ	\$47,419 as of today (change)	<b>OMV</b> ⓘ	\$26,359
<b>COE</b> ⓘ	\$38,602	<b>ARF</b> ⓘ	\$28,903
<b>Engine Cap</b>	1,984 cc	<b>Power</b>	180.0 kW (241 bhp)
<b>Curb Weight</b> ⓘ	1,577 kg	<b>No. of Owners</b> ⓘ	2