

ASS. REC. BY:

REF:

MSG/ 220128161K

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

Res.: Yes or No

Lum Sum:

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SLT 2346S

Yr Regn:

10, 17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Volel

c.c

1496

Colour

An. Red

A/C: Insured / Std / NI / NA

Sp. Reading

121100

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

R41

1223502

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD / Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

21/12/22

D.O.I.

28/12/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Data/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

A T AUTO CONSULTANT

Blk 113 Telok Ayer Kuning Lane #05-650 Singapore 680113
HP: 8386 8989 EMAIL: atautoconsultant@gmail.com
Co. Reg. No.: 53368526E

Date of Estimate: 22.12.2022

Vehicle No: SLT2346S

Owner: YEO HWEE LIAN SOPHIA

Date of Accident: 21.12.2022

Make & Model: Honda Vezel

Chassis No: RU11223502

ESTIMATE FOR ACCIDENT VEHICLE NO SLT2346S

PARTS

| | | |
|----|---|---------------------------------|
| 1 | 1 | Rear bumper |
| 2 | 2 | Rear corner panel LH/RH |
| 3 | 2 | Rear bumper side retainer LH/RH |
| 4 | 2 | Rear bumper reflector LH/RH |
| 5 | 1 | Tailgate |
| 6 | 1 | Tailgate reflector LH/RH |
| 7 | 1 | Tailgate lock |
| 8 | 1 | Tailgate inner trim |
| 9 | 1 | Tailgate windscreen seal |
| 10 | 1 | Tailgate weatherstrip |
| 11 | 1 | Tailgate emblem "VEZEL" |
| 12 | 1 | Tailgate moulding |
| 13 | 1 | Taillamp LH/RH |
| 14 | 1 | Taillamp corner panel LH/RH |
| 15 | 1 | Rear end panel |
| 16 | 1 | Rear end panel top garnish |
| 17 | 1 | Rear floor panel |
| 18 | 1 | Rear floor panel top garnish |
| 19 | 1 | Rear floor panel under cover |
| 20 | 1 | Rear tool box garnish |
| 21 | 1 | Remote key buzzer |

| | | | | |
|---|----------|--------|------------|---|
| | | Bul/No | \$1,100.00 | ✓ |
| @ | \$298.00 | Sm | \$596.00 | X |
| @ | \$59.00 | Sm | \$118.00 | X |
| @ | \$151.00 | Sm | \$302.00 | X |
| | | Sm | \$1,386.00 | ✓ |
| @ | \$412.00 | Sm | \$824.00 | X |
| | | Sm | \$339.00 | ✓ |
| | | | \$301.00 | ? |
| | | Sm | \$385.00 | ✓ |
| | | | \$321.00 | ? |
| | | Sm | \$72.00 | ✓ |
| | | Sm | \$422.00 | X |
| @ | \$467.00 | Sm | \$934.00 | X |
| @ | \$281.00 | Sm | \$562.00 | X |
| | | | \$556.00 | ? |
| | | | \$286.00 | ? |
| | | Sm | \$912.00 | X |
| | | Sm | \$378.00 | X |
| | | Sm | \$365.00 | X |
| | | Sm | \$265.00 | X |
| | | | \$87.00 | ? |

SUB TOTAL

LESS 20 %

DISCOUNTED SUB TOTAL

\$10,511.00
\$2,138.80
\$8,372.20

S. NETT ITEM

| | | |
|---|------|-----------------------------|
| 1 | 1set | Rear bumper clips |
| 2 | 1set | Reverse sensor |
| 3 | 1set | Rear number plate & garnish |
| 4 | 1 | Reverse cam |

| | | |
|----------|----------|------|
| Sm | \$50.00 | ✓ |
| Notishun | \$330.00 | 2000 |
| Sm | \$100.00 | X |
| Sm | \$180.00 | X |

SUB TOTAL

LESS 0 %

DISCOUNTED SUB TOTAL

\$660.00
\$0.00
\$660.00

LABOUR

| | |
|---|---|
| 1 | Panel beating for replace and repair affected parts |
| 2 | Spray painting on accident areas |
| 3 | Wiring charges |
| 4 | Apply undercoating to above affected areas |
| 5 | Remove/refix reverse sensor |
| 6 | Remove/refix tailgate components |
| 7 | Remove/refix tailgate windscreen |

AT Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

| | |
|------------|------|
| \$1,200.00 | ? |
| \$1,200.00 | 400 |
| \$100.00 | 150 |
| \$120.00 | 300 |
| \$50.00 | ✓ |
| \$100.00 | 600 |
| \$250.00 | 1200 |

SUB TOTAL (LABOUR)

Page 1 of Acknowledged by Repairer

Signature:

Date:

\$3,020.00

Not Authen
L1 Pay &
Money After Rain
4-5 days



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 22/12/2022 11:26 (SGT)
Reported by Both
Date of Accident 21/12/2022 17:05 (SGT)
Exact Location of Accident Tanah Merah Coast Rd, Singapore
Additional Location Information JUNCTION OF TANAH MERAH FERRY ROAD
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLT2346S

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner YEO HWEE LIAN SOPHIA
NRIC No S8605754I
Email Address sophiayeo@hotmail.com
Mobile Phone No (Phone) +65-92774612
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Honda
Model Vezel
Variant -
Exact purpose for which vehicle was being used at time of accident -
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1496

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number 2070137451-02

DRIVER

Name of Driver YEO HWEE LIAN SOPHIA
NRIC No S8605754I
Date Of Birth 22/02/1986
Occupation Indoor



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time


Actual Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan

Tanah Merah Ferry Road



A-SLT2346S

B-SKQ5974L

Date 21/12/2022

Time 1705

Tanah Merah Coast Road