

ASS. REC. BY:

REF:

CTZ/22012825/HV

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKG369U

Yr Regn:

01, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes

GLANCE

c.c

1395

Colour:

M. Gray

AC:

Insured / Std / NI / NA

Sp. Reading:

80481

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDC1569422J669113

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

233/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

22/12/2

D.O.I.

27/12/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Prell. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fines

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



# 方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.  
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

Ng Boon Kheong  
Apt Blk 604A Punggol Road  
#12-768  
Singapore 821604

*Not Authorised  
C/Sump &  
Resurvey After Paint  
5 days*

Dear sir

Estimate cost of repair to vehicle no. SKG369U

To supply

1. Front fender right	R <sub>1</sub>	991.41	✓
2. Front fender arc garish	DD / G <sub>1</sub>	218.77	✓
3. Wheel rim	L.R Part	580.12	X
4. Front door	R <sub>1</sub>	2,249.10	✓
5. Front door channel	R <sub>1</sub>	123.11	X
6. Front door rubber	R <sub>1</sub>	234.20	✓
7. Front door power motor and gear		631.68	?
8. Rocker garish	DD / G <sub>1</sub>	831.80	✓
9. Rear door	R <sub>1</sub>	1,820.10	✓
10. Rear door rubber	R <sub>1</sub>	234.20	✓
11. Rear door sticker	R <sub>1</sub>	80.00	✓
12. Door rivet 20x4.5	R <sub>1</sub>	90.00	✓
13. Rear fender arc garish	G <sub>1</sub>	229.80	✓

Labour charges

Rust proofing

Panel beating

Spray painting

Total

nn 100.00 X  
1,200.00 600  
1,000.00 660  
10,614.29

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:





# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	23/12/2022 13:06 (SGT)
Reported by	Both
Date of Accident	22/12/2022 15:30 (SGT)
Exact Location of Accident	Orchard Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKG369U
-----------------------------	---------

### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	NG BOON KHEONG
NRIC No	S7922140F
Email Address	brucengboonkheong@hotmail.com
Mobile Phone No	(Phone) +65-97321638
Alternative Phone No	-

### VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	Gla180
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1600

### INSURANCE COMPANY

Name of Insurance Company	Sompo Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	D22MTPV01000106

### DRIVER

Name of Driver	NG BOON KHEONG
NRIC No	S7922140F
Date Of Birth	04/08/1979
Occupation	Outdoor

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the **Personal Information**) and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the **Insurers**), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the **Purposes**);
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel  
(Name as in NRIC card)

SOH JIT HOON

### Sketch Plan







T/20221222/2121

2 of 4

Report No. T/20221222/2121

Of Origin:  
Bedok North Road SINGAPORE 469676  
Tel No: 1800-2449999

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKG369U	TENET SOMPO INSURANCE PTE. LTD.	D22MTPV01000106	07/01/2022	06/01/2023

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	NG BOON KHEONG	ID No.	S7922140F
Related Vehicle	SKG369U (Car)	Contact No.	97321638
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	22/12/2022	Date Discharge	22/12/2022
No. of Days granted Medical Leave	02	Degree of Injury	Slight
Driver			
Name	TAN TIANG WEE	ID No.	S7635481B
Related Vehicle	SKU6707P (Car)	Contact No.	91809524
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On the 22/12/22 at about 1530hrs I was driving along Orchard Road. I was on my way to a project site. As I approach junction between the Orchard Road and Oxley Road, suddenly I felt a big impact from the right side of my vehicle. I immediately applied my brakes. I exited from the passenger door of my car as the driver door was jammed. One black Honda Vezel, SKU6707P had hit on the right side of my vehicle. The right side of my vehicle was badly dented and has a lot of scratches. The driver door of my car was jammed.

I spoke to the other driver and exchanged particulars. A police car came however the other driver and I have already shifted our vehicles. I informed the police that everything was fine, and the police left. I did not suffer any physical injuries at that moment. Later today, I felt pain on my right upper chest and I went to Changi General Hospital to seek treatment. I was discharge on the same day and given medical leave for 2 days, 22/12/22 to 23/12/22. I already informed the other driver informing him of my injuries.