# **SINGAPORE ACCIDENT STATEMENT**

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
   5. Any false reporting may be referred to the Police for investigation.
   6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

# **ACCIDENT STATEMENT**

Date of Submission 23/12/2022 13:33 (SGT) Reported by Driver Date of Accident 22/12/2022 22:00 (SGT) Exact Location of Accident Huddington Ave, Singapore Additional Location Information Country/State of Loss Singapore

# **DETAILS OF OWN VEHICLE**

Vehicle Registration Number SMM5281A

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner L CAR RENTAL PTE. LTD. Company Reg No 201918675R Email Address yongwei.koh@gmail.com Mobile Phone No (Phone) +65-97884369 Alternative Phone No

#### VEHICLE PARTICULARS

Manufacturer Honda Model Fit Variant Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Private hire Transmission Auto CC 1499

#### **INSURANCE COMPANY**

Name of Insurance Company Income Insurance Limited Policy Number / Cover Note Number 5117591755-02

#### DRIVER

Name of Driver KOH YONG WEI NRIC No S9216283D Date Of Birth 12/05/1992 Occupation Outdoor

Date Of Driving Pass 18/04/2018 Driving experience 4 YEARS AND 8 MONTHS Gender Mobile Number (Phone) +65-97884369 Alt. Phone Number Email Address yongwei.koh@gmail.com Address BLK 37 BEDOK SOUTH AVENUE 2 Address complement #13-463 Postcode 460037 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? Nο Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Hit and run / Vandalism / Damaged whilst parked Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION Was the accident reported to the police? Yes Police Station Name Traffic Police Police Station Phone No (Phone) +65-65470000 Alt. Police Station Phone No (Fax) +65-65474900 Police Station Address 10 Ubi Avenue 3 Singapore 408865 Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT PLEASE SEE ATTACHED SKETCH PLANS. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes **DETAILS OF OTHER VEHICLE PROPERTY 1** 

SHA1312T

Hyundai

140

Accident report SS2S22CN0001
------------------------------

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model

Vehicle Variant

Vehicle Colour Vehicle Category	Blue Taxi
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	_

# WITNESS DETAILS

WITNESS 1

Name N.A
Phone Email -

WITNESS 2

 Name
 N.A

 Phone

 Email

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Rental of the state of the stat


Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan





	Plane rates	notice	sanort	
	Pleuse refer 7/20.	Puice.	140017	
	7/20.	22/223/	1004	
		1		
			**************************************	
			NAME OF THE PARTY	
				<u> </u>
Claim OD Clai	im Third Party	Claim OD/	TP at other workshop	D. Paradia o Oalu
			ir at other workshop	□ Reporting Only
ase forward a copy of m	y efile accident repo	ort to:		
workshop:				
ail address :				
rself email : Yong 60%, k	inh earnist com	C.		
				own damage claim under
ar own policy. Kindly ch	eck with your own I	insurer for more	e information.	
The second secon				
claration				
	are are true in every room	seel :		
	ars are true in every resp	1		
claration  e declara the foregoing particular of the foreg	ars are true in every resp	asnte	<u></u>	A TOTAL OF THE PARTY OF THE PAR
declare the foregoing particul	ars are true in every resp	1	7	















































1 of 4 Report No. T/20221223/7004

#### REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made; 23/12/2022 01:51		Vide Report No.: F/20221222/0173	Station Diary No.:	
Informa	nt's Partic	ulars		
	Informant: NG WEI		Address: 37 BEDOK SOUTH AV	/ENUE 2 #13-463 SINGAPORE 460037
ID Type NRIC NO	/ ID No.: ) / S92162	83D	Contact No.: Home/Office:	Mobile: 97884369
Nationali SINGAP	ty: ORE CITIZ	EN	Email: YONGWEI.KOH@GM	AIL.COM
Sex: Male	Age: 30	Date of Birth: 12/05/1992	Type of Informant: Driver	
Race: Chinese		Language: English	Institution / School Name:	
Occupation:		Driving Licence Information: Class: Date of Expiry:		

General Inform	mation of the Accident			
Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 22/12/2022 22:00	Type of Location: Straight Road
Location: HUDDINGTO	N AVENUE			
Weather: Clear		Road Surface: Dry	8	Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collis Moving Vehic	ion: le Against - Parked Vehicl	е		Anyone conveyed by ambulance: No

Vehicle No.	Туре	Make	Model	Color	Conditio	No of
SHA1312T (Not Accurate)	Car	HYUNDAI	140	Blue		0
SMM5281A	Car					0





2 of 4 Report No. T/20221223/7004

#### CONTINUATION OF REPORT

Details of Perso						
Any Pedestrian I	nvolved: No		25-50		6-00-0	
No. of Pedestrian	is Injured: NIL		Use of Pec	destrian C	ross	ing: NA
Driver						
Name	KOH YONG WEI	i e		ID No.		S9216283D
Related Vehicle	SMM5281A (Car)			Contact	No.	97884369
Hospital/Clinic	NIL			Class of Driving Licence Expiry		Class: NIL Date of Expiry: NIL
Date	NIL		Date	1	1IL	
No. of Days gran	ted Medical Leave NIL		Degree of	1	IIL.	

#### Brief Details.

At approximately 2201hours, a loud bang was heard, which then I came out of the house.

The neighbour/witness from 6 & 8 Huddington Avenue saw the ComfortDelgro Blue Taxi, SHA1312T, impacted the right side of my vehicle which at that time was parked along Huddington Avenue, positioned right beside the kerbs on the left of the road. The impact have damaged the Right Rear Door, Right Front Door, Right Side Mirror & Right Front Rim.

Both witnesses tried to chase and wave down the Taxi, however SHA1312T did not stop, and took off real quick, leaving the accident scene.

After I came out of the house, the neighbours approached me to share with me the Taxi plate number. I have also retrieve the dashcam footage, my friend's vehicle footage and house CCTV footage which will be provided below as links under Google Drive.

Then I proceeded to make a police report which TP have attended to the case.

#### Video links:

House CCTV: https://drive.google.com/file/d/1GBfJTk2MB1sAknGJeiFwZE-PcAuKGl8j/view?usp=drivesdk

#### Vehicle Dashcam Front:

https://drive.google.com/file/d/1GLNIKvP15dkVUcMW04wwz6zKafatBMwV/view?usp=drivesdkhttps://drive.google.com/file/d/1GQCNysTVcpnsjKk1oIOuxA5Uk6jdlL8R/view?usp=drivesdkhttps://drive.google.com/file/d/1GQCNysTVcpnsjKk1oIOuxA5Uk6jdlL8R/view?usp=drivesdkhttps://drive.google.com/file/d/1GQCNysTVcpnsjKk1oIOuxA5Uk6jdlL8R/view?usp=drivesdkhttps://drive.google.com/file/d/1GQCNysTVcpnsjKk1oIOuxA5Uk6jdlL8R/view?usp=drivesdkhttps://drive.google.com/file/d/1GQCNysTVcpnsjKk1oIOuxA5Uk6jdlL8R/view?usp=drivesdkhttps://drive.google.com/file/d/1GQCNysTVcpnsjKk1oIOuxA5Uk6jdlL8R/view?usp=drivesdkhttps://drive.google.com/file/d/1GQCNysTVcpnsjKk1oIOuxA5Uk6jdlL8R/view?usp=drivesdkhttps://drive.google.com/file/d/1GQCNysTVcpnsjKk1oIOuxA5Uk6jdlL8R/view?usp=drivesdkhttps://drive.google.com/file/d/1GQCNysTVcpnsjKk1oIOuxA5Uk6jdlL8R/view?usp=drivesdkhttps://drive.google.com/file/d/1GQCNysTVcpnsjKk1oIOuxA5Uk6jdlL8R/view?usp=drivesdkhttps://drive.google.com/file/d/1GQCNysTVcpnsjKk1oIOuxA5Uk6jdlL8R/view?usp=drivesdkhttps://drive.google.com/file/d/1GQCNysTVcpnsjKk1oIOuxA5Uk6jdlL8R/view?usp=drivesdkhttps://drivesdkhttps:/

#### Vehicle Dashcam Rear:

https://drive.google.com/file/d/1GDcWgbkkYPv4S6A6VDfVEke3gZQKm9GC/view?usp=drivesdk

### Friend's Vehicle Dashcam Front:

https://drive.google.com/file/d/1GTUHgQ34EaC71HqetqYm5SiSrbRlUtfB/view?usp=drivesdk





3 of 4 Report No. T/20221223/7004

# CONTINUATION OF REPORT

Friend's Vehicle Dashcam Rear: https://drive.google.com/file/d/1GReaxIBOmTrvZPoU0BBReNlvzs4ckde4/view?usp=drivesdk





4 of 4 Report No. T/20221223/7004

# CONTINUATION OF REPORT

Sketch Plan	
Informant is	not able to provide sketch

Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Date/Time: 23/12/2022 01:51
Classification Of Case:

